

Register entry, as of 29 October 2026

Listed for sale

Record ID 7907919c3272

# 2024 Volkswagen Atlas Cross Sport 4Motion SEL Premium R-Line

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**1V2** **FE2CA** **2** **R** **C** **233366**

WMI 1-3

Volkswagen Group Of Ame...

DESCRIPTOR 4-8

Atlas Cross Sport · 2.0 L

CHECK 9

Verified

YEAR 10

2024

PLANT 11

Chattanooga

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |                            |        |                                       |
|------------|----------------------------|--------|---------------------------------------|
| Model year | 2024                       | Engine | 2.0 L, 4 cylinders                    |
| Make       | Volkswagen                 | Fuel   | Gasoline                              |
| Model      | Atlas Cross Sport          | Drive  | AWD                                   |
| Trim       | 4Motion SEL Premium R-Line | Maker  | VOLKSWAGEN GROUP OF AMERICA, INC.     |
| Body       | Sport Utility Vehicle      | Plant  | Chattanooga, Tennessee, United States |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/volkswagen/atlas-cross-sport/2024](https://cardog.app/tools/recalls/volkswagen/atlas-cross-sport/2024)

## 7 recalls listed by Transport Canada for this model year

### Visual system

2026357 22 Jul 2026

Issue: Under certain conditions, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to update the rearview camera software.

### Suspension

2025355 25 Jun 2025

Issue: On certain vehicles, certain bolt(s) on the chassis, brake system and/or suspension may not have been tightened properly. As a result, the bolt(s) could loosen and cause a loss of control. Safety Risk: A loss of control could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the affected bolt(s) on the chassis, brake system and/or suspension.

### Visual system

2025272 21 May 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display properly. Canadian regulations require the rearview image to display properly when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display properly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to update the infotainment display software.



## Engine

2025079 17 Feb 2025

Issue: On certain vehicles, the engine cover may come loose after service. If this happens, the engine cover could contact hot surfaces in the engine compartment and melt. Safety Risk: An engine cover that melts onto a hot surface could create the risk of a fire. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to remove the engine cover.

## Brakes

2024568 27 Sep 2024

Issue: On certain vehicles, the brake master cylinder may not have been manufactured properly. As a result, there could be reduced braking. Note: This problem could cause the brake pedal to feel soft and/or spongy and a brake warning light could turn on in the instrument cluster. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the brake master cylinder.

## Visual system

2024365 27 Jun 2024

Issue: On certain vehicles, a software problem could cause the rearview camera image to be delayed or not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to update the infotainment software.

1 more on the model-year record, [cardog.app/tools/recalls/volkswagen/atlas-cross-sport/2024](https://cardog.app/tools/recalls/volkswagen/atlas-cross-sport/2024)

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.  
Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.  
[www.vw.ca/en/owners-and-drivers/recalls.html](https://www.vw.ca/en/owners-and-drivers/recalls.html)

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

§3 VALUE <sup>[4]</sup>

This car asks \$40,895<sup>[5]</sup>, \$1,055 under the median of \$41,950<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$34,995            |
| Middle half | \$39,970 – \$43,585 |
| Median ask  | \$41,950            |
| This car    | \$40,895            |

Same configuration · 40 live listings · as of 29 Oct 2026

OTHER 2024 VOLKSWAGEN ATLAS CROSS SPORT LISTINGS <sup>[5]</sup>

|                               |          |
|-------------------------------|----------|
| Hamilton, ON · 53,650 km      | \$36,993 |
| Orangeville, ON · 79,755 km   | \$36,495 |
| Sherwood Park, AB · 49,358 km | \$41,907 |
| Lévis, QC · 39,000 km         | \$38,980 |
| Edmonton, AB · 42,880 km      | \$39,500 |
| St. John's, NL · 57,567 km    | \$42,995 |

## §4 EVENTS

2024                      Model year 2024<sup>[1]</sup>  
Assembly plant Chattanooga, Tennessee, United States



|             |                                                                                                         |
|-------------|---------------------------------------------------------------------------------------------------------|
| 19 Jun 2024 | Transport Canada recall 2024354 <sup>[2]</sup><br>Issued for the model year · Airbag                    |
| 27 Jun 2024 | Transport Canada recall 2024365 <sup>[2]</sup><br>Issued for the model year · Visual system             |
| 27 Sep 2024 | Transport Canada recall 2024568 <sup>[2]</sup><br>Issued for the model year · Brakes                    |
| 17 Feb 2025 | Transport Canada recall 2025079 <sup>[2]</sup><br>Issued for the model year · Engine                    |
| 21 May 2025 | Transport Canada recall 2025272 <sup>[2]</sup><br>Issued for the model year · Visual system             |
| 25 Jun 2025 | Transport Canada recall 2025355 <sup>[2]</sup><br>Issued for the model year · Suspension                |
| 22 Jul 2026 | Transport Canada recall 2026357 <sup>[2]</sup><br>Issued for the model year · Visual system             |
| 21 Oct 2026 | Listed for sale, Lasalle, QC <sup>[5]</sup><br>Spinelli Campbell & Cameron Volkswagen · asking \$40,895 |
| 29 Oct 2026 | Listing last updated <sup>[5]</sup><br>asking \$40,895                                                  |

## §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.

## SOURCES

- |                                                                     |                                                                                  |
|---------------------------------------------------------------------|----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 40 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     | [5] Live public dealer listings on Cardog, as of 29 Oct 2026                     |
| [3] NHTSA recall records (United States), listed for the model year |                                                                                  |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

