Register entry, as of 29 October 2026 Listed for sale Record ID b156c12b6857

2021 Volkswagen Atlas Cross Sport 4Motion SEL Premium R-Line

3.6 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1V2	FE2CA	6	M	C	213632
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen Group Of Ame…	Atlas Cross Sport · 3.6 L	Verified	2021	Chattanooga	Build sequence

§1 IDENTITY [1]

Model year	2021	Engine	3.6 L, 6 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Atlas Cross Sport	Drive	AWD
Trim	4Motion SEL Premium R-Line	Maker	VOLKSWAGEN GROUP OF AMERICA, INC.
Body	Sport Utility Vehicle	Plant	Chattanooga, Tennessee, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/atlas-cross-sport/2021

8 recalls listed by Transport Canada for this model year

Airbag

2024354 19 Jun 2024

Issue: On certain vehicles, the passenger occupant detection system (PODS) may malfunction. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause an error message to display on the instrument panel and a warning chime to sound. The airbag indicator light would also display "passenger airbag off". Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the PODS sensor mat and seat harness. Volkswagen advises that you shouldn't use the front passenger seat if a PODS error message displays on the instrument panel or if the airbag indicator light displays "passenger airbag off" with an occupant in the seat.

Visual system

2022382 20 Jul 2022

Issue: Under certain conditions, the rearview camera image may not appear on the center screen. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to update the infotainment software.

Fuel system

2022182 13 Apr 2022

Issue: On certain vehicles, the long fuel injectors may have been assembled without a filter element. As a result, fuel could leak into the engine compartment. Safety Risk: A fuel leak in the engine compartment can create the risk of a fire. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to replace the long fuel injectors.

Airbag

2022110 11 Mar 2022

Issue: On certain vehicles, the wiring contacts for the front doors may become damaged. If this happens, there could be a delay before the side airbags inflate in a side-impact crash. This problem could also cause the parking brake to engage while driving at low speed, cause the windows to roll down on their own, or give warning of a faulty door sensor. Safety Risk: Delayed inflation of the side airbags could create an increased the risk of injury in a crash. Corrective Actions: Volkswagen will notify owners by mail. The corrective actions for this recall are under development.

Heater and defroster

2021705 17 Nov 2021

Issue: On certain vehicles, the drain tube for the air conditioning system may be blocked. As a result, water may leak inside the vehicle and into the airbag control module. If this happens, the airbag control module may not work properly and could cause the airbags to inflate without a crash. Safety Risk: An airbag that inflates suddenly without a crash could create a risk of injury. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the air conditioning system drain tube. If the tube is blocked, the dealer will repair it and replace the airbag control module.

Steering

2021032 27 Jan 2021

Issue: On certain vehicles, the front steering knuckles may not have been manufactured correctly. As a result, the steering knuckle could break suddenly while driving. If this happens, there would be a loss of steering control. Safety Risk: A loss of steering control could create a risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the front knuckles and replace them, if necessary.

2 more on the model-year record, cardog.app/tools/recalls/volkswagen/atlas-cross-sport/2021

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 14 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $28,260[5], $1,602 under the median of $29,862[4].



Lowest ask	$23,995
Middle half	$28,390 – $31,564
Median ask	$29,862
This car	$28,260

Same configuration · 10 live listings · as of 29 Oct 2026

OTHER 2021 VOLKSWAGEN ATLAS CROSS SPORT LISTINGS [5]

Kelowna, BC · 108,271 km	$27,870
Edmonton, AB · 90,799 km	$29,750
Mirabel, QC · 104,809 km	$23,995
Petawawa, ON · 88,882 km	$30,697
Calgary, AB · 99,979 km	$31,853
Ste-Agathe-les-Monts, QC · 109,459 km	$22,883

§4 EVENTS

2021	Model year 2021[1] Assembly plant Chattanooga, Tennessee, United States
13 Nov 2020	Transport Canada recall 2020546[2] Issued for the model year · Tires
18 Nov 2020	Transport Canada recall 2020556[2] Issued for the model year · Visual system
27 Jan 2021	Transport Canada recall 2021032[2] Issued for the model year · Steering
17 Nov 2021	Transport Canada recall 2021705[2] Issued for the model year · Heater and defroster
11 Mar 2022	Transport Canada recall 2022110[2] Issued for the model year · Airbag
13 Apr 2022	Transport Canada recall 2022182[2] Issued for the model year · Fuel system
20 Jul 2022	Transport Canada recall 2022382[2] Issued for the model year · Visual system
19 Jun 2024	Transport Canada recall 2024354[2] Issued for the model year · Airbag
8 Jul 2026	Listed for sale, Grande Prairie, AB[5] Grande Prairie Volkswagen · asking $28,260
26 Oct 2026	Listing last updated[5] asking $28,260

§5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 10 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.