Register entry, as of 28 October 2026 Listed for sale Record ID 92d053ebe835

# 2023 Volkswagen Atlas 4Motion SEL Premium R-Line

3.6 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1V2 | FR2CA | X | P | C | 549597 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Volkswagen Group Of Ame… | Atlas · 3.6 L | Verified | 2023 | Chattanooga | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2023 | Engine | 3.6 L, 6 cylinders |
| Make | Volkswagen | Fuel | Gasoline |
| Model | Atlas | Drive | AWD |
| Trim | 4Motion SEL Premium R-Line | Maker | VOLKSWAGEN GROUP OF AMERICA, INC. |
| Body | Sport Utility Vehicle | Plant | Chattanooga, Tennessee, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/atlas/2023

**4** recalls listed by Transport Canada for this model year

### Suspension

2025355 25 Jun 2025

Issue: On certain vehicles, certain bolt(s) on the chassis, brake system and/or suspension may not have been tightened properly. As a result, the bolt(s) could loosen and cause a loss of control. Safety Risk: A loss of control could increase the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the affected bolt(s) on the chassis, brake system and/or suspension.

### Airbag

2024354 19 Jun 2024

Issue: On certain vehicles, the passenger occupant detection system (PODS) may malfunction. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause an error message to display on the instrument panel and a warning chime to sound. The airbag indicator light would also display "passenger airbag off". Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the PODS sensor mat and seat harness. Volkswagen advises that you shouldn't use the front passenger seat if a PODS error message displays on the instrument panel or if the airbag indicator light displays "passenger airbag off" with an occupant in the seat.

### Suspension

2022612 26 Oct 2022

Issue: On certain vehicles, the bolts for the left-rear trailing arm may not have been properly tightened. As a result, the bolts may loosen over time and fall out. If this happens, the trailing arm may break and cause a sudden loss of vehicle control. Safety Risk: A loss of control could create the risk of a crash. Corrective Actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership to replace the left-rear trailing arm bolts.

### Engine

2022576 7 Oct 2022

Issue: On certain vehicles, the connecting rod bearings may become damaged. If this happens, the engine could make abnormal noises and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail and/or an oil leak could occur. Safety Risk: An engine failure can cause a sudden loss of power, which could increase the risk of a crash. An oil leak could create the risk of a vehicle fire. Corrective actions: Volkswagen will notify owners by mail and instruct you to take your vehicle to a dealership for an engine inspection test. The engine will be replaced, if necessary.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $42,625[5], $5,375 over the median of $37,250[4].




| | |
|---|---|
| Lowest ask | $28,895 |
| Middle half | $35,944 – $39,688 |
| Median ask | $37,250 |
| This car | $42,625 |

Same configuration · 43 live listings · as of 28 Oct 2026

OTHER 2023 VOLKSWAGEN ATLAS LISTINGS [5]

| | |
|---|---|
| Sundridge, ON · 106,649 km | $34,895 |
| Sundridge, ON · 113,373 km | $37,960 |
| Winnipeg, MB · 24,331 km | $40,610 |
| Essex, ON · 62,037 km | $34,990 |
| Airdrie, AB · 155,373 km | $31,906 |
| Cayuga, ON · 123,000 km | $30,950 |

## §4 EVENTS

| | |
|---|---|
| 2023 | Model year 2023[1]<br>Assembly plant Chattanooga, Tennessee, United States |
| 7 Oct 2022 | Transport Canada recall 2022576[2]<br>Issued for the model year · Engine |
| 26 Oct 2022 | Transport Canada recall 2022612[2]<br>Issued for the model year · Suspension |
| 19 Jun 2024 | Transport Canada recall 2024354[2]<br>Issued for the model year · Airbag |
| 25 Jun 2025 | Transport Canada recall 2025355[2]<br>Issued for the model year · Suspension |

27 Oct 2026 **Listed for sale, Abbotsford, BC**[5]
Abbotsford Volkswagen · asking $42,625

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 43 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.