Register entry, as of 28 October 2026 Listed for sale Record ID 0b13febb9783

2019 Volkswagen Atlas 4Motion SEL Premium

3.6 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1V2	TR2CA	4	K	C	608171
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Volkswagen Group Of Ame…	Atlas · 3.6 L	Verified	2019	Chattanooga	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	3.6 L, 6 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Atlas	Drive	AWD
Trim	4Motion SEL Premium	Maker	VOLKSWAGEN GROUP OF AMERICA, INC.
Body	Sport Utility Vehicle	Plant	Chattanooga, Tennessee, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/atlas/2019

6 recalls listed by Transport Canada for this model year

Airbag

2023183 29 Mar 2023

Issue: On certain vehicles, the passenger occupant detection system (PODS) may malfunction. This could cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause an error message to display on the instrument panel and a warning chime to sound. The airbag indicator light would also display "passenger airbag off". Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Volkswagen will notify owners by mail and advise you to take your vehicle to a dealership to replace the PODS sensor mat and seat harness. Volkswagen advises that you shouldn't use the front passenger seat until the recall repairs are completed.

Airbag

2022110 11 Mar 2022

Issue: On certain vehicles, the wiring contacts for the front doors may become damaged. If this happens, there could be a delay before the side airbags inflate in a side-impact crash. This problem could also cause the parking brake to engage while driving at low speed, cause the windows to roll down on their own, or give warning of a faulty door sensor. Safety Risk: Delayed inflation of the side airbags could create an increased the risk of injury in a crash. Corrective Actions: Volkswagen will notify owners by mail. The corrective actions for this recall are under development.

Tires

2021116 5 Mar 2021

Issue: Certain vehicles were built with tires that may have been cured too long. As a result, the sidewall could crack or the tread and belts could separate. This could lead to a sudden loss of air pressure and could cause a tire failure. Note: This recall only affects certain Continental tires, with specific date codes and mold numbers. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Volkswagen will notify the owners by mail and instruct them to take the vehicle to a dealer to inspect and replace the tires, if necessary.

Label

2020353 4 Aug 2020

Issue: On certain vehicles, the warning label for the engine block heater cable is written in English only. As a result, a French user may not receive important safety information about how to use the engine block heater. A label that is not provided in both official languages could create confusion. Safety Risk: User confusion could increase the risk of injury when trying to use the block heater. Corrective Actions: The company will mail each owner a new label for the block heater cable. If you would like help installing the label, you can contact a dealer for assistance.

Lights and instruments

2019242 23 May 2019

Issue: Certain vehicles were built with headlights that may allow horizontal adjustment. This is not allowed under Canadian regulations. Safety Risk: Headlights that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the headlights. A blocking cap will be installed on the horizontal adjusters as necessary.

Lights and instruments

2018644 21 Nov 2018

Certain vehicles do not to conform to Canada Motor Vehicle Safety Standard (CMVSS) 114 - Theft Protection and Rollaway Prevention. Due to incorrect programming, the vehicle may fail to provide an audible warning when a driver opens their door after turning off the ignition, and the key is left in the ignition switch. This could increase the risk of vehicle theft. Correction: Dealers will reprogram the instrument cluster.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $25,995[5], $4,108 over the median of $21,887[4].

Lowest ask	$14,975
Middle half	$18,977 – $25,995
Median ask	$21,887
This car	$25,995

Same configuration · 9 live listings · as of 28 Oct 2026

OTHER 2019 VOLKSWAGEN ATLAS LISTINGS [5]

Scarborough, ON · 129,000 km	$21,480
Whitby, ON · 92,363 km	$24,600
Airdrie, AB · 149,893 km	$23,588
Edmonton, AB · 128,598 km	$24,400
Sault Ste. Marie, ON · 72,214 km	$25,695
Olds, AB · 149,893 km	$23,588

§4 EVENTS

2019	Model year 2019[1] Assembly plant Chattanooga, Tennessee, United States
21 Nov 2018	Transport Canada recall 2018644[2] Issued for the model year · Lights and instruments

23 May 2019	Transport Canada recall 2019242[2] Issued for the model year · Lights and instruments
4 Aug 2020	Transport Canada recall 2020353[2] Issued for the model year · Label
5 Mar 2021	Transport Canada recall 2021116[2] Issued for the model year · Tires
11 Mar 2022	Transport Canada recall 2022110[2] Issued for the model year · Airbag
29 Mar 2023	Transport Canada recall 2023183[2] Issued for the model year · Airbag
26 Oct 2026	Listed for sale, Waterloo, ON[5] Carimex Auto Sales Waterloo · asking $25,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 9 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.