Register entry, as of 29 October 2026 Listed for sale Record ID b0742a6302b6

# 2018 Volkswagen Passat SE, SE w/ Technology

2.0 L, 4 cylinders · FWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 1VW | BA7A3 | 6 | J | C | 046761 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Volkswagen Group Of Ame… | Passat · 2.0 L | Verified | 2018 | Chattanooga | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2018 | Engine | 2.0 L, 4 cylinders |
| Make | Volkswagen | Fuel | Gasoline |
| Model | Passat | Drive | FWD |
| Trim | SE, SE w/ Technology | Maker | VOLKSWAGEN GROUP OF AMERICA, INC. |
| Body | Sedan | Plant | Chattanooga, Tennessee, United States |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/passat/2018

**3** recalls listed by Transport Canada for this model year

### Lights and instruments

2019242 23 May 2019

Issue: Certain vehicles were built with headlights that may allow horizontal adjustment. This is not allowed under Canadian regulations. Safety Risk: Headlights that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the headlights. A blocking cap will be installed on the horizontal adjusters as necessary.

### Brakes

2018429 15 Aug 2018

On certain vehicles, the brake caliper bracket bolts may not be properly tightened and could loosen, allowing the caliper to move. This could cause increased stopping distances, result in wheel damage and/or cause a loss of vehicle control, increasing the risk of a crash causing injury and/or property damage. Correction: Dealers will inspect the vehicles and, if a loose bolt is found, the bolt will be replaced and tightened to the correct specification. Note: On Atlas models, only the front brake caliper bracket bolts are affected, and on Passat models, only the rear brake caliper bracket bolts are affected.

### Brakes

2018292 1 Jun 2018

On certain vehicles, a problem with the brake system may cause gas bubbles to form in the brake fluid. This could cause a soft brake pedal feel and a reduction in brake performance, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will bleed the front or rear brakes as necessary. Note: In the interim, owners are advised to stop driving their vehicle until the defect has been repaired. Affected owners should call Volkswagen's Roadside Assistance number at 1-800-411-6688.

> Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.
> Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.
> www.vw.ca/en/owners-and-drivers/recalls.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $20,995[5], $2,680 over the median of $18,315[4].




| | |
|---|---|
| Lowest ask | $15,500 |
| Middle half | $17,584 – $20,995 |
| Median ask | $18,315 |
| This car | $20,995 |

Same configuration · 8 live listings · as of 29 Oct 2026

### OTHER 2018 VOLKSWAGEN PASSAT LISTINGS [5]

| | |
|---|---|
| Toronto, ON · 172,818 km | $11,400 |
| Aurora, ON · 138,689 km | $14,988 |
| Prince George, BC · 116,759 km | $16,636 |
| Quebec, QC · 97,000 km | $13,995 |
| Dorval, QC · 156,410 km | $8,890 |
| Château-Richer, QC · 167,000 km | $9,995 |

## §4 EVENTS

| | |
|---|---|
| 2018 | Model year 2018[1]<br>Assembly plant Chattanooga, Tennessee, United States |
| 1 Jun 2018 | Transport Canada recall 2018292[2]<br>Issued for the model year · Brakes |
| 15 Aug 2018 | Transport Canada recall 2018429[2]<br>Issued for the model year · Brakes |
| 23 May 2019 | Transport Canada recall 2019242[2]<br>Issued for the model year · Lights and instruments |
| 8 Oct 2026 | Listed for sale, Terrebonne, QC[5]<br>Occasion Grenier · asking $20,995 |
| 29 Oct 2026 | Listing last updated[5]<br>asking $20,995 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 8 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.