

Register entry, as of 27 October 2026

Listed for sale

Record ID 4501c17d8211

2015 Volkswagen Passat SE

1.8 L, 4 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

1VW **BS7A3** **1** **F** **C** **003286**

WMI 1-3

Volkswagen Group Of Ame...

DESCRIPTOR 4-8

Passat · 1.8 L

CHECK 9

Verified

YEAR 10

2015

PLANT 11

Chattanooga

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	1.8 L, 4 cylinders
Make	Volkswagen	Fuel	Gasoline
Model	Passat	Drive	Not in the decode
Trim	SE	Maker	VOLKSWAGEN GROUP OF AMERICA, INC.
Body	Sedan	Plant	Chattanooga, Tennessee, United States

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/volkswagen/passat/2015

6 recalls listed by Transport Canada for this model year

Label	2020353 4 Aug 2020
Issue: On certain vehicles, the warning label for the engine block heater cable is written in English only. As a result, a French user may not receive important safety information about how to use the engine block heater. A label that is not provided in both official languages could create confusion. Safety Risk: User confusion could increase the risk of injury when trying to use the block heater. Corrective Actions: The company will mail each owner a new label for the block heater cable. If you would like help installing the label, you can contact a dealer for assistance.	
Lights and instruments	2019242 23 May 2019
Issue: Certain vehicles were built with headlights that may allow horizontal adjustment. This is not allowed under Canadian regulations. Safety Risk: Headlights that are not properly adjusted could cause reduced visibility or glare for oncoming drivers, and could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the headlights. A blocking cap will be installed on the horizontal adjusters as necessary.	
Airbag	2019002 3 Jan 2019
Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the driver-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Actions: Owners will be notified by mail and instructed to take their vehicle to a dealer to have the driver-front airbag inflator replaced. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.	



Engine

2015504 23 Oct 2015

On certain vehicles, the camshaft lobe which actuates the vacuum pump may fail, causing the pump to fail to deliver further vacuum supply to the brake booster, potentially increasing stopping distances. This would also result in a reduction in available engine power. These issues could increase the risk of a crash causing injury and/or damage to property. Note: This issue would result in the Engine Malfunction Indicator Light (MIL) illuminating. Correction: Dealers will update the engine control module (ECM) software.

Fuel system

2014575 17 Dec 2014

On certain vehicles, a sealing cap at the fuel rail may fail to seal, allowing fuel to leak into the engine compartment during engine operation. Leaking fuel, in the presence of an ignition source, could lead to a fire causing injury and/or damage to property. Correction: Dealers will inspect, and if necessary, replace the fuel rail.

Seats and restraints

2014469 22 Oct 2014

On certain vehicles equipped with manual front seatback recliners, the retaining bracket may have been improperly assembled and may not engage correctly. This could cause the seatback to shift fore and/or aft with minimal effort. Should this movement occur unexpectedly with the driver's seatback, it could startle the driver and lead to a crash. In a crash, if the movement occurs on either seat, this could increase the risk of personal injury to the driver and/or front passenger occupant. Correction: Dealers will inspect the seatback recliner retaining bracket, and if found out of specification, it will be corrected.

Listed for the model year, not checked against your VIN. Volkswagen confirms which apply.

Check your VIN with Volkswagen Canada or call a Volkswagen dealer with your VIN.

www.vw.ca/en/owners-and-drivers/recalls.html

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$9,900^[5], \$900 under the median of \$10,800^[4].



Lowest ask	\$3,972
Middle half	\$9,495 – \$11,999
Median ask	\$10,800
This car	\$9,900

Same model year · 13 live listings · as of 27 Oct 2026

OTHER 2015 VOLKSWAGEN PASSAT LISTINGS [5]

Toronto, ON · 0 km	\$9,995
Barrie, ON · 139,441 km	\$10,990
Scarborough, ON · 243,000 km	\$3,972
Lasalle, QC · 24,593 km	\$18,749
Saskatoon, SK · 196,916 km	\$9,495
Toronto, ON · 149,300 km	\$8,995

§4 EVENTS

2015

Model year 2015^[1]

Assembly plant Chattanooga, Tennessee, United States



22 Oct 2014 Transport Canada recall 2014469^[2]
Issued for the model year · Seats and restraints

17 Dec 2014 Transport Canada recall 2014575^[2]
Issued for the model year · Fuel system

23 Oct 2015 Transport Canada recall 2015504^[2]
Issued for the model year · Engine

3 Jan 2019 Transport Canada recall 2019002^[2]
Issued for the model year · Airbag

23 May 2019 Transport Canada recall 2019242^[2]
Issued for the model year · Lights and instruments

4 Aug 2020 Transport Canada recall 2020353^[2]
Issued for the model year · Label

2 Apr 2026 Listed for sale, Truro, NS^[5]
Scammell Auto · asking \$9,900

27 Oct 2026 Listing last updated^[5]
asking \$9,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

- [1] Cardog identity register, decoded from the VIN
- [2] Transport Canada recall database, listed for the model year
- [3] NHTSA recall records (United States), listed for the model year

- [4] Cardog market quote, same model year, 13 live listings, as of 27 Oct 2026
- [5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

