

Register entry, as of 29 October 2026

Listed for sale

Record ID 7c60d014fe09

# 2014 Ford Mustang V6 Coupe

3.7 L, 6 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

**1ZV BP8AM 1 E 5 250696**

WMI 1-3

Ford · AUTO ALLIANCE INT...

DESCRIPTOR 4-8

Mustang · 3.7 L

CHECK 9

Verified

YEAR 10

2014

PLANT 11

Flat Rock

SERIAL 12-17

Build sequence

## §1 IDENTITY [1]

|            |          |        |                                    |
|------------|----------|--------|------------------------------------|
| Model year | 2014     | Engine | 3.7 L, 6 cylinders                 |
| Make       | Ford     | Fuel   | Gasoline                           |
| Model      | Mustang  | Drive  | Not in the decode                  |
| Trim       | V6 Coupe | Maker  | AUTO ALLIANCE INTERNATIONAL, USA   |
| Body       | Coupe    | Plant  | Flat Rock, Michigan, United States |

## §2 OBLIGATIONS [2]

[cardog.app/tools/recalls/ford/mustang/2014](https://cardog.app/tools/recalls/ford/mustang/2014)

## 3 recalls listed by Transport Canada for this model year

### Airbag

2021077 19 Feb 2021

Issue: This recall is for certain vehicles that had the driver-front and/or passenger-front airbag inflator replaced after a collision or theft. An obsolete airbag may have been installed. On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the driver-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: The company will notify owners by mail and instruct you to take your vehicle to a Ford dealer to inspect the driver and/or passenger airbag inflator or module and replace it, if necessary. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.

### Airbag

2019005 8 Jan 2019

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the passenger-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Actions: Owners will be notified by mail and instructed to take their vehicle to a dealer to have the passenger-front airbag inflator replaced. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected. Additional note: This recall supersedes recalls 2016-347 (Ford Safety Improvement Program 16S26), 2017-024 (Ford Recall 17S01) and 2018-035 (Ford Recall 18S01). Vehicles repaired under the previous recalls do not require repair under this recall.



**Airbag**

2015232 28 May 2015

On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Note: This recall supersedes special service campaign 2015-052. Correction: Depending on the model, dealers will either replace the driver frontal airbag inflator or airbag module. All vehicles having received a replacement inflator as part of a previous special service campaign will have a replacement inflator installed.

Listed for the model year, not checked against your VIN. Ford confirms which apply.  
Check your VIN with Ford Canada or call a Ford dealer with your VIN.

[www.ford.ca/support/recalls/](http://www.ford.ca/support/recalls/)

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.<sup>[3]</sup>

**§3 VALUE** <sup>[4]</sup>

This car asks \$16,995<sup>[5]</sup>, the median<sup>[4]</sup>.



|             |                     |
|-------------|---------------------|
| Lowest ask  | \$12,950            |
| Middle half | \$14,990 – \$18,438 |
| Median ask  | \$16,995            |
| This car    | \$16,995            |

Same configuration · 11 live listings · as of 29 Oct 2026

**OTHER 2014 FORD MUSTANG LISTINGS** <sup>[5]</sup>

|                            |          |
|----------------------------|----------|
| Ancaster, ON · 66,000 km   | \$16,995 |
| Guelph, ON · 82,205 km     | \$14,990 |
| Newmarket, ON · 110,169 km | \$14,990 |
| Watrous, SK · 22,758 km    | \$38,995 |
| Newmarket, ON · 73,900 km  | \$12,999 |
| Edmonton, AB · 89,276 km   | \$16,899 |

**§4 EVENTS**

|             |                                                                                      |
|-------------|--------------------------------------------------------------------------------------|
| 2014        | Model year 2014 <sup>[1]</sup><br>Assembly plant Flat Rock, Michigan, United States  |
| 28 May 2015 | Transport Canada recall 2015232 <sup>[2]</sup><br>Issued for the model year · Airbag |
| 8 Jan 2019  | Transport Canada recall 2019005 <sup>[2]</sup><br>Issued for the model year · Airbag |
| 19 Feb 2021 | Transport Canada recall 2021077 <sup>[2]</sup><br>Issued for the model year · Airbag |
| 15 Oct 2026 | Listed for sale, Picton, ON <sup>[5]</sup><br>STORMY'S CAR SALES · asking \$16,995   |



28 Oct 2026      Listing last updated<sup>[5]</sup>  
asking \$16,995

## §5 DOCUMENTS

Window sticker      We do not collect window stickers for this manufacturer.

## SOURCES

- |                                                                     |                                                                                  |
|---------------------------------------------------------------------|----------------------------------------------------------------------------------|
| [1] Cardog identity register, decoded from the VIN                  | [4] Cardog market quote, same configuration, 11 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year     |                                                                                  |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026                     |

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

