Register entry, as of 29 October 2026 Listed for sale Record ID 64d63d087bf9

2011 Chrysler Town and Country

3.6 L, 6 cylinders · FWD · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2A4	RR8DG	3	B	R	715747
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chrysler · FCA CANADA INC.	Town and Country · 3.6 L	Verified	2011	Windsor	Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	3.6 L, 6 cylinders
Make	Chrysler	Fuel	Gasoline
Model	Town and Country	Drive	FWD
Trim	Not in the decode	Maker	FCA CANADA INC.
Body	Minivan	Plant	Windsor, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chrysler/town-and-country/2011

6 recalls listed by Transport Canada for this model year

Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

Seats and restraints

2018439 21 Aug 2018

On certain wheelchair-accessible vehicles, the bolts used to attach the removable seats to the floor may contain a defect and could break in the event of a crash, creating a risk of injury. Correction: Dealers will replace the defective bolts.

Fuel system

2016575 17 Nov 2016

On certain Amerivan 10 wheelchair accessible vehicles built on Dodge Grand Caravan and Chrysler Town and Country platforms, the crimp fasteners used to retain fittings in the fuel line may not be fully crimped or compressed. This could result in a fuel leak. Leaking fuel, in the presence of an ignition source, could lead to a fire causing injury and/or damage to property. Correction: Dealers will inspect fasteners and crimp the fasteners further to ensure they are fully compressed and seated.

Electrical

2014167 8 May 2014

On certain vehicles, if the vent window switch (located in the driver's door armrest) is exposed to liquids, it could overheat. An overheated vent switch could result in a burning odour, smoke, or fire, increasing the risk of injury and/or property damage. Correction: Dealers will replace the switch with an updated design.

Steering

2011224 10 Jun 2011

Certain vehicles may have been built with a missing or incorrectly installed steering column pivot rivet. A steering column with a miss-installed rivet may not perform as intended in the event of a crash, which may increase the risk of personal injury. Correction: Dealers will inspect for steering column rivet presence and alignment, and repair as required.

> Listed for the model year, not checked against your VIN. Chrysler confirms which apply.
> Check your VIN with Mopar Canada or call a Chrysler dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $3,491[5], $4,404 under the median of $7,895[4].

Lowest ask	$3,491
Middle half	$5,693 – $9,945
Median ask	$7,895
This car	$3,491

Same model year · 3 live listings · as of 29 Oct 2026

§4 EVENTS

2011	Model year 2011[1] Assembly plant Windsor, Ontario, Canada
10 Jun 2011	Transport Canada recall 2011224[2] Issued for the model year · Steering
8 May 2014	Transport Canada recall 2014167[2] Issued for the model year · Electrical
17 Nov 2016	Transport Canada recall 2016575[2] Issued for the model year · Fuel system
21 Aug 2018	Transport Canada recall 2018439[2] Issued for the model year · Seats and restraints

21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
15 Aug 2024	Transport Canada recall 2024548[2] Issued for the model year · Label
29 Jul 2026	Listed for sale, Kentville, NS[5] Kings County Honda · asking $3,491
29 Oct 2026	Listing last updated[5] asking $3,491

§5 DOCUMENTS

Window sticker This VIN reads as model year 1981 or 2011, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 3 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.