Register entry, as of 27 October 2026 Listed for sale Record ID f808f882a22b

2014 Chrysler 300 300S

3.6 L, 6 cylinders · RWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2C3	CCABG	6	E	H	310066
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Chrysler · FCA CANADA INC.	300 · 3.6 L	Verified	2014	Brampton	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	3.6 L, 6 cylinders
Make	Chrysler	Fuel	Gasoline
Model	300	Drive	RWD
Trim	300S	Maker	FCA CANADA INC.
Body	Sedan	Plant	Brampton, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chrysler/300/2014

9 recalls listed by Transport Canada for this model year

Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Airbag

2019016 11 Jan 2019

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the passenger-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Owners will be notified by mail and instructed to take their vehicle to a dealer to have the passenger-front airbag inflator replaced. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.

Accessories

2018396 27 Jul 2018

Note: This recall affects the following Powertrain Control Modules (PCM) that were sold through dealers as high-performance accessories: - Mopar Stage 1 high performance Powertrain Control Modules (PCM), part numbers P5160023 and P5160025 (campaign U82) - Mopar high performance Powertrain Control Modules (PCM) included in the Demon Crate, part number 68412287AA (campaign U83) On certain vehicles, an electronic fault may create a situation where the cruise control cannot be deactivated. If this occurs and the driver does not apply the brakes or shift the transmission to neutral, the vehicle could maintain speed or accelerate without warning, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the PCM software and perform an update as necessary. Note: In the interim, owners are advised not to use the cruise control until the vehicle is repaired. This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act, as these aftermarket products were not regulated by the Act.

Engine

2018269 17 May 2018

On certain vehicles, an electronic fault may create a situation where the cruise control cannot be deactivated. If this occurs and the driver does not apply the brakes or shift the transmission to neutral, the vehicle could maintain speed or accelerate without warning, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the Powertrain Control Module (PCM) software and perform an update as necessary. Note: In the interim, owners are advised not to use the cruise control until the vehicle is repaired.

Electrical

2017574 22 Nov 2017

On certain vehicles equipped with 3.6L engines and 160 amp output alternators, the alternator may fail suddenly. This could result in the engine stalling, causing a loss of motive power which could increase the risk of a crash as well as disable various vehicle safety systems, and could also cause a fire. Both issues could increase the risk of injury and/or damage to property. Correction: Dealers will replace the alternator. Note: This is an expansion of recall 2014-446.

Electrical

2017341 10 Jul 2017

On certain vehicles equipped with electro-hydraulic power steering ("EHPS"), the alternator may fail suddenly. This could result in the engine stalling, causing a loss of motive power which could increase the risk of a crash as well as disable various vehicle safety systems, and could also cause a fire. Both issues could increase the risk of injury and/or damage to property. Correction: Dealers will inspect the part number on the alternator, and will replace the alternator as necessary. Note: Only specific engine and alternator combinations are affected by this campaign.

3 more on the model-year record, cardog.app/tools/recalls/chrysler/300/2014

> Listed for the model year, not checked against your VIN. Chrysler confirms which apply.
> Check your VIN with Mopar Canada or call a Chrysler dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $2,999[5], $8,247 under the median of $11,246[4].

Lowest ask	$9,341
Middle half	$10,050 – $12,749
Median ask	$11,246
This car	$2,999

Same model year · 10 live listings · as of 27 Oct 2026

OTHER 2014 CHRYSLER 300 LISTINGS [5]

Edmonton, AB · 63,709 km	$10,998
Olds, AB · 146,253 km	$9,900
North Vancouver, BC · 170,072 km	$10,500
Toronto, ON · 183,870 km	$11,999

Fort McMurray, AB · 191,804 km	$9,341
St-Hubert, QC · 94,085 km	$11,495

§4 EVENTS

2014	Model year 2014[1] Assembly plant Brampton, Ontario, Canada
9 Oct 2014	Transport Canada recall 2014446[2] Issued for the model year · Electrical
26 Apr 2016	Transport Canada recall 2016184[2] Issued for the model year · Powertrain
15 Feb 2017	Transport Canada recall 2017081[2] Issued for the model year · Powertrain
10 Jul 2017	Transport Canada recall 2017341[2] Issued for the model year · Electrical
22 Nov 2017	Transport Canada recall 2017574[2] Issued for the model year · Electrical
17 May 2018	Transport Canada recall 2018269[2] Issued for the model year · Engine
27 Jul 2018	Transport Canada recall 2018396[2] Issued for the model year · Accessories
11 Jan 2019	Transport Canada recall 2019016[2] Issued for the model year · Airbag
15 Aug 2024	Transport Canada recall 2024548[2] Issued for the model year · Label
26 Oct 2026	Listed for sale, Laval, QC[5] Autos Deal · asking $2,999

§5 DOCUMENTS

Window sticker — We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 10 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.