

Register entry, as of 27 October 2026

Listed for sale

Record ID bda7215ab84d

2019 Dodge Charger SXT

3.6 L, 6 cylinders · RWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2C3 CDXBG 4 K H 630675

WMI 1-3

Dodge · FCA CANADA INC.

DESCRIPTOR 4-8

Charger · 3.6 L

CHECK 9

Verified

YEAR 10

2019

PLANT 11

Brampton

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	3.6 L, 6 cylinders
Make	Dodge	Fuel	Gasoline
Model	Charger	Drive	RWD
Trim	SXT	Maker	FCA CANADA INC.
Body	Sedan	Plant	Brampton, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/dodge/charger/2019

5 recalls listed by Transport Canada for this model year

Label	2024548	15 Aug 2024
Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.		
Airbag	2024168	14 Mar 2024
Issue: On certain vehicles, the side curtain airbag inflators could be defective. As a result, the driver and/or passenger side curtain airbag inflator(s) could rupture unexpectedly and metal fragments could be propelled toward vehicle occupants. Safety Risk: An airbag inflator that ruptures can create a risk of injury. Corrective Actions: FCA will notify owners by mail and advise you to take your vehicle to a dealership to replace both side curtain airbag modules.		
Visual system	2020397	27 Aug 2020
Issue: On certain vehicles, if the "stealth mode" feature is activated to turn off the rearview camera image, the display will not turn on when the driver shifts to reverse. Canadian regulations require the rearview image to display each time that the transmission is shifted into reverse gear. Note: Deactivating stealth mode will return the display to normal operation. Safety Risk: A rearview camera image that does not display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Fiat Chrysler Automobiles will notify owners by mail and instruct you to take your vehicle to a dealer to update the body control module software. This update will disable stealth mode when the transmission is shifted into reverse.		



Label

2019161 29 Mar 2019

Issue: Certain vehicles may have incorrect or missing airbag warning labels on the driver and passenger sun visors. These labels are required under Canadian regulations. Safety Risk: Vehicles with missing or incorrect airbag warning information could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to replace the driver and passenger sun visors.

Lights and instruments

2019137 15 Mar 2019

Issue: On certain vehicles, the instrument cluster may not work. Safety Risk: An instrument cluster that does not work may prevent an operator from receiving information regarding the status of vehicle systems. This could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a dealer to have the instrument cluster software updated.

Listed for the model year, not checked against your VIN. Dodge confirms which apply.

Check your VIN with Mopar Canada or call a Dodge dealer with your VIN.

www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$19,898^[5], \$410 over the median of \$19,488^[4].



Lowest ask	\$9,900
Middle half	\$16,599 – \$19,999
Median ask	\$19,488
This car	\$19,898

Same model year · 19 live listings · as of 27 Oct 2026

OTHER 2019 DODGE CHARGER LISTINGS [5]

Chatham-Kent, ON · 110,963 km	\$17,586
Dartmouth, NS · 124,898 km	\$15,699
Leamington, ON · 125,010 km	\$19,488
La Malbaie, QC · 107,887 km	\$19,999
St. Paul, AB · 202,854 km	\$18,999
Duncan, BC · 88,297 km	\$19,900

§4 EVENTS

2019	Model year 2019 ^[1] Assembly plant Brampton, Ontario, Canada
15 Mar 2019	Transport Canada recall 2019137 ^[2] Issued for the model year · Lights and instruments
29 Mar 2019	Transport Canada recall 2019161 ^[2] Issued for the model year · Label
27 Aug 2020	Transport Canada recall 2020397 ^[2] Issued for the model year · Visual system



14 Mar 2024 Transport Canada recall 2024168^[2]
Issued for the model year · Airbag

15 Aug 2024 Transport Canada recall 2024548^[2]
Issued for the model year · Label

22 Aug 2026 Listed for sale, Sherwood Park, AB^[5]
Sherwood Honda · asking \$19,898

26 Oct 2026 Listing last updated^[5]
asking \$19,898

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 19 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

