

Register entry, as of 26 October 2026

Listed for sale

Record ID eeed7e2b8f41

2015 Dodge Challenger SXT Plus

3.6 L, 6 cylinders · RWD · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2C3 CDZBG X F H 712380

WMI 1-3

Dodge · FCA CANADA INC.

DESCRIPTOR 4-8

Challenger · 3.6 L

CHECK 9

Verified

YEAR 10

2015

PLANT 11

Brampton

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	3.6 L, 6 cylinders
Make	Dodge	Fuel	Gasoline
Model	Challenger	Drive	RWD
Trim	SXT Plus	Maker	FCA CANADA INC.
Body	Coupe	Plant	Brampton, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/dodge/challenger/2015

5 recalls listed by Transport Canada for this model year

Label 2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Accessories 2018396 27 Jul 2018

Note: This recall affects the following Powertrain Control Modules (PCM) that were sold through dealers as high-performance accessories: - Mopar Stage 1 high performance Powertrain Control Modules (PCM), part numbers P5160023 and P5160025 (campaign U82) - Mopar high performance Powertrain Control Modules (PCM) included in the Demon Crate, part number 68412287AA (campaign U83) On certain vehicles, an electronic fault may create a situation where the cruise control cannot be deactivated. If this occurs and the driver does not apply the brakes or shift the transmission to neutral, the vehicle could maintain speed or accelerate without warning, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the PCM software and perform an update as necessary. Note: In the interim, owners are advised not to use the cruise control until the vehicle is repaired. This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act, as these aftermarket products were not regulated by the Act.

Engine 2018269 17 May 2018

On certain vehicles, an electronic fault may create a situation where the cruise control cannot be deactivated. If this occurs and the driver does not apply the brakes or shift the transmission to neutral, the vehicle could maintain speed or accelerate without warning, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the Powertrain Control Module (PCM) software and perform an update as necessary. Note: In the interim, owners are advised not to use the cruise control until the vehicle is repaired.



Airbag

2015203 14 May 2015

On certain vehicles, a bolt which attaches the side air bag inflated curtain to the vehicle structure may be loose or missing. In the event of a side impact or roll-over crash that warrants side air bag curtain deployment, a loose or missing bolt could result in improper deployment. This could increase the risk of injury. Correction: Dealers will inspect and repair the bolts as required.

Fuel system

2015086 26 Feb 2015

On certain vehicles equipped with a 6.2L supercharged engine, the fuel rail crossover hose may leak in the engine compartment. Leaking fuel in the presence of an ignition source could lead to a fire causing injury and/or damage to property. Correction: Dealers will replace the fuel rail crossover hose.

Listed for the model year, not checked against your VIN. Dodge confirms which apply.
Check your VIN with Mopar Canada or call a Dodge dealer with your VIN.
www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$19,995^[5], \$7,254 under the median of \$27,249^[4].



Lowest ask	\$14,882
Middle half	\$18,248 – \$33,747
Median ask	\$27,249
This car	\$19,995

Same model year · 14 live listings · as of 26 Oct 2026

OTHER 2015 DODGE CHALLENGER LISTINGS ^[5]

Surrey, BC · 69,498 km	\$31,885
Surrey, BC · 109,782 km	\$30,999
Winnipeg, MB · 47,811 km	\$30,499
Scarborough, ON · 0 km	\$77,777
Ottawa, ON · 132,396 km	\$17,997
Scarborough, ON · 63,502 km	\$33,996

§4 EVENTS

2015	Model year 2015 ^[1] Assembly plant Brampton, Ontario, Canada
26 Feb 2015	Transport Canada recall 2015086 ^[2] Issued for the model year · Fuel system
14 May 2015	Transport Canada recall 2015203 ^[2] Issued for the model year · Airbag
17 May 2018	Transport Canada recall 2018269 ^[2] Issued for the model year · Engine



27 Jul 2018	Transport Canada recall 2018396 ^[2] Issued for the model year · Accessories
15 Aug 2024	Transport Canada recall 2024548 ^[2] Issued for the model year · Label
26 Oct 2026	Listed for sale, Shawinigan, QC ^[5] garagedulac.net · asking \$19,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 14 live listings, as of 26 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 26 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

