

Register entry, as of 27 October 2026

Listed for sale

Record ID 8b9d94239a05

2008 Chrysler 300 Touring

3.5 L, 6 cylinders · RWD · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2C3

WMI 1-3

Chrysler · FCA CANADA INC.

KA53G

DESCRIPTOR 4-8

300 · 3.5 L

X

CHECK 9

Verified

8

YEAR 10

2008

H

PLANT 11

Brampton

252815

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2008	Engine	3.5 L, 6 cylinders
Make	Chrysler	Fuel	Gasoline
Model	300	Drive	RWD
Trim	Touring	Maker	FCA CANADA INC.
Body	Sedan	Plant	Brampton, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chrysler/300/2008

4 recalls listed by Transport Canada for this model year

Airbag 2016265 27 May 2016

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

Airbag 2015228 27 May 2015

On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Note: This recall supersedes special service campaign 2015-003. Correction: Dealers will replace airbag inflators. All vehicles having received a replacement inflator as part of the previous special service campaign will have a replacement inflator installed.

Electrical 2014404 18 Sep 2014

On certain vehicles, the ignition key may not fully return to the RUN position from the START position once the key is released after starting the vehicle. This could affect various vehicle electrical functions, and also cause an unintended change in ignition switch position, which could cause the engine to stall. This would result in a loss of motive power and affect functioning of the power steering and power braking assist systems as well as other safety systems including airbags. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the Wireless Ignition Node (WIN) module (i.e. ignition switch) and FOBs (keys).



Other

2008233 3 Jul 2008

On certain vehicles, incorrectly manufactured rear axle hub nuts could, in time, loosen, and allow the halfshaft to disengage from the wheel hub assembly. This could cause the vehicle to lose propulsion which, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash. Correction: Dealers will replace the rear axle hub nuts.

Listed for the model year, not checked against your VIN. Chrysler confirms which apply.
Check your VIN with Mopar Canada or call a Chrysler dealer with your VIN.
www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$1,495^[5], \$500 under the median of \$1,995^[4].



Lowest ask	\$1,495
Middle half	\$1,745 – \$4,472
Median ask	\$1,995
This car	\$1,495

Same model year · 3 live listings · as of 27 Oct 2026

OTHER 2008 CHRYSLER 300 LISTINGS [5]

London, ON · 111,367 km	\$1,995
Hamilton, ON · 138,814 km	\$6,950

§4 EVENTS

2008	Model year 2008 ^[1] Assembly plant Brampton, Ontario, Canada
3 Jul 2008	Transport Canada recall 2008233 ^[2] Issued for the model year · Other
18 Sep 2014	Transport Canada recall 2014404 ^[2] Issued for the model year · Electrical
27 May 2015	Transport Canada recall 2015228 ^[2] Issued for the model year · Airbag
27 May 2016	Transport Canada recall 2016265 ^[2] Issued for the model year · Airbag
25 Oct 2026	Listed for sale, London, ON ^[5] Tiger Auto Sales Ltd. · asking \$1,495
27 Oct 2026	Listing last updated ^[5] asking \$1,495



§5 DOCUMENTS

Window sticker This VIN reads as model year 2008, before our coverage for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 3 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

