Register entry, as of 26 October 2026 Listed for sale Record ID 61c0307c5906

2022 Chrysler Pacifica Touring L

3.6 L, 6 cylinders · FWD · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2C4	RC1BG	X	N	R	106144
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chrysler · FCA CANADA INC.	Pacifica · 3.6 L	Verified	2022	Windsor	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	3.6 L, 6 cylinders
Make	Chrysler	Fuel	Gasoline
Model	Pacifica	Drive	FWD
Trim	Touring L	Maker	FCA CANADA INC.
Body	Minivan	Plant	Windsor, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chrysler/pacifica/2022

8 recalls listed by Transport Canada for this model year

High voltage

2026272 4 Jun 2026

Issue: On certain vehicles, the high-voltage battery could fail. If this happens, the high-voltage battery could overheat. Note: This recall only affects plug-in hybrid (PHEV) models. Safety Risk: A high-voltage battery that fails can create a fire risk, even while the vehicle is parked and turned off. Corrective Actions: To reduce the safety risk, FCA Canada advises that you should not charge your vehicle and to park the vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed. FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the high-voltage battery. The dealer will also install an advanced diagnostic software that will monitor the high-voltage battery and warn you if it detects a problem.

Seats and restraints

2026141 26 Mar 2026

Issue: On certain vehicles, the side curtain airbag(s) may not have been manufactured properly. As a result, the airbag(s) may not inflate properly in a crash. Note: This is an expansion of Transport Canada recalls 2025-291 and 2025-454. Safety Risk: A side curtain airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the side curtain airbag(s), as necessary.

Seats and restraints

2026003 5 Jan 2026

Issue: On certain vehicles converted for wheelchair access by Vantage Mobility, the wheelchair tie-down retractors may not have been manufactured properly. As a result, the retractor(s) may not lock automatically. If this happens, the wheelchair may not be secured correctly and could move in a crash. Note: This recall only affects certain Q'Straint QRT-DELUXE and QRT-MAX wheelchair retractors with the part number Q8-6200 or Q8-6209. Safety Risk: A wheelchair that moves in a crash could increase the risk of injury. Corrective Actions: To reduce the safety risk, Vantage Mobility recommends you confirm the wheelchair is secured properly by attempting to move it before driving until the recall repairs have been completed. Vantage Mobility will notify owners by mail and advise you to take your vehicle to a Vantage Mobility service center to inspect and, if necessary, replace the wheelchair retractor(s).

Airbag

2025291 29 May 2025

Issue: On certain vehicles, the side curtain airbag(s) may not have been manufactured properly. As a result, the airbag(s) may not inflate properly in a crash. Safety Risk: A side curtain airbag that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners in writing. The corrective actions for this recall are under development.

Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Visual system

2024338 13 Jun 2024

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Note: For the Grand Cherokee model, this recall affects 2022-2023 Jeep Grand Cherokee and 2021-2023 Grand Cherokee L models. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the radio software.

2 more on the model-year record, cardog.app/tools/recalls/chrysler/pacifica/2022

> Listed for the model year, not checked against your VIN. Chrysler confirms which apply.
> Check your VIN with Mopar Canada or call a Chrysler dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $34,000[5], $6,964 over the median of $27,036[4].



Lowest ask	$19,900
Middle half	$26,895 – $28,996
Median ask	$27,036
This car	$34,000

Same configuration · 13 live listings · as of 26 Oct 2026

OTHER 2022 CHRYSLER PACIFICA LISTINGS [5]

Nanaimo, BC · 104,208 km	$30,985
Lloydminster, AB · 70,658 km	$32,995
Simcoe, ON · 99,719 km	$33,495
Mont-Laurier, QC · 102,051 km	$29,998
Manotick, ON · 121,000 km	$28,795
London, ON · 67,803 km	$30,999

§4 EVENTS

2022 **Model year 2022**[1]
Assembly plant Windsor, Ontario, Canada

11 Aug 2022	Transport Canada recall 2022454[2] Issued for the model year · Visual system
18 Jan 2023	Transport Canada recall 2023008[2] Issued for the model year · Electrical
13 Jun 2024	Transport Canada recall 2024338[2] Issued for the model year · Visual system
15 Aug 2024	Transport Canada recall 2024548[2] Issued for the model year · Label
29 May 2025	Transport Canada recall 2025291[2] Issued for the model year · Airbag
5 Jan 2026	Transport Canada recall 2026003[2] Issued for the model year · Seats and restraints
26 Mar 2026	Transport Canada recall 2026141[2] Issued for the model year · Seats and restraints
4 Jun 2026	Transport Canada recall 2026272[2] Issued for the model year · High voltage
26 Oct 2026	Listed for sale, Oakville, ON[5] SOUTH OAKVILLE CHRYSLER · asking $34,000

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 13 live listings, as of 26 Oct 2026
[5] Live public dealer listings on Cardog, as of 26 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.