Register entry, as of 29 October 2026 Listed for sale Record ID 4c595a204a09

2011 GMC Terrain SLT 1

3.0 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2CT	FLVE5	9	B	6	383955
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
GMC · GENERAL MOTORS…	Terrain · 3.0 L	Verified	2011	Ingersoll	Build sequence

§1 IDENTITY [1]

Model year	2011	Engine	3.0 L, 6 cylinders
Make	GMC	Fuel	Gasoline
Model	Terrain	Drive	AWD
Trim	SLT 1	Maker	GENERAL MOTORS LLC
Body	Sport Utility Vehicle	Plant	Ingersoll, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/gmc/terrain/2011

4 recalls listed by Transport Canada for this model year

Visual system

2018137 16 Mar 2018

In certain vehicles, water may drain from the windshield cowl area onto the windshield wiper transmission link joints. Over time, this could result in corrosion and/or wear to the joint, which could result in the separation of the wiper link ball from its corresponding socket. If separation were to occur, the windshield wipers could become inoperative, which could limit the driver's visibility under certain operating conditions and increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will relocate drain holes in the windshield cowl and install a wiper module with revised joints. Note: This is an expansion of recall 2016-318 to include vehicles originally sold or registered in the province of British Columbia.

Visual system

2016318 22 Jun 2016

In certain vehicles registered and operated in areas where road salt is used on the roadways during winter months for extended time periods (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island and Newfoundland-Labrador), water may drain from the windshield cowl area onto one of the windshield wiper transmission link joints. Over time, this could result in corrosion and/or wear to the joint, which could result in the separation of the wiper link ball from its corresponding socket. If separation were to occur, the windshield wipers could become inoperative, which could limit the driver’s visibility under certain operating conditions which may increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will relocate drain holes in the windshield cowl and install a wiper module with revised joints.

Seats and restraints

2014311 23 Jul 2014

On certain vehicles equipped with power height adjustable front seats, a bolt securing the adjuster mechanism may loosen and fall out. This would cause the seat to drop to the lowest vertical adjustment position, which could affect the driver's ability to safety operate vehicle controls as well as cause reduced driver visibility. These issues could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the bolt.

Seats and restraints

2010446 16 Dec 2010

On certain vehicles, the driver and/or front passenger seatbelt buckle anchors may fracture and separate near the seat attachment during a vehicle crash. If this were to occur, the seatbelt system may not restrain the seat occupant as intended, which could increase the risk of personal injuries during a crash. Correction: Dealers will modify the passenger and, in some cases, the driver seatbelt buckle assemblies.

Listed for the model year, not checked against your VIN. GMC confirms which apply.
Check your VIN with GMC Canada or call a GMC dealer with your VIN.
www.gmccanada.ca/en/ownercenter/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $9,946[5], $204 over the median of $9,742[4].

Lowest ask	$3,495
Middle half	$3,998 – $11,245
Median ask	$9,742
This car	$9,946

Same model year · 8 live listings · as of 29 Oct 2026

OTHER 2011 GMC TERRAIN LISTINGS [5]

Drummondville, QC · 149,952 km	$3,995
Powell River, BC · 117,041 km	$10,588
London, ON · 149,350 km	$3,495
Warman, SK · 159,463 km	$11,995
Mississauga, ON · 215,809 km	$1,900
London, ON · 150,995 km	$10,995

§4 EVENTS

2011	Model year 2011[1] Assembly plant Ingersoll, Ontario, Canada
16 Dec 2010	Transport Canada recall 2010446[2] Issued for the model year · Seats and restraints
23 Jul 2014	Transport Canada recall 2014311[2] Issued for the model year · Seats and restraints
22 Jun 2016	Transport Canada recall 2016318[2] Issued for the model year · Visual system
16 Mar 2018	Transport Canada recall 2018137[2] Issued for the model year · Visual system
7 Mar 2026	Listed for sale, Calgary, AB[5] Fine Auto Zone · asking $9,946

24 Oct 2026 Listing last updated[5]
asking $9,946

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 8 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.