Register entry, as of 28 October 2026 Listed for sale Record ID 7856902eb5e6

# 2010 Dodge Grand Caravan SE

3.3 L, 6 cylinders · FWD · Minivan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 2D4 | RN4DE | 6 | A | R | 203703 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Dodge · FCA CANADA INC. | Grand Caravan · 3.3 L | Verified | 2010 | Windsor | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2010 | Engine | 3.3 L, 6 cylinders |
| Make | Dodge | Fuel | Gasoline |
| Model | Grand Caravan | Drive | FWD |
| Trim | SE | Maker | FCA CANADA INC. |
| Body | Minivan | Plant | Windsor, Ontario, Canada |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/dodge/grand-caravan/2010

**9** recalls listed by Transport Canada for this model year

### Airbag

2020311 8 Jul 2020

Issue: On certain vehicles, the emblem on the steering wheel could become loose. If this happens, the emblem or its retainers could become projectiles when the airbag inflates in a crash. Safety Risk: Loose parts that are projected toward the occupants when an airbag deploys could increase the risk of an injury. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to replace the airbag cover on the steering wheel.

### Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

### Seats and restraints

2018439 21 Aug 2018

On certain wheelchair-accessible vehicles, the bolts used to attach the removable seats to the floor may contain a defect and could break in the event of a crash, creating a risk of injury. Correction: Dealers will replace the defective bolts.

### Fuel system

2016575 17 Nov 2016

On certain Amerivan 10 wheelchair accessible vehicles built on Dodge Grand Caravan and Chrysler Town and Country platforms, the crimp fasteners used to retain fittings in the fuel line may not be fully crimped or compressed. This could result in a fuel leak. Leaking fuel, in the presence of an ignition source, could lead to a fire causing injury and/or damage to property. Correction: Dealers will inspect fasteners and crimp the fasteners further to ensure they are fully compressed and seated.

### Electrical

2015250 4 Jun 2015

On certain vehicles, the Wireless Ignition Node (a.k.a ignition switch) may allow the ignition key to inadvertently move from the ON position to the accessory (ACC) position while driving, causing the engine to shut off. This would result in a loss of motive power, power steering and power brakes, and would disable the airbags as well as other supplemental restraint systems (SRS). Increased steering and braking effort and a loss of motive power could increase the risk of a crash causing injury and/or damage to property. Loss of airbag / SRS function in a crash that warrants airbag deployment and/or other supplemental restraint system function could increase the risk of injury to vehicle occupants. Correction: Dealers will install a revised WIN module and frequency operated button ignition key (FOBIK). Note: Until the correction is performed, owners are advised to remove all objects from the FOBIK (Ignition Key) such as additional keys, key chains, etc, leaving only the FOBIK (ignition key). After starting the vehicle, drivers should ensure that the key is securely and correctly aligned in the “ON” position before driving the vehicle. Note: This recall supersedes recalls 2011096 and 2014261. Vehicles having been serviced as part of these previous recalls will require re-inspection and repair.

### Electrical

2014261 2 Jul 2014

On certain vehicles, the Wireless Ignition Node (a.k.a ignition switch) may allow the ignition key to inadvertently move from the ON position to the accessory (ACC) position while driving, causing the engine to shut off. This would result in a loss of motive power, power steering and power brakes, and would disable the airbags as well as other supplemental restraint systems (SRS). Increased steering and braking effort and a loss of motive power could increase the risk of a crash causing injury and/or damage to property. Loss of airbag / SRS function in a crash that warrants airbag deployment and/or other supplemental restraint system function could increase the risk of injury to vehicle occupants. Correction: Dealers will install a revised WIN module and frequency operated button ignition key (FOBIK). Note: Until the correction is performed, owners are advised to remove all objects from the FOBIK (Ignition Key) such as additional keys, key chains, etc, leaving only the FOBIK (ignition key). After starting the vehicle, drivers should ensure that the key is securely and correctly aligned in the “ON” position before driving the vehicle. Note: This recall is superseded by recall 2015-250.

3 more on the model-year record, cardog.app/tools/recalls/dodge/grand-caravan/2010

> Listed for the model year, not checked against your VIN. Dodge confirms which apply.
> Check your VIN with Mopar Canada or call a Dodge dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $1,900[5], $2,095 under the median of $3,995[4].




| | |
|---|---|
| Lowest ask | $1,900 |
| Middle half | $2,999 – $5,656 |
| Median ask | $3,995 |
| This car | $1,900 |

Same configuration · 9 live listings · as of 28 Oct 2026

### OTHER 2010 DODGE GRAND CARAVAN LISTINGS [5]

| | |
|---|---|
| Windsor, ON · 0 km | $5,656 |
| Grimsby, ON · 270,637 km | $3,498 |
| Fenwick, ON · 299,000 km | $3,690 |
| New Westminster, BC · 200,000 km | $6,500 |

| | |
|---|---|
| Mission, BC · 170,223 km | $5,500 |
| Toronto, ON · 95,000 km | $19,999 |

## §4 EVENTS

| | |
|---|---|
| 2010 | Model year 2010[1]<br>Assembly plant Windsor, Ontario, Canada |
| 2 Mar 2011 | Transport Canada recall 2011096[2]<br>Issued for the model year · Other |
| 3 Feb 2014 | Transport Canada recall 2014031[2]<br>Issued for the model year · Structure |
| 8 May 2014 | Transport Canada recall 2014167[2]<br>Issued for the model year · Electrical |
| 2 Jul 2014 | Transport Canada recall 2014261[2]<br>Issued for the model year · Electrical |
| 4 Jun 2015 | Transport Canada recall 2015250[2]<br>Issued for the model year · Electrical |
| 17 Nov 2016 | Transport Canada recall 2016575[2]<br>Issued for the model year · Fuel system |
| 21 Aug 2018 | Transport Canada recall 2018439[2]<br>Issued for the model year · Seats and restraints |
| 21 Aug 2019 | Transport Canada recall 2019420[2]<br>Issued for the model year · Other |
| 8 Jul 2020 | Transport Canada recall 2020311[2]<br>Issued for the model year · Airbag |
| 25 Oct 2026 | Listed for sale, Aylmer, ON[5]<br>Arrow Motors · asking $1,900 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $1,900 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | This VIN reads as model year 1980 or 2010, before our coverage for this manufacturer. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 9 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.