

Register entry, as of 28 October 2026

Listed for sale

Record ID 2ca581376080

2017 Ford Flex SEL

3.5 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2FM **HK6C8** **8** **H** **B** **A07303**

WMI 1-3

Ford Motor Company Of C...

DESCRIPTOR 4-8

Flex · 3.5 L

CHECK 9

Verified

YEAR 10

2017

PLANT 11

Oakville

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	3.5 L, 6 cylinders
Make	Ford	Fuel	Gasoline
Model	Flex	Drive	AWD
Trim	SEL	Maker	FORD MOTOR COMPANY OF CANADA, LTD.
Body	Sport Utility Vehicle	Plant	Oakville, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/flex/2017

5 recalls listed by Transport Canada for this model year

Structure	2026328	1 Jul 2026
Issue: On certain vehicles, the exterior B-pillar trims on the front and rear driver-side and passenger-side doors may not be properly attached. As a result, the trim(s) could loosen and separate from the vehicle. Note: This recall replaces Transport Canada recall no. 2025-588. Safety Risk: Trim that detaches from the vehicle could create a hazard for others and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to secure the exterior B-pillar trims.		
Structure	2025588	24 Oct 2025
Issue: On certain vehicles, the exterior B-pillar trims on the driver and front passenger doors may not be properly attached. As a result, the trim(s) could loosen and separate from the vehicle. Safety Risk: Trim that detaches from the vehicle could create a hazard for others and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, repair or replace the exterior B-pillar trims, as necessary.		
Suspension	2020051	11 Feb 2020
Issue: On certain vehicles, the rear suspension toe link(s) could break. This could cause a sudden loss of vehicle stability. Note: Vehicles previously repaired under Ford Campaign 19R01 or 19S18 do not require repair under this recall. For the Taurus model, only the SHO Performance Package model is included in this recall. Safety Risk: A loss of vehicle stability could cause a loss of control and increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a Ford or Lincoln dealer to install improved rear suspension toe links.		



Suspension

2019281 11 Jun 2019

Issue: On certain vehicles, a buildup of dirt and mud could cause the rear suspension toe links to break. This could result in a sudden loss of vehicle stability. Note: This problem affects vehicles operated in Alberta, Saskatchewan and Manitoba. The unique soil properties in this region could make a toe link more likely to break. Safety Risk: A loss of stability could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to install improved rear suspension toe links.

Powertrain

2016639 19 Dec 2016

On certain vehicles, the turbocharger oil supply tube may have been improperly brazed. This could allow engine oil to leak and come in contact with hot surfaces, increasing the risk of fire resulting in injury and/or damage to property. Correction: Dealers will inspect oil supply lines and replace as required.

Listed for the model year, not checked against your VIN. Ford confirms which apply.

Check your VIN with Ford Canada or call a Ford dealer with your VIN.

www.ford.ca/support/recalls/

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$13,889^[5], \$219 over the median of \$13,670^[4].



Lowest ask	\$10,999
Middle half	\$12,837 – \$14,416
Median ask	\$13,670
This car	\$13,889

Same model year · 4 live listings · as of 28 Oct 2026

OTHER 2017 FORD FLEX LISTINGS [5]

Toronto, ON · 155,300 km	\$10,999
Quebec, QC · 127,300 km	\$13,450
Toronto, ON · 136,600 km	\$15,999

§4 EVENTS

2017	Model year 2017 ^[1] Assembly plant Oakville, Ontario, Canada
19 Dec 2016	Transport Canada recall 2016639 ^[2] Issued for the model year · Powertrain
11 Jun 2019	Transport Canada recall 2019281 ^[2] Issued for the model year · Suspension
11 Feb 2020	Transport Canada recall 2020051 ^[2] Issued for the model year · Suspension
24 Oct 2025	Transport Canada recall 2025588 ^[2] Issued for the model year · Structure



1 Jul 2026	Transport Canada recall 2026328 ^[2] Issued for the model year · Structure
22 Jul 2026	Listed for sale, St Stephen, NB ^[5] Downey Ford Sales (St Stephen Div) · asking \$13,889
28 Oct 2026	Listing last updated ^[5] asking \$13,889

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 4 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

