

Register entry, as of 28 October 2026

Listed for sale

Record ID 7a5dcfc3245c

2016 Ford Edge Titanium

3.5 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2FM **PK4K8** **5** **G** **B** **C18748**

WMI 1-3

Ford Motor Company Of C...

DESCRIPTOR 4-8

Edge · 3.5 L

CHECK 9

Verified

YEAR 10

2016

PLANT 11

Oakville

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	3.5 L, 6 cylinders
Make	Ford	Fuel	Gasoline
Model	Edge	Drive	AWD
Trim	Titanium	Maker	FORD MOTOR COMPANY OF CANADA, LTD.
Body	Sport Utility Vehicle	Plant	Oakville, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ford/edge/2016

7 recalls listed by Transport Canada for this model year

Visual system

2025449 3 Sep 2025

Issue: On certain vehicles, there could be a problem with the connections inside the rearview camera. As a result, the rearview camera image may not display correctly or at all when the transmission is shifted into reverse. Note: For certain models, this recall also affects incomplete vehicles.

Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the rearview camera.

Brakes

2025435 22 Aug 2025

Issue: On certain vehicles, the rear brake hoses could fail and cause a progressive brake fluid leak. If this happens, there could be reduced braking. Note: This problem could cause a change in brake pedal feel and travel. Safety Risk: Reduced braking can cause extended stopping distances and increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to inspect and replace or reroute the rear brake hoses, as necessary.

Powertrain

2022311 13 Jun 2022

Issue: On certain vehicles, the shift cable may detach from the transmission. This could cause the transmission not to shift gears when the shifter is moved. As a result, the transmission could be in a different gear than the gear shifter indicates. If a driver attempts to exit the vehicle while the transmission is not in Park, and the parking brake is not applied, the vehicle could move suddenly. Safety Risk: Sudden and unexpected movement of the vehicle could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and instruct you to take your vehicle to a dealership to replace the transmission shifter cable bushing and install a protective service cap. Ford advises that you should apply the parking brake each time the vehicle is parked.



Brakes

2020373 13 Aug 2020

Issue: On certain vehicles, the front brake hoses could fail, causing a progressive brake fluid leak. If this happens, the driver may experience a change in brake pedal feel and travel. This can cause reduced brake performance. **Note:** A brake fluid leak would cause the brake warning light to turn on. **Safety Risk:** Reduced brake performance could cause extended stopping distances and increase the risk of a crash. **Corrective Actions:** Ford will notify owners by mail and instruct you to take your vehicle to a dealer to replace the front brake hoses.

Steering

2019431 27 Aug 2019

Issue: On certain vehicles, the bolts that attach the electric power steering assist motor to the steering gear may corrode and break. This could cause a loss of power steering assist. This recall applies to vehicles originally sold or currently registered in areas of heavy road salt usage (Ontario, Quebec, New Brunswick, Nova Scotia, Prince Edward Island, and Newfoundland & Labrador). **Safety Risk:** A loss of power steering assist may result in a sudden increase in steering effort, especially at low vehicle speeds. This could increase the risk of a crash. **Corrective Actions:** The company will notify owners by mail and instruct you to take your vehicle to a Ford or Lincoln dealer to replace the bolts and apply a wax sealer. If one or more of the bolts are broken or missing, a new steering gear will be installed.

Airbag

2017102 1 Mar 2017

Certain vehicles may fail to comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 208 - Occupant Protection in Frontal Impacts. Certain driver frontal airbag modules may have been assembled incorrectly. In the event of a crash warranting deployment of the driver's frontal airbag, the airbag may not completely fill, or the airbag cushion may detach from the airbag module, which would not protect the driver as expected, and could increase the risk of injury. **Correction:** Dealers will replace the driver's frontal airbag.

1 more on the model-year record, cardog.app/tools/recalls/ford/edge/2016

Listed for the model year, not checked against your VIN. Ford confirms which apply.

Check your VIN with Ford Canada or call a Ford dealer with your VIN.

www.ford.ca/support/recalls/

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$11,999^[5], \$946 under the median of \$12,945^[4].



Lowest ask	\$6,995
Middle half	\$10,988 – \$14,888
Median ask	\$12,945
This car	\$11,999

Same model year · 37 live listings · as of 28 Oct 2026

OTHER 2016 FORD EDGE LISTINGS ^[5]

Lethbridge, AB · 91,376 km	\$17,827
Aylmer, ON · 97,000 km	\$13,495
Kentville, NS · 76,037 km	\$16,999
Notre-Dame-Des-Prairies, QC · 102,566 km	\$15,995
Montréal, QC · 58,369 km	\$15,995
Carignan, QC · 99,979 km	\$12,945



§4 EVENTS

2016	Model year 2016 ^[1] Assembly plant Oakville, Ontario, Canada
11 Oct 2016	Transport Canada recall 2016493 ^[2] Issued for the model year · Brakes
1 Mar 2017	Transport Canada recall 2017102 ^[2] Issued for the model year · Airbag
27 Aug 2019	Transport Canada recall 2019431 ^[2] Issued for the model year · Steering
13 Aug 2020	Transport Canada recall 2020373 ^[2] Issued for the model year · Brakes
13 Jun 2022	Transport Canada recall 2022311 ^[2] Issued for the model year · Powertrain
22 Aug 2025	Transport Canada recall 2025435 ^[2] Issued for the model year · Brakes
3 Sep 2025	Transport Canada recall 2025449 ^[2] Issued for the model year · Visual system
27 Oct 2026	Listed for sale, Parry Sound, ON ^[5] Parry Sound Chevrolet Buick GMC Ltd · asking \$11,999
28 Oct 2026	Listing last updated ^[5] asking \$11,999

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|---|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 37 live listings, as of 28 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 28 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

