Register entry, as of 28 October 2026 Listed for sale Record ID 4ed19cdffa15

2014 Chevrolet Camaro 2LT

3.6 L, 6 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2G1	FC1E3	6	E	9	286002
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chevrolet · GENERAL MOT…	Camaro · 3.6 L	Verified	2014	Oshawa #1	Build sequence

§1 IDENTITY [1]

Model year	2014	Engine	3.6 L, 6 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Camaro	Drive	Not in the decode
Trim	2LT	Maker	GENERAL MOTORS LLC
Body	Coupe	Plant	Oshawa #1, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/camaro/2014

3 recalls listed by Transport Canada for this model year

Electrical

2019463 19 Sep 2019

Issue: This recall is for replacement flip key assemblies sold as replacement parts. Please see Transport Canada Recall No. 2014-243 for additional details. There is a risk that some drivers may bump the ignition key with their knee and unintentionally move the key out of the "run" position. If this happens, engine power, power braking and power steering would be affected. This can cause a sudden increase steering and brake pedal effort. This could also cause the airbags not to deploy in a crash. Safety Risk: Airbags that do not deploy properly could create an increased risk of injury in a crash. An increase brake pedal effort could cause extended stopping distances and increase the risk of a crash. Sudden changes in steering effort could also increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and instruct them to take their vehicle to a dealer to inspect the key(s). If a flip key is found, it will be replaced with a flat blade key as in Transport Canada Recall No. 2014-243.

Electrical

2014243 20 Jun 2014

On certain vehicles, there is a risk that some drivers may bump the ignition key with their knee and unintentionally move the key from out of the "run" position. If this were to occur, engine power, power braking and power steering would be affected, which would unexpectedly increase steering and brake pedal effort, potentially increasing stopping distances and the risk of a crash causing injury and/or damage to property. The timing of the key movement out of the "run" position, relative to the activation of the sensing algorithm of the crash event, may also result in the airbags not deploying in a subsequent collision, increasing the risk of injury. Correction: Dealers are to remove the key blade from the original flip key/transmitter assemblies provided with the vehicle, and provide two new keys and two key rings for every original key. Important note: Until the correction is performed, drivers should adjust their seat and steering column to allow clearance between their knee and the ignition key.

Airbag

2013333 27 Sep 2013

Certain vehicles may not comply with Canada Motor Vehicle Safety Standard 208 - Occupant Protection in Frontal Impacts. The airbag warning labels may not be permanently affixed to sun visors. Correction: Owners will be sent instructions on how to inspect labels, or may have the inspection performed at a dealer. Where labels are found to be defective, the sun visors will be replaced.

Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
www.chevrolet.ca/en/ownercenter/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $15,900[5], $10,024 under the median of $25,924[4].

Lowest ask	$11,999
Middle half	$16,674 – $47,148
Median ask	$25,924
This car	$15,900

Same model year · 10 live listings · as of 28 Oct 2026

OTHER 2014 CHEVROLET CAMARO LISTINGS [5]

Notre-Dame-Des-Pins, QC · 35,695 km	$52,995
Surrey, BC · 53,001 km	$22,997
Surrey, BC · 168,099 km	$13,999
Toronto, ON · 167,266 km	$11,999
Toronto, ON · 39,221 km	$52,900
Scarborough, ON · 0 km	$124,777

§4 EVENTS

2014	Model year 2014[1] Assembly plant Oshawa #1, Ontario, Canada
27 Sep 2013	Transport Canada recall 2013333[2] Issued for the model year · Airbag
20 Jun 2014	Transport Canada recall 2014243[2] Issued for the model year · Electrical
19 Sep 2019	Transport Canada recall 2019463[2] Issued for the model year · Electrical
4 Sep 2026	Listed for sale, Cornwall, ON[5] Cornwall Honda · asking $15,900
28 Oct 2026	Listing last updated[5] asking $15,900

§5 DOCUMENTS

Window sticker	This VIN reads as model year 1984 or 2014, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 10 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.