Register entry, as of 25 November 2026 Listed for sale Record ID 1966ee95641e

2006 Chevrolet Impala LS

3.5 L, 6 cylinders · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2G1	WB58N	0	6	9	175874
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Chevrolet · GENERAL MOT…	Impala · 3.5 L	Verified	2006	Oshawa #1	Build sequence

§1 IDENTITY [1]

Model year	2006	Engine	3.5 L, 6 cylinders
Make	Chevrolet	Fuel	Gasoline
Model	Impala	Drive	Not in the decode
Trim	LS	Maker	GENERAL MOTORS LLC
Body	Sedan	Plant	Oshawa #1, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/impala/2006

3 recalls listed by Transport Canada for this model year

Other

2019420 21 Aug 2019

Issue: This recall is for aftermarket replacement rear window glass produced by Vitro Automotriz. Certain rear window glass may not have been properly tempered. If the window breaks, the glass may separate into large pieces instead of very small ones. Note: This is a voluntary recall that is not being conducted under the requirements of the Motor Vehicle Safety Act. Safety Risk: Glass that breaks in to large pieces could create a risk of injury. Corrective Actions: The company will notify consumers by mail and instruct them to inspect the designation code marked on the rear window glass. Products affected by this recall have the designation “DOT 287” along with the lettering “VMR” (Replacement Market) and a date code that is before July 2019. This information is printed on the bottom corner of the glass. Consumers should contact Vitro's customer service at 1-412-995-6457 or argbacklites@vitro.com to arrange for replacement of the glass.

Electrical

2014246 23 Jun 2014

On certain vehicles, a defect in the ignition switch could allow the switch to move out of the "run" position if the key ring is carrying added weight or the vehicle goes off-road or is subjected to some other jarring event. If this were to occur, engine power, power steering and power braking would be affected, increasing the risk of a crash causing injury and/or damage to property. The timing of the key movement out of the “run” position, relative to the activation of the sensing algorithm of the crash event, may also result in the airbags not deploying in a subsequent collision, increasing the risk of injury. Correction: For each key, dealers will install two key rings and modify the key ring opening shape. Note: Until the correction is performed, all items should be removed from the key ring.

Seats and restraints

2006138 15 Jun 2006

On certain vehicles, the weld that attaches the passenger seat adjuster to the left floor mounting bracket may be mislocated and not meet strength specification. In a severe vehicle crash, the seat adjuster may separate from the mounting bracket, increasing the risk of occupant injury. Correction: Dealers will inspect the seat adjuster for a specific date code. All seat adjusters found with that date code will be replaced.

> Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
> Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
> www.chevrolet.ca/en/ownercenter/recalls

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $1,250[5], $1,374 under the median of $2,624[4].



Lowest ask	$1,250
Middle half	$1,937 – $3,310
Median ask	$2,624
This car	$1,250

Same model year · 2 live listings · as of 25 Nov 2026

OTHER 2006 CHEVROLET IMPALA LISTINGS [5]

Prince George, BC · 385,249 km	$3,997

§4 EVENTS

2006	**Model year 2006**[1] Assembly plant Oshawa #1, Ontario, Canada
15 Jun 2006	**Transport Canada recall 2006138**[2] Issued for the model year · Seats and restraints
23 Jun 2014	**Transport Canada recall 2014246**[2] Issued for the model year · Electrical
21 Aug 2019	**Transport Canada recall 2019420**[2] Issued for the model year · Other
24 Jul 2026	**Listed for sale, Burlington, ON**[5] United Stars Auto · asking $1,250
25 Nov 2026	**Listing last updated**[5] asking $1,250

§5 DOCUMENTS

Window sticker	This VIN reads as model year 2006, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 2 live listings, as of 25 Nov 2026
[5] Live public dealer listings on Cardog, as of 25 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.