Register entry, as of 27 November 2026 Listed for sale Record ID 0fbc4a3bf9f4

# 2022 Chevrolet Silverado LTZ

5.3 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 2GC | UDGED | 1 | N | 1 | 516115 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Chevrolet · GENERAL MOT… | Silverado · 5.3 L | Verified | 2022 | Oshawa | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2022 | Engine | 5.3 L, 8 cylinders |
| Make | Chevrolet | Fuel | Gasoline |
| Model | Silverado | Drive | 4WD |
| Trim | LTZ | Maker | GENERAL MOTORS LLC |
| Body | Pickup | Plant | Oshawa, Ontario, Canada |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/chevrolet/silverado/2022

**9** recalls listed by Transport Canada for this model year

### Powertrain

2026060 12 Feb 2026

Issue: On certain vehicles, the recall repairs completed by a General Motors dealer during recall N242454440 (Transport Canada recall no. 2024-637) may not have been done correctly. As a result, a second repair is required. Over time, the transmission control valve could wear and lose pressure. If this happens, the transmission could shift harshly and could cause the rear wheels to lock up. Note: This recall only affects vehicles equipped with a diesel engine. Safety Risk: Rear wheels that lock suddenly could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to update the transmission control module software to detect excess wear in advance of a wheel lock up. If detected, a service engine light would turn on, a message would display in the instrument panel and the vehicle would be limited to fifth gear.

### Engine

2025225 24 Apr 2025

Issue: On certain vehicles, the connecting rods and/or crankshaft components may not have been manufactured properly. As a result, the engine could make abnormal noises and a warning light may turn on. If you continue to drive the vehicle with these symptoms, the engine could fail. Note: This recall only affects certain vehicles equipped with a 6.2 L V8 gas engine. Safety Risk: An engine failure could cause a sudden loss of power to the wheels and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to inspect and, if necessary, repair or replace the engine. For vehicles that pass the engine inspection, the dealer will replace the oil with a higher viscosity oil, install a new oil fill cap, replace the oil filter, and add an insert to the owner's manual.

### Powertrain

2024637 24 Oct 2024

Issue: Over time, the transmission control valve could wear and lose pressure. If this happens, the transmission could shift harshly and could cause the rear wheels to lock up. Note: This recall only affects vehicles equipped with a diesel engine. Safety Risk: Rear wheels that lock suddenly could cause a loss of control and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to update the transmission control module software to detect excess wear in advance of a wheel lock up. If detected, a service engine light would turn on, a message would display in the instrument panel and the vehicle would be limited to fifth gear.

### Structure

2024061 1 Feb 2024

Issue: On certain trucks, water could leak into the exterior tailgate switch. As a result, the tailgate could unlatch and open unexpectedly while parked. If this happens, cargo that is not secured could fall out of the truck bed and onto the road when the vehicle is moving. Note: This recall only affects trucks equipped with a power-locking tailgate. Safety Risk: Cargo that falls from the truck bed could create a road hazard for others and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your truck to a dealership to replace the exterior tailgate switch. To reduce the safety risk, General Motors recommends that you should inspect the tailgate to ensure it's closed and latched before driving.

### Lights and instruments

2024060 1 Feb 2024

Issue: On certain vehicles, a software problem could cause the lower beam headlamps not to turn on as it becomes dark outside if the multi-function switch is in the "OFF" or "PARKING LAMP" position. This could also cause the daytime running lamps (DRLs) to turn off when the vehicle is moving. As a result, the vehicles may not meet certain requirements of Canadian regulations. Safety Risk: Headlamps and/or DRLs that don't turn on could reduce visibility, make the vehicle less visible to others and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and advise you to take your vehicle to a dealership to update the body control module (BCM)software.

### Lights and instruments

2023472 24 Aug 2023

Issue: On certain vehicles, the automatic headlamps may not turn on soon enough as it becomes dark outside. Canadian regulations require automatic headlamps to turn on when the ambient light level drops below a certain point (1000 lux). Safety Risk: Headlamps that don't turn on as it becomes dark outside could reduce visibility and increase the risk of a crash. Corrective Actions: General Motors will notify owners by mail and send a wireless over-the-air software update to eligible vehicles to update the body control module (BCM) software. Alternatively, you may schedule an appointment to have the update performed at a GM dealership.

3 more on the model-year record, cardog.app/tools/recalls/chevrolet/silverado/2022

> Listed for the model year, not checked against your VIN. Chevrolet confirms which apply.
> Check your VIN with Chevrolet Canada or call a Chevrolet dealer with your VIN.
> www.chevrolet.ca/en/ownercenter/recalls

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $43,950[5], $4,462 over the median of $39,488[4].




| | |
|---|---|
| Lowest ask | $17,500 |
| Middle half | $34,894 – $44,789 |
| Median ask | $39,488 |
| This car | $43,950 |

Same model year · 199 live listings · as of 27 Nov 2026

### OTHER 2022 CHEVROLET SILVERADO LISTINGS [5]

| | |
|---|---|
| Cayuga, ON · 51,840 km | $37,995 |
| Sainte-Marie, QC · 69,000 km | $34,995 |
| Thunder Bay, ON · 66,858 km | $41,000 |

| | |
|---|---|
| Langford, BC · 145,317 km | $36,440 |
| Gananoque, ON · 56,673 km | $3,999,995 |
| Unity, SK · 96,467 km | $37,774 |

## §4 EVENTS

| | |
|---|---|
| 2022 | Model year 2022[1]<br>Assembly plant Oshawa, Ontario, Canada |
| 31 Mar 2022 | Transport Canada recall 2022160[2]<br>Issued for the model year · Accessories |
| 30 Jun 2022 | Transport Canada recall 2022348[2]<br>Issued for the model year · Lights and instruments |
| 8 Dec 2022 | Transport Canada recall 2022700[2]<br>Issued for the model year · Lights and instruments |
| 24 Aug 2023 | Transport Canada recall 2023472[2]<br>Issued for the model year · Lights and instruments |
| 1 Feb 2024 | Transport Canada recall 2024061[2]<br>Issued for the model year · Structure |
| 1 Feb 2024 | Transport Canada recall 2024060[2]<br>Issued for the model year · Lights and instruments |
| 24 Oct 2024 | Transport Canada recall 2024637[2]<br>Issued for the model year · Powertrain |
| 24 Apr 2025 | Transport Canada recall 2025225[2]<br>Issued for the model year · Engine |
| 12 Feb 2026 | Transport Canada recall 2026060[2]<br>Issued for the model year · Powertrain |
| 14 Nov 2026 | Listed for sale, Kincardine, ON[5]<br>Lakeside Chevrolet Buick GMC · asking $43,950 |
| 26 Nov 2026 | Listing last updated[5]<br>asking $43,950 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We have not collected this label yet. |

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 199 live listings, as of 27 Nov 2026
[5] Live public dealer listings on Cardog, as of 27 Nov 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.