Register entry, as of 29 October 2026 Listed for sale Record ID c720006bcb92

2016 Honda Civic LX

2.0 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2HG	FC2E5	7	G	H	026362
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Honda Of Canada Mfg., A…	Civic · 2.0 L	Verified	2016	Alliston	Build sequence

§1 IDENTITY [1]

Model year	2016	Engine	2.0 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	Civic	Drive	4x2
Trim	LX	Maker	HONDA OF CANADA MFG., A DIVISION OF HONDA CANADA INC.
Body	Sedan	Plant	Alliston, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/civic/2016

3 recalls listed by Transport Canada for this model year

Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Lights and instruments

2016355 8 Jul 2016

Certain two-door vehicles may not comply with the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 108 - Lighting System and Retroreflective Devices. Some taillight assemblies may have a damaged rear LED side marker light, making it inoperable and are therefore not compliant with the requirements of the standard. This could reduce vehicle conspicuity, which could increase the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect, and, if necessary, replace the tail light assembly.

Engine

2016047 1 Feb 2016

On certain vehicles equipped with 2.0L engines, a piston pin circlip may not have been installed or may have been improperly installed into the piston during assembly. If the circlip is not properly installed, over the course of engine operation, the piston pin will rub against the cylinder wall causing noise and damage, or in the worst case, the piston pin may detach from one side of the piston and cause an engine failure. Engine damage will eventually result in the engine stalling. Engine stalling would result in a loss of motive power; an engine failure would result in a sudden loss of motive power and may result in an under hood fire. These potential outcomes in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will inspect, and repair as necessary.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $13,900[5], $2,112 over the median of $11,788[4].

Lowest ask	$6,796
Middle half	$9,373 – $13,799
Median ask	$11,788
This car	$13,900

Same configuration · 14 live listings · as of 28 Oct 2026

OTHER 2016 HONDA CIVIC LISTINGS [5]

Mississauga, ON · 115,681 km	$14,988
Toronto, ON · 155,798 km	$13,995
Coquitlam, BC · 200,892 km	$10,580
Oakville, ON · 0 km	$15,899
Toronto, ON · 88,000 km	$14,900
London, ON · 244,589 km	$10,495

§4 EVENTS

2016	Model year 2016[1] Assembly plant Alliston, Ontario, Canada
1 Feb 2016	Transport Canada recall 2016047[2] Issued for the model year · Engine
8 Jul 2016	Transport Canada recall 2016355[2] Issued for the model year · Lights and instruments
21 May 2026	Transport Canada recall 2026251[2] Issued for the model year · Seats and restraints
26 Oct 2026	Listed for sale, Truro, NS[5] Scammell Auto · asking $13,900

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 14 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.