Register entry, as of 28 October 2026 Listed for sale Record ID bff3c3a3aec1

# 2019 Honda Civic LX

2.0 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 2HG | FC2F5 | 2 | K | H | 043173 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Honda Of Canada Mfg., A… | Civic · 2.0 L | Verified | 2019 | Alliston | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2019 | Engine | 2.0 L, 4 cylinders |
| Make | Honda | Fuel | Gasoline |
| Model | Civic | Drive | 4x2 |
| Trim | LX | Maker | HONDA OF CANADA MFG., A DIVISION OF HONDA CANADA INC. |
| Body | Sedan | Plant | Alliston, Ontario, Canada |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/civic/2019

**6** recalls listed by Transport Canada for this model year

### Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

### Wheels

2025599 30 Oct 2025

Issue: This recall is for certain aluminum wheels that were installed before delivery or sold as a dealer accessory. On certain vehicles, the wheels may not have been manufactured properly. As a result, the wheel nut(s) could loosen and cause the wheel(s) to detach. Safety Risk: A wheel separation could cause a loss of control and increase the risk of a crash. Additionally, a wheel that separates could create a road hazard for others. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the hub(s), wheel(s) and wheel nut(s).

### Fuel system

2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

### Fuel system

2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

### Fuel system

2021182 26 Mar 2021

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada Recall No. 2020-236. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump motor.

### Fuel system

2020236 28 May 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: For the RLX model, only the RLX Hybrid model is affected by this recall. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump motor.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $17,775[5], $223 under the median of $17,998[4].

| | |
|---|---|
| Lowest ask | $10,980 |
| Middle half | $16,495 – $19,995 |
| Median ask | $17,998 |
| This car | $17,775 |

Same configuration · 53 live listings · as of 28 Oct 2026

#### OTHER 2019 HONDA CIVIC LISTINGS [5]

| | |
|---|---|
| Baie Verte, NB · 95,213 km | $19,995 |
| London, ON · 116,298 km | $17,995 |
| Pointe-Aux-Trembles, QC · 99,370 km | $17,795 |
| Saint-Constant, QC · 139,500 km | $14,495 |
| Québec, QC · 82,035 km | $18,383 |
| Newmarket, ON · 99,941 km | $18,888 |

## §4 EVENTS

2019 Model year 2019[1]
Assembly plant Alliston, Ontario, Canada

| | |
|---|---|
| 28 May 2020 | Transport Canada recall 2020236[2]<br>Issued for the model year · Fuel system |
| 26 Mar 2021 | Transport Canada recall 2021182[2]<br>Issued for the model year · Fuel system |
| 18 Dec 2023 | Transport Canada recall 2023679[2]<br>Issued for the model year · Fuel system |
| 6 May 2024 | Transport Canada recall 2024262[2]<br>Issued for the model year · Fuel system |
| 30 Oct 2025 | Transport Canada recall 2025599[2]<br>Issued for the model year · Wheels |
| 21 May 2026 | Transport Canada recall 2026251[2]<br>Issued for the model year · Seats and restraints |
| 27 Oct 2026 | Listed for sale, Sherbrooke, QC[5]<br>Sherbrooke Honda · asking $17,775 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $17,775 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 53 live listings, as of 28 Oct 2026

[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.