Register entry, as of 29 October 2026 Listed for sale Record ID 2f74bc5be233

2023 Honda Civic LX

2.0 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2HG	FE2F2	2	P	H	112354
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Honda Of Canada Mfg., A…	Civic · 2.0 L	Verified	2023	Alliston	Build sequence

§1 IDENTITY [1]

Model year	2023	Engine	2.0 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	Civic	Drive	4x2
Trim	LX	Maker	HONDA OF CANADA MFG., A DIVISION OF HONDA CANADA INC.
Body	Sedan	Plant	Alliston, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/civic/2023

6 recalls listed by Transport Canada for this model year

Wheels

2025599 30 Oct 2025

Issue: This recall is for certain aluminum wheels that were installed before delivery or sold as a dealer accessory. On certain vehicles, the wheels may not have been manufactured properly. As a result, the wheel nut(s) could loosen and cause the wheel(s) to detach. Safety Risk: A wheel separation could cause a loss of control and increase the risk of a crash. Additionally, a wheel that separates could create a road hazard for others. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the hub(s), wheel(s) and wheel nut(s).

Seats and restraints

2024696 14 Nov 2024

Issue: On a small number of vehicles, the bolts that attach the driver's seat cushion frame may not have been properly tightened. As a result, the bolts could loosen, and the seat could move or detach in a crash. Safety Risk: A seat that moves or detaches could increase the risk of injury in a crash. Corrective Action: Honda will notify owners by mail and advise you to take your vehicle to a dealership to replace the driver's seat cushion frame.

Steering

2024588 3 Oct 2024

Issue: On certain vehicles, the steering gearbox may not have been manufactured properly. As a result, there could be a sudden change in steering feel and an increase in steering effort. Safety Risk: A sudden change in steering effort could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to add grease to the steering gearbox and replace the electronic power steering spring.

Steering

2023562 19 Oct 2023

Issue: On certain vehicles, the incorrect steering gear box assembly may have been installed during a repair. As a result, the tires could become damaged by contact with the chassis and fail. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the steering gear box assembly. The dealer will also inspect the tires for damage and replace them, as necessary.

Brakes

2023349 15 Jun 2023

Issue: Under certain conditions when the vehicle is in "auto-brake hold" mode, a problem with the vehicle stability assist (VSA) modulator may cause the vehicle to move unexpectedly. Safety Risk: A vehicle that moves unexpectedly could create the risk of an injury or a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to replace the VSA modulator.

Seats and restraints

2023191 30 Mar 2023

Issue: On certain Civic Type-R models, the driver's seat frame may not have been properly welded. As a result, the seat frame could break in a crash. Safety Risk: A seat frame that breaks in a crash could create an increased risk of injury. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealership to replace the driver's seat cushion frame.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $21,990[5], $2,000 under the median of $23,990[4].



Lowest ask	$19,678
Middle half	$22,900 – $25,644
Median ask	$23,990
This car	$21,990

Same configuration · 48 live listings · as of 29 Oct 2026

OTHER 2023 HONDA CIVIC LISTINGS [5]

Thornhill, ON · 19,752 km	$25,688
Québec, QC · 39,194 km	$24,983
Lower Sackville, NS · 42,117 km	$24,995
Newmarket, ON · 91,499 km	$25,496
Gatineau, QC · 150,932 km	$19,995
Mississauga, ON · 44,500 km	$27,991

§4 EVENTS

2023	Model year 2023[1] Assembly plant Alliston, Ontario, Canada
30 Mar 2023	Transport Canada recall 2023191[2] Issued for the model year · Seats and restraints

15 Jun 2023	Transport Canada recall 2023349[2] Issued for the model year · Brakes
19 Oct 2023	Transport Canada recall 2023562[2] Issued for the model year · Steering
3 Oct 2024	Transport Canada recall 2024588[2] Issued for the model year · Steering
14 Nov 2024	Transport Canada recall 2024696[2] Issued for the model year · Seats and restraints
30 Oct 2025	Transport Canada recall 2025599[2] Issued for the model year · Wheels
28 Oct 2026	Listed for sale, Kitchener, ON[5] KITCHENER HONDA · asking $21,990
29 Oct 2026	Listing last updated[5] asking $21,990

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 48 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.