Register entry, as of 29 October 2026 Listed for sale Record ID 543132e30843

# 2022 Honda Civic LX

2.0 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 2HG | FE2F2 | 6 | N | H | 102715 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Honda Of Canada Mfg., A… | Civic · 2.0 L | Verified | 2022 | Alliston | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2022 | Engine | 2.0 L, 4 cylinders |
| Make | Honda | Fuel | Gasoline |
| Model | Civic | Drive | 4x2 |
| Trim | LX | Maker | HONDA OF CANADA MFG., A DIVISION OF HONDA CANADA INC. |
| Body | Sedan | Plant | Alliston, Ontario, Canada |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/civic/2022

**5** recalls listed by Transport Canada for this model year

### Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

### Wheels

2025599 30 Oct 2025

Issue: This recall is for certain aluminum wheels that were installed before delivery or sold as a dealer accessory. On certain vehicles, the wheels may not have been manufactured properly. As a result, the wheel nut(s) could loosen and cause the wheel(s) to detach. Safety Risk: A wheel separation could cause a loss of control and increase the risk of a crash. Additionally, a wheel that separates could create a road hazard for others. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the hub(s), wheel(s) and wheel nut(s).

### Steering

2024588 3 Oct 2024

Issue: On certain vehicles, the steering gearbox may not have been manufactured properly. As a result, there could be a sudden change in steering feel and an increase in steering effort. Safety Risk: A sudden change in steering effort could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to add grease to the steering gearbox and replace the electronic power steering spring.

### Airbag

2024059 1 Feb 2024

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership for an inspection if the SRS warning light is on. If the SRS warning light is on due to a faulty weight sensor, the weight sensor will be replaced. When repair parts are available, Honda will send you a second letter. They will advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

### Steering

2023562 19 Oct 2023

Issue: On certain vehicles, the incorrect steering gear box assembly may have been installed during a repair. As a result, the tires could become damaged by contact with the chassis and fail. Safety Risk: A tire failure could cause a loss of control and increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the steering gear box assembly. The dealer will also inspect the tires for damage and replace them, as necessary.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $26,134[5], $4,007 over the median of $22,127[4].

| | |
|---|---|
| Lowest ask | $14,460 |
| Middle half | $20,895 – $23,495 |
| Median ask | $22,127 |
| This car | $26,134 |

Same configuration · 125 live listings · as of 29 Oct 2026

#### OTHER 2022 HONDA CIVIC LISTINGS [5]

| | |
|---|---|
| Thornhill, ON · 36,738 km | $25,988 |
| Québec, QC · 79,655 km | $21,383 |
| Saint John, NB · 114,292 km | $22,179 |
| Ottawa, ON · 55,604 km | $26,888 |
| Thornhill, ON · 52,878 km | $24,954 |
| North Vancouver, BC · 128,243 km | $25,995 |

## §4 EVENTS

| | |
|---|---|
| 2022 | Model year 2022[1]<br>Assembly plant Alliston, Ontario, Canada |
| 19 Oct 2023 | Transport Canada recall 2023562[2]<br>Issued for the model year · Steering |
| 1 Feb 2024 | Transport Canada recall 2024059[2]<br>Issued for the model year · Airbag |

| | |
|---|---|
| 3 Oct 2024 | Transport Canada recall 2024588[2]<br>Issued for the model year · Steering |
| 30 Oct 2025 | Transport Canada recall 2025599[2]<br>Issued for the model year · Wheels |
| 21 May 2026 | Transport Canada recall 2026251[2]<br>Issued for the model year · Seats and restraints |
| 5 Sep 2026 | Listed for sale, Brandon, MB[5]<br>Forman Honda · asking $26,134 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $26,134 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 125 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.