Register entry, as of 29 October 2026 Listed for sale Record ID 08659e8f160b

2012 Honda Civic SI

2.4 L, 4 cylinders · Coupe · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2HG	FG4A5	7	C	H	101643
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Honda Of Canada Mfg., A…	Civic · 2.4 L	Verified	2012	Alliston	Build sequence

§1 IDENTITY [1]

Model year	2012	Engine	2.4 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	Civic	Drive	Not in the decode
Trim	SI	Maker	HONDA OF CANADA MFG., A DIVISION OF HONDA CANADA INC.
Body	Coupe	Plant	Alliston, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/civic/2012

4 recalls listed by Transport Canada for this model year

Powertrain

2020610 10 Dec 2020

Issue: On certain vehicles, the paint on the front axle shafts could delaminate or become damaged by road debris. As a result the axle shaft could corrode. If this happens, the axle shafts could break and cause a loss of power to the wheels. Also, if this happens and the vehicle is parked without the parking brake applied, the vehicle could roll away. Safety Risk: A loss of power to the wheels or a vehicle rollaway could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealer to inspect, and if necessary, replace both axle shafts.

Powertrain

2012174 1 Jun 2012

On certain vehicles equipped with automatic transmissions, the driver's side driveshaft could separate from the CV joint due to an improperly seated snap ring. This could result in a loss of vehicle propulsion, or allow the vehicle to roll away despite being set in the PARK position. Loss of vehicle propulsion, in conjunction with traffic and road conditions, and the driver's reactions, could increase the risk of a crash causing property damage and/or personal injury. Also, the vehicle rolling away could result in property damage and/or personal injury. Correction: Dealers will inspect the driveshaft and replace if necessary.

Airbag

2012031 31 Jan 2012

On certain vehicles, the side curtain airbag inflators may have been incorrectly manufactured and, as a result, one or both airbags may not deploy as intended. Failure of a side curtain airbag to deploy during a crash (where deployment is warranted), could increase the risk of personal injury to the seat occupant. Correction: Dealers will inspect and, if necessary, replace one or both side curtain airbag assemblies.

Fuel system

2011200 17 May 2011

On certain vehicles, the fuel supply line may have been manufactured incorrectly, which could allow a fuel leak to develop. Fuel leakage, in the presence of an ignition source, could result in a fire causing property damage and/or personal injury. Correction: Dealers will replace the fuel supply line.

Listed for the model year, not checked against your VIN. Honda confirms which apply.
Check your VIN with Honda Canada or call a Honda dealer with your VIN.
www.honda.ca/en/recalls

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $9,950[5], $1,451 over the median of $8,499[4].

Lowest ask	$2,995
Middle half	$6,495 – $9,999
Median ask	$8,499
This car	$9,950

Same model year · 37 live listings · as of 29 Oct 2026

OTHER 2012 HONDA CIVIC LISTINGS [5]

Montréal, QC · 252,220 km	$4,999
Vancouver, BC · 0 km	$9,999
Winnipeg, MB · 207,747 km	$8,499
Matane, QC · 117,260 km	$8,950
Hamilton, ON · 297,026 km	$2,999
Laval, QC · 169,000 km	$4,999

§4 EVENTS

2012	Model year 2012[1] Assembly plant Alliston, Ontario, Canada
17 May 2011	Transport Canada recall 2011200[2] Issued for the model year · Fuel system
31 Jan 2012	Transport Canada recall 2012031[2] Issued for the model year · Airbag
1 Jun 2012	Transport Canada recall 2012174[2] Issued for the model year · Powertrain
10 Dec 2020	Transport Canada recall 2020610[2] Issued for the model year · Powertrain
16 Dec 2025	Listed for sale, Mississauga, ON[5] VAULT MOTORS · asking $9,950

28 Oct 2026	Listing last updated[5] asking $9,950

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 37 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.