Register entry, as of 24 November 2026 Listed for sale Record ID 166f402b553e

2007 Honda Ridgeline RTS

3.5 L, 6 cylinders · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2HJ	YK164	7	7	H	001323
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Honda Of Canada Mfg., A…	Ridgeline · 3.5 L	Verified	2007	Alliston	Build sequence

§1 IDENTITY [1]

Model year	2007	Engine	3.5 L, 6 cylinders
Make	Honda	Fuel	Gasoline
Model	Ridgeline	Drive	Not in the decode
Trim	RTS	Maker	HONDA OF CANADA MFG., A DIVISION OF HONDA CANADA INC.
Body	Pickup	Plant	Alliston, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/ridgeline/2007

4 recalls listed by Transport Canada for this model year

Structure

2022320 16 Jun 2022

Issue: On certain vehicles, the rear frame could rust where the fuel tank and rear subframe are mounted. If this happens, the fuel tank and/or rear subframe mounts could separate from the frame. This can allow the fuel tank to fall and become damaged, which could cause a fuel leak. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the rear frame for corrosion. Depending on the outcome of the inspection, the dealer will either apply corrosion protection and install a support brace, or repair the frame. Honda will offer to repurchase vehicles that do not pass the inspection.

Airbag

2017009 10 Jan 2017

On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, could eventually degrade the propellant contained in the passenger frontal airbag inflator. This could cause the airbag to deploy with more force than normal. As a result, if the vehicle were involved in a collision that warrants airbag deployment, fragments could be propelled toward vehicle occupants, and the airbag assembly could be damaged, preventing proper function. These issues could increase the risk of injury. Correction: Dealers will replace the passenger frontal airbag inflator. Note: Canadian climate results in the propellant degrading slowly. The recall is being conducted as a precaution to address future risk, and is expected to replace airbag inflators before their function would be affected.

Airbag

2016046 1 Feb 2016

On certain vehicles, the driver frontal airbag inflator could produce excessive internal pressure during airbag deployment. Increased pressure may cause the inflator to rupture, which could allow fragments to be propelled toward vehicle occupants, increasing the risk of injury. This could also damage the airbag module, which could prevent proper deployment. Failure of the airbag to fully deploy during a crash (where deployment is warranted) could increase the risk of personal injury to the seat occupant. Correction: Dealers will inspect/replace the driver's frontal airbag inflator. Note: Honda Canada has created a special Airbag Inflator Hotline for immediate assistance. For more information, please contact: For Honda Owners: 1-877-445-7754 For Acura Owners: 1-877-445-9844

Other

2010018 26 Jan 2010

On certain vehicles, a wiring harness connector for the heating, ventilation and air conditioning blower motor located under the passenger's side of the instrument panel may be subject to kicking by the front seat passenger's feet. If this occurs, the connector terminal may overheat, and this may cause the wire insulation to melt or the wiring connector to melt. A fire may occur if the wiring insulation melts and the exposed wires make contact with each other and create a short circuit. Correction: Dealers will replace damaged connectors and install a protective cover.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 10 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $8,999[5], $1,187 under the median of $10,186[4].



Lowest ask	$8,999
Middle half	$9,592 – $10,780
Median ask	$10,186
This car	$8,999

Same model year · 2 live listings · as of 24 Nov 2026

OTHER 2007 HONDA RIDGELINE LISTINGS [5]

London, ON · 211,783 km	$11,373

§4 EVENTS

2007	Model year 2007[1] Assembly plant Alliston, Ontario, Canada
26 Jan 2010	Transport Canada recall 2010018[2] Issued for the model year · Other
1 Feb 2016	Transport Canada recall 2016046[2] Issued for the model year · Airbag
10 Jan 2017	Transport Canada recall 2017009[2] Issued for the model year · Airbag
16 Jun 2022	Transport Canada recall 2022320[2] Issued for the model year · Structure

25 Oct 2025	Listed for sale, London, ON[5] EcoMotors Auto sales · asking $8,999
24 Nov 2026	Listing last updated[5] asking $8,999

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 2 live listings, as of 24 Nov 2026

[5] Live public dealer listings on Cardog, as of 24 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.