Register entry, as of 28 October 2026 Listed for sale Record ID 6bde32f13e52

# 2023 Honda CR-V LX

1.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 2HK | RS4H2 | 5 | P | H | 106035 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Honda Of Canada Mfg., A… | CR-V · 1.5 L | Verified | 2023 | Alliston | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2023 | Engine | 1.5 L, 4 cylinders |
| Make | Honda | Fuel | Gasoline |
| Model | CR-V | Drive | 4WD |
| Trim | LX | Maker | HONDA OF CANADA MFG., A DIVISION OF HONDA CANADA INC. |
| Body | Sport Utility Vehicle | Plant | Alliston, Ontario, Canada |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/cr-v/2023

**4** recalls listed by Transport Canada for this model year

### Other

2026274 4 Jun 2026

Issue: On certain vehicles, if the tire repair kit nozzle is not properly attached to the tire valve, pressure could build up in the sealant bottle. As a result, excessive pressure could cause the bottle cap to detach. Safety Risk: If the bottle cap detaches, it could increase the risk of injury. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to replace the nozzle on the tire repair kit. If the sealant bottle has been previously used, it will be replaced.

### Fuel system

2024606 15 Oct 2024

Issue: On certain vehicles, the high-pressure fuel pump may not have been manufactured properly. As a result, the fuel pump could crack and leak fuel. Safety Risk: A fuel leak can create the risk of a fire. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the high-pressure fuel pump.

### Steering

2024588 3 Oct 2024

Issue: On certain vehicles, the steering gearbox may not have been manufactured properly. As a result, there could be a sudden change in steering feel and an increase in steering effort. Safety Risk: A sudden change in steering effort could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to add grease to the steering gearbox and replace the electronic power steering spring.

### High voltage

2024585 3 Oct 2024

Issue: On certain vehicles, some negative terminals in the high-voltage battery may not have been manufactured properly. As a result, a terminal and/or bus bar could break and cause electrical arcing (sparks). Note: This recall only affects hybrid (FHEV) models. Safety Risk: Electrical arcing can create the risk of a fire or injury. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to replace the high-voltage battery module.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $28,976[5], $22 under the median of $28,998[4].




| | |
|---|---|
| Lowest ask | $22,957 |
| Middle half | $28,513 – $30,722 |
| Median ask | $28,998 |
| This car | $28,976 |

Same configuration · 38 live listings · as of 28 Oct 2026

#### OTHER 2023 HONDA CR-V LISTINGS [5]

| | |
|---|---|
| Vancouver, BC · 91,217 km | $33,995 |
| Dorval, QC · 29,533 km | $34,490 |
| Victoriaville, QC · 33,092 km | $34,495 |
| Surrey, BC · 88,032 km | $32,995 |
| Vancouver, BC · 88,032 km | $32,995 |
| Halifax, NS · 73,405 km | $29,995 |

## §4 EVENTS

| | |
|---|---|
| 2023 | Model year 2023[1]<br>Assembly plant Alliston, Ontario, Canada |
| 3 Oct 2024 | Transport Canada recall 2024588[2]<br>Issued for the model year · Steering |
| 3 Oct 2024 | Transport Canada recall 2024585[2]<br>Issued for the model year · High voltage |
| 15 Oct 2024 | Transport Canada recall 2024606[2]<br>Issued for the model year · Fuel system |
| 4 Jun 2026 | Transport Canada recall 2026274[2]<br>Issued for the model year · Other |

26 Oct 2026 **Listed for sale, Chicoutimi, QC**[5]
LEO AUTOMOBILE LTEE · asking $28,976

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 38 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.