

Register entry, as of 27 October 2026

Listed for sale

Record ID 3674ee87e6a8

2017 Honda CR-V EX

1.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2HK **RW2H5** **4** **H** **H** **112767**

WMI 1-3

Honda Of Canada Mfg., A...

DESCRIPTOR 4-8

CR-V · 1.5 L

CHECK 9

Verified

YEAR 10

2017

PLANT 11

Alliston

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	1.5 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	CR-V	Drive	4WD
Trim	EX	Maker	HONDA OF CANADA MFG., A DIVISION OF HONDA CANADA INC.
Body	Sport Utility Vehicle	Plant	Alliston, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/cr-v/2017

4 recalls listed by Transport Canada for this model year

Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Seats and restraints

2023127 9 Mar 2023

Issue: On certain vehicles, the seat belt buckles for the driver and front-passenger seats could wear over time and may not latch securely. If this happens, the seat belt could unlatch unexpectedly. Safety Risk: A seat belt that doesn't latch securely could create an increased risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the driver and front-passenger seat belt assemblies. In most cases, the seat belt buckle release buttons will be replaced. If the dealer determines that a buckle can't be repaired, it will be replaced with a new part.

Steering

2018536 27 Sep 2018

On certain vehicles, the electric power steering system could get caught in an infinite loop of steering assist going from lock to lock due to a manufacturing defect in the torque sensor. This could cause unintended steering input, reducing vehicle manoeuvrability, which could result in a crash causing injury and/or damage to property. Correction: Dealers will replace the steering gearbox assembly.



Fuel system

2017347 14 Jul 2017


On certain vehicles, the fuel feed pipe may not have been properly manufactured. Upon the fuel lines being pressurized, the connection between the feed pipe and fuel hose could separate, resulting in a fuel leak which could cause an engine stall. Additionally, a fuel leak in the presence of an ignition source could increase the risk of fire causing injury and/or damage to property. Correction: Dealers will replace the fuel feed pipe and associated single use retainers.

Listed for the model year, not checked against your VIN. Honda confirms which apply.
Check your VIN with Honda Canada or call a Honda dealer with your VIN.
www.honda.ca/en/recalls

United States: 7 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$16,995^[5], \$1,893 under the median of \$18,888^[4].



Lowest ask	\$12,995
Middle half	\$16,695 – \$19,930
Median ask	\$18,888
This car	\$16,995

Same configuration · 34 live listings · as of 27 Oct 2026

OTHER 2017 HONDA CR-V LISTINGS ^[5]

St. Catharines, ON · 163,500 km	\$17,595
Regina, SK · 159,000 km	\$21,995
Newmarket, ON · 157,635 km	\$18,995
Moncton, NB · 130,807 km	\$19,694
Victoria, BC · 203,104 km	\$16,595
Airdrie, AB · 120,226 km	\$21,695

§4 EVENTS

2017	Model year 2017 ^[1] Assembly plant Alliston, Ontario, Canada
14 Jul 2017	Transport Canada recall 2017347 ^[2] Issued for the model year · Fuel system
27 Sep 2018	Transport Canada recall 2018536 ^[2] Issued for the model year · Steering
9 Mar 2023	Transport Canada recall 2023127 ^[2] Issued for the model year · Seats and restraints
21 May 2026	Transport Canada recall 2026251 ^[2] Issued for the model year · Seats and restraints



26 Oct 2026 Listed for sale, Victoriaville, QC^[5]
Groupe ROY Auto · asking \$16,995

27 Oct 2026 Listing last updated^[5]
asking \$16,995

§5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 34 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

