Register entry, as of 29 November 2026 Listed for sale Record ID a6b85f1e39be

2019 Honda CR-V EX

1.5 L, 4 cylinders · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2HK	RW2H5	5	K	H	123364
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Honda Of Canada Mfg., A…	CR-V · 1.5 L	Verified	2019	Alliston	Build sequence

§1 IDENTITY [1]

Model year	2019	Engine	1.5 L, 4 cylinders
Make	Honda	Fuel	Gasoline
Model	CR-V	Drive	Not in the decode
Trim	EX	Maker	HONDA OF CANADA MFG., A DIVISION OF HONDA CANADA INC.
Body	Sport Utility Vehicle	Plant	Alliston, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/cr-v/2019

8 recalls listed by Transport Canada for this model year

Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

Fuel system

2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Fuel system

2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

Seats and restraints

2023127 9 Mar 2023

Issue: On certain vehicles, the seat belt buckles for the driver and front-passenger seats could wear over time and may not latch securely. If this happens, the seat belt could unlatch unexpectedly. Safety Risk: A seat belt that doesn't latch securely could create an increased risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the driver and front-passenger seat belt assemblies. In most cases, the seat belt buckle release buttons will be replaced. If the dealer determines that a buckle can't be repaired, it will be replaced with a new part.

Fuel system

2021182 26 Mar 2021

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada Recall No. 2020-236. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump motor.

Other

2019471 26 Sep 2019

Issue: On certain vehicles, the owner's manual incorrectly describes when the “passenger airbag off” light should turn on. The manual states that if the front passenger seat is empty the indicator light will not turn on. It should instead state that if the seat is empty, the indicator light will turn on. This could cause a user to misunderstand how the passenger airbag system should work. Safety Risk: A user that does not understand how the airbag system operates may be at an increased risk of injury in a crash. Corrective Actions: Honda will mail a sticker to all current owners that has the correct description for the “passenger airbag off” indicator light. They will also provide the owner with instructions on where to place it in the owner's manual. Owners who would like help installing the label can contact a Honda dealer.

2 more on the model-year record, cardog.app/tools/recalls/honda/cr-v/2019

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $28,990[5], $6,995 over the median of $21,995[4].



Lowest ask	$15,900
Middle half	$19,490 – $23,521
Median ask	$21,995
This car	$28,990

Same configuration · 57 live listings · as of 29 Nov 2026

OTHER 2019 HONDA CR-V LISTINGS [5]

Brantford, ON · 109,195 km	$24,496
Simcoe, ON · 96,215 km	$27,499
Barrie, ON · 171,070 km	$18,990
Carignan, QC · 93,457 km	$20,998
Vancouver, BC · 173,770 km	$16,999
Cranbrook, BC · 112,384 km	$24,995

§4 EVENTS

2019	Model year 2019[1] Assembly plant Alliston, Ontario, Canada
21 May 2019	Transport Canada recall 2019240[2] Issued for the model year · Airbag
1 Aug 2019	Transport Canada recall 2019378[2] Issued for the model year · Fuel system
26 Sep 2019	Transport Canada recall 2019471[2] Issued for the model year · Other
26 Mar 2021	Transport Canada recall 2021182[2] Issued for the model year · Fuel system
9 Mar 2023	Transport Canada recall 2023127[2] Issued for the model year · Seats and restraints
18 Dec 2023	Transport Canada recall 2023679[2] Issued for the model year · Fuel system
6 May 2024	Transport Canada recall 2024262[2] Issued for the model year · Fuel system
21 May 2026	Transport Canada recall 2026251[2] Issued for the model year · Seats and restraints
22 Oct 2026	Listed for sale, Lloydminster, AB[5] Lloydminster Honda · asking $28,990
29 Nov 2026	Listing last updated[5] asking $28,990

§5 DOCUMENTS

Window sticker	We do not collect window stickers for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 57 live listings, as of 29 Nov 2026
[5] Live public dealer listings on Cardog, as of 29 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.