Register entry, as of 27 October 2026 Listed for sale Record ID c8d083bc89dc

# 2020 Honda CR-V EX-L

1.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 2HK | RW2H8 | X | L | H | 242748 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Honda Of Canada Mfg., A… | CR-V · 1.5 L | Verified | 2020 | Alliston | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2020 | Engine | 1.5 L, 4 cylinders |
| Make | Honda | Fuel | Gasoline |
| Model | CR-V | Drive | 4WD |
| Trim | EX-L | Maker | HONDA OF CANADA MFG., A DIVISION OF HONDA CANADA INC. |
| Body | Sport Utility Vehicle | Plant | Alliston, Ontario, Canada |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/cr-v/2020

5 recalls listed by Transport Canada for this model year

### Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

### Fuel system

2024262 6 May 2024

Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall replaces Transport Canada recall no. 2023-679. Vehicles that were repaired under that recall don't require this repair. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

### Airbag

2024059 1 Feb 2024

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership for an inspection if the SRS warning light is on. If the SRS warning light is on due to a faulty weight sensor, the weight sensor will be replaced. When repair parts are available, Honda will send you a second letter. They will advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

### Fuel system

2023679 18 Dec 2023

This recall was replaced by Transport Canada recall no. 2024-262. Issue: This recall is for low-pressure fuel pumps installed on certain vehicles or sold at dealerships as a replacement part. On certain vehicles, the low-pressure fuel pump could fail. If this happens, the engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This is an expansion of Transport Canada recall nos. 2020-236 and 2021-182. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the fuel pump motor.

### Seats and restraints

2023127 9 Mar 2023

Issue: On certain vehicles, the seat belt buckles for the driver and front-passenger seats could wear over time and may not latch securely. If this happens, the seat belt could unlatch unexpectedly. Safety Risk: A seat belt that doesn't latch securely could create an increased risk of injury in a crash. Corrective Actions: Honda will notify owners by mail and instruct you to take your vehicle to a dealership to inspect the driver and front-passenger seat belt assemblies. In most cases, the seat belt buckle release buttons will be replaced. If the dealer determines that a buckle can't be repaired, it will be replaced with a new part.

> Listed for the model year, not checked against your VIN. Honda confirms which apply.
> Check your VIN with Honda Canada or call a Honda dealer with your VIN.
> www.honda.ca/en/recalls

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $28,542[5], $3,896 over the median of $24,646[4].

| | |
|---|---|
| Lowest ask | $15,741 |
| Middle half | $22,591 – $27,550 |
| Median ask | $24,646 |
| This car | $28,542 |

Same configuration · 28 live listings · as of 27 Oct 2026

#### OTHER 2020 HONDA CR-V LISTINGS [5]

| | |
|---|---|
| Toronto, ON · 71,525 km | $29,995 |
| Saint-Hyacinthe, QC · 113,000 km | $21,995 |
| Whitby, ON · 58,000 km | $25,301 |
| Calgary, AB · 120,799 km | $28,985 |
| Thunder Bay, ON · 81,568 km | $26,000 |
| Milton, ON · 93,829 km | $24,499 |

## §4 EVENTS

| | |
|---|---|
| 2020 | Model year 2020[1]<br>Assembly plant Alliston, Ontario, Canada |
| 9 Mar 2023 | Transport Canada recall 2023127[2]<br>Issued for the model year · Seats and restraints |
| 18 Dec 2023 | Transport Canada recall 2023679[2]<br>Issued for the model year · Fuel system |

| | |
|---|---|
| 1 Feb 2024 | Transport Canada recall 2024059[2]<br>Issued for the model year · Airbag |
| 6 May 2024 | Transport Canada recall 2024262[2]<br>Issued for the model year · Fuel system |
| 21 May 2026 | Transport Canada recall 2026251[2]<br>Issued for the model year · Seats and restraints |
| 25 Oct 2026 | Listed for sale, Huntsvillle, ON[5]<br>Edmonds GM · asking $28,542 |
| 26 Oct 2026 | Listing last updated[5]<br>asking $28,542 |

## §5 DOCUMENTS

Window sticker We do not collect window stickers for this manufacturer.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 28 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.