Register entry, as of 29 October 2026 Listed for sale Record ID d562942c505c

# 2022 Honda CR-V Touring

1.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 2HK | RW2H9 | 9 | N | H | 214175 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Honda Of Canada Mfg., A… | CR-V · 1.5 L | Verified | 2022 | Alliston | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2022 | Engine | 1.5 L, 4 cylinders |
| Make | Honda | Fuel | Gasoline |
| Model | CR-V | Drive | 4WD |
| Trim | Touring | Maker | HONDA OF CANADA MFG., A DIVISION OF HONDA CANADA INC. |
| Body | Sport Utility Vehicle | Plant | Alliston, Ontario, Canada |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/honda/cr-v/2022

**2** recalls listed by Transport Canada for this model year

### Seats and restraints

2026251 21 May 2026

Issue: On certain vehicles, the weight sensor for the front passenger seat may not have been manufactured properly. As a result, the passenger-front airbag and knee airbag could deploy in a crash that doesn't require them to. Note: This recall is an expansion of Transport Canada recall no. 2024-059. If the weight sensor fails, the SRS warning light would turn on in the instrument panel. Safety Risk: An airbag system that doesn't work properly could increase the risk of injury in a crash. Corrective Actions: The company will notify owners by mail and advise you to take your vehicle to a dealership to replace the passenger-front seat weight sensor.

### Steering

2024119 23 Feb 2024

Issue: On certain vehicles, a sensor in the electronic power steering could fail. If this happens, there could be a sudden increase in steering effort. Safety Risk: A sudden increase in steering effort could increase the risk of a crash. Corrective Actions: Honda will notify owners by mail and advise you to take your vehicle to a dealership to replace the electronic power steering gearbox.

Listed for the model year, not checked against your VIN. Honda confirms which apply.
Check your VIN with Honda Canada or call a Honda dealer with your VIN.
www.honda.ca/en/recalls

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $26,753[5], $3,742 under the median of $30,495[4].

| | |
|---|---|
| Lowest ask | $24,855 |
| Middle half | $28,900 – $31,986 |
| Median ask | $30,495 |
| This car | $26,753 |

Same configuration · 53 live listings · as of 29 Oct 2026

### OTHER 2022 HONDA CR-V LISTINGS [5]

| | |
|---|---|
| Calgary, AB · 143,986 km | $31,995 |
| Québec, QC · 82,994 km | $26,913 |
| Orangeville, ON · 97,443 km | $29,993 |
| St-Félicien, QC · 71,368 km | $28,101 |
| Thornhill, ON · 87,153 km | $27,672 |
| Thornhill, ON · 75,414 km | $29,488 |

## §4 EVENTS

| | |
|---|---|
| 2022 | Model year 2022[1]<br>Assembly plant Alliston, Ontario, Canada |
| 23 Feb 2024 | Transport Canada recall 2024119[2]<br>Issued for the model year · Steering |
| 21 May 2026 | Transport Canada recall 2026251[2]<br>Issued for the model year · Seats and restraints |
| 29 Oct 2026 | Listed for sale, Québec, QC[5]<br>Kia Ste-Foy · asking $26,753 |

## §5 DOCUMENTS

Window sticker — We do not collect window stickers for this manufacturer.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 53 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.