Register entry, as of 28 October 2026 Listed for sale Record ID 0e678c516f27

# 2019 Lincoln Nautilus Reserve

2.0 L, 4 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 2LM | PJ8L9 | 9 | K | B | L15286 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Lincoln · FORD MOTOR CO… | Nautilus · 2.0 L | Verified | 2019 | Oakville | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2019 | Engine | 2.0 L, 4 cylinders |
| Make | Lincoln | Fuel | Gasoline |
| Model | Nautilus | Drive | AWD |
| Trim | Reserve | Maker | FORD MOTOR COMPANY OF CANADA, LTD. |
| Body | Sport Utility Vehicle | Plant | Oakville, Ontario, Canada |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/lincoln/nautilus/2019

**3** recalls listed by Transport Canada for this model year

### Visual system

2025360 27 Jun 2025

Issue: On certain vehicles, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Ford will notify owners by mail and advise you to take your vehicle to a dealership to update the SYNC software.

### Seats and restraints

2020335 20 Jul 2020

Issue: On certain vehicles, the wiring for the front seats could be damaged when a person uses the tilt function. As a result, certain system in the vehicle may not work properly. Depending on which wires are damaged, the occupant classification system may not work properly. This can cause the passenger airbag to not work properly in a crash. The damage could also cause the driver or passenger front airbag to deploy suddenly without a crash. Note: This recall only affects vehicles equipped with 16-way power front seats. Safety Risk: An airbag that does not deploy properly in a crash could increase the risk of injuries. A sudden airbag deployment when there is no crash could also create a risk of injury. Corrective Actions: Ford will notify owners by mail and instruct you to take your vehicle to a dealer to install protective tape on the exposed edge of the cushion frames. The dealer will also inspect the wire harness and repair or replace it, as needed.

### Steering

2019017 14 Jan 2019

Issue: Certain vehicles may not detect when the driver removes their hands from the steering wheel while using adaptive cruise control with lane centering. If this occurs, the driver may not be alerted by warnings to hold the steering wheel. This system is not designed for hands-free operation. Safety Risk: A driver may not be warned to put their hands back on the steering wheel, which could increase the risk of a crash. Corrective Actions: The company will notify owners by mail. Owners will be instructed to take their vehicle to a Ford or Lincoln dealer for an update of the software for the Power Steering Control Module.

> Listed for the model year, not checked against your VIN. Lincoln confirms which apply.
> Check your VIN with Lincoln Canada or call a Lincoln dealer with your VIN.
> www.lincolncanada.com/support/recalls/

United States: 8 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $21,900[5], $976 over the median of $20,924[4].

| | |
|---|---|
| Lowest ask | $14,995 |
| Middle half | $19,992 – $24,244 |
| Median ask | $20,924 |
| This car | $21,900 |

Same configuration · 11 live listings · as of 28 Oct 2026

### OTHER 2019 LINCOLN NAUTILUS LISTINGS [5]

| | |
|---|---|
| Winnipeg, MB · 133,972 km | $24,885 |
| Winnipeg, MB · 133,972 km | $24,885 |
| Calgary, AB · 117,265 km | $27,541 |
| Grimsby, ON · 176,538 km | $17,995 |
| St. Catharines, ON · 176,538 km | $17,995 |
| Lethbridge, AB · 108,697 km | $28,557 |

## §4 EVENTS

| | |
|---|---|
| 2019 | Model year 2019[1]<br>Assembly plant Oakville, Ontario, Canada |
| 14 Jan 2019 | Transport Canada recall 2019017[2]<br>Issued for the model year · Steering |
| 20 Jul 2020 | Transport Canada recall 2020335[2]<br>Issued for the model year · Seats and restraints |
| 27 Jun 2025 | Transport Canada recall 2025360[2]<br>Issued for the model year · Visual system |
| 4 Sep 2026 | Listed for sale, Toronto, ON[5]<br>COLISEUM AUTO SALES ON WESTON · asking $21,900 |
| 28 Oct 2026 | Listing last updated[5]<br>asking $21,900 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

## SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 11 live listings, as of 28 Oct 2026
[5] Live public dealer listings on Cardog, as of 28 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.