

Register entry, as of 29 October 2026

Listed for sale

Record ID 3f051c7a3c3d

2013 Toyota Corolla

1.8 L, 4 cylinders · 4x2 · Sedan · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2T1 **BU4EE** **X** **D** **C** **067242**

WMI 1-3

Toyota Motor Manufacturi...

DESCRIPTOR 4-8

Corolla · 1.8 L

CHECK 9

Verified

YEAR 10

2013

PLANT 11

Cambridge

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2013	Engine	1.8 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	Corolla	Drive	4x2
Trim	Not in the decode	Maker	TOYOTA MOTOR MANUFACTURING CANADA
Body	Sedan	Plant	Cambridge, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/corolla/2013

3 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Airbag

2020013 17 Jan 2020

Issue: On certain vehicles, the circuits within the airbag control module could be damaged in a crash. This could cause the airbags and seat belt pretensioners to not deploy in certain crashes. Safety Risk: Airbags or seat belts that do not work properly in a crash could create an increased risk of injury. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to install an electrical noise filter to prevent damage to the airbag control module.



Airbag

2019008 9 Jan 2019

Issue: On certain vehicles, long-term exposure to high absolute humidity and temperature, combined with high temperature cycling, may eventually degrade the propellant contained in the passenger-front airbag. This could cause the airbag to deploy with more force than normal. If the airbag inflator ruptures, fragments could be propelled toward vehicle occupants or cause damage to the airbag assembly, preventing its proper function. Safety Risk: If the vehicle is involved in a crash requiring an airbag deployment, the airbag inflator could rupture and create a risk of injury. Corrective Action: Owners will be notified by mail and instructed to take their vehicle to a dealer to have the passenger-front airbag inflator or airbag module replaced. Note: The Canadian climate results in the propellant degrading slowly. This recall is being conducted as a precaution to address future risk. It is expected that all airbag inflators will be replaced before their function would be affected.


Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.

www.toyota.ca/en/owners/recalls/

United States: 5 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$9,995^[5], \$855 under the median of \$10,850^[4].



Lowest ask	\$6,900
Middle half	\$9,499 – \$12,490
Median ask	\$10,850
This car	\$9,995

Same configuration · 29 live listings · as of 29 Oct 2026

OTHER 2013 TOYOTA COROLLA LISTINGS ^[5]

Gatineau, QC · 93,909 km	\$12,698
Markham, ON · 138,339 km	\$12,998
Laval, QC · 149,000 km	\$6,999
Laval, QC · 99,000 km	\$8,999
Waterloo, ON · 89,000 km	\$14,995
Nanaimo, BC · 111,516 km	\$15,777

§4 EVENTS

2013	Model year 2013 ^[1] Assembly plant Cambridge, Ontario, Canada
9 Jan 2019	Transport Canada recall 2019008 ^[2] Issued for the model year · Airbag
17 Jan 2020	Transport Canada recall 2020013 ^[2] Issued for the model year · Airbag
24 Nov 2021	Transport Canada recall 2021723 ^[2] Issued for the model year · Electrical



26 Oct 2026 Listed for sale, Granby, QC^[5]
Estrie Toyota · asking \$9,995

28 Oct 2026 Listing last updated^[5]
asking \$9,995

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same configuration, 29 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

