Register entry, as of 27 October 2026 Listed for sale Record ID e471a556e3f1

2022 Lexus NX 350h Base

2.5 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2T2	AKCEZ	9	N	C	001034
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Lexus · TOYOTA MOTOR M…	NX · 2.5 L	Verified	2022	Cambridge	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	2.5 L, 4 cylinders
Make	Lexus	Fuel	Gasoline
Model	NX	Drive	4WD
Trim	350h Base	Maker	TOYOTA MOTOR MANUFACTURING CANADA
Body	Sport Utility Vehicle	Plant	Cambridge, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lexus/nx/2022

5 recalls listed by Transport Canada for this model year

Visual system

2026125 18 Mar 2026

Issue: Under certain conditions, a software problem could cause the rearview camera image not to display when the transmission is shifted into reverse. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: Lexus will notify owners by mail and advise you to take your vehicle to a dealership to update the rearview camera software or replace the rearview camera, as necessary.

Visual system

2025594 30 Oct 2025

Issue: Under certain conditions, a software problem could cause the rearview camera image to freeze or not to display. If this happens, the rearview image may not display when the transmission is shifted into reverse. Canadian regulations require the rearview image to display when the vehicle is reversing. Note: This recall only affects certain vehicles equipped with a panoramic view monitor system. Safety Risk: A rearview camera image that doesn't display correctly could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: The company will notify owners in writing and advise you to take your vehicle to a dealership to update the parking assist ECU software.

Brakes

2022493 1 Sep 2022

Issue: On certain vehicles, a programming error could cause the parking brake system to malfunction. If this happens, a warning light will turn on and the message "Parking Brake Malfunction, Visit Your Dealer" will display. Also, you may not be able to apply the parking brake, and if the vehicle isn't in park, it could roll away. Safety Risk: A parked vehicle that moves unexpectedly could increase the risk of an injury or a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealership to reprogram the skid control ECU.

Structure

2022180 13 Apr 2022

Issue: On certain vehicles, the body panels near the front shock absorber mounts may be missing welds. As a result, the shock absorber mounting areas could crack over time and break. If this happens, a shock absorber could separate and cause a sudden loss of vehicle stability. Safety Risk: A loss of vehicle stability could increase the risk of a crash. Corrective Actions: Lexus will contact owners by mail and instruct you to take your vehicle to a dealership to inspect the spot-welds around the front shock absorber mounting areas. The corrective actions for this recall are under development.

Brakes

2022179 13 Apr 2022

Issue: Under certain conditions, the vehicle stability control (VSC) system may not switch on when the ignition is restarted. This can happen if the driver manually turns off the VSC, depresses the brake pedal, and then turns off and restarts the vehicle while continuously depressing the brake pedal. Canadian regulations require the stability control system to be active each time that you start the vehicle. Safety Risk: A stability control system that is switched off could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to update the skid control ECU software.

> Listed for the model year, not checked against your VIN. Lexus confirms which apply.
> Check your VIN with Lexus Canada or call a Lexus dealer with your VIN.
> www.lexus.ca/en/maintain-your-lexus/campaigns/

United States: 3 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $42,290[5], $756 under the median of $43,046[4].

Lowest ask	$26,995
Middle half	$40,186 – $46,220
Median ask	$43,046
This car	$42,290

Same model year · 64 live listings · as of 27 Oct 2026

OTHER 2022 LEXUS NX LISTINGS [5]

Maple Ridge, BC · 17,458 km	$48,400
Brampton, ON · 47,512 km	$41,888
Brampton, ON · 84,903 km	$41,920
Brampton, ON · 62,459 km	$47,888
Orleans, ON · 117,853 km	$42,777
Calgary, AB · 81,774 km	$44,898

§4 EVENTS

2022	Model year 2022[1] Assembly plant Cambridge, Ontario, Canada
13 Apr 2022	Transport Canada recall 2022180[2] Issued for the model year · Structure
13 Apr 2022	Transport Canada recall 2022179[2] Issued for the model year · Brakes

1 Sep 2022	Transport Canada recall 2022493[2] Issued for the model year · Brakes
30 Oct 2025	Transport Canada recall 2025594[2] Issued for the model year · Visual system
18 Mar 2026	Transport Canada recall 2026125[2] Issued for the model year · Visual system
26 Oct 2026	Listed for sale, Richmond Hill, ON[5] Lexus Of Richmond Hill · asking $42,290

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 64 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.