Register entry, as of 29 November 2026 Listed for sale Record ID a9a28c404e27

2018 Lexus RX 450h/450h F Sport

3.5 L, 6 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2T2	BGMCA	6	J	C	027934
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Lexus · TOYOTA MOTOR M…	RX · 3.5 L	Verified	2018	Cambridge	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.5 L, 6 cylinders
Make	Lexus	Fuel	Gasoline
Model	RX	Drive	4WD
Trim	450h/450h F Sport	Maker	TOYOTA MOTOR MANUFACTURING CANADA
Body	Sport Utility Vehicle	Plant	Cambridge, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/lexus/rx/2018

4 recalls listed by Transport Canada for this model year

Electrical

2021723 24 Nov 2021

Issue: This recall is for certain block heater kits installed on certain vehicles or sold as accessories at Toyota or Lexus dealerships. On certain vehicles, the engine block heater cable may not have enough heat protection and could be damaged by high temperatures. If this happens, the cable could short circuit while plugged in, and cause the wiring to overheat or melt. Note: This recall only affects the following block heater/cord part numbers: C014003034 PK5A408J09 PU14000904 C014003151 PK5A408J13 PU14000905 C014000885 PK5A489J11 PU14000907 C014000888 PK5A489J22 PU14000909 C014000907 PK5A410H00 PU14000911 C014100904 PU14000900 PU14000913 C014100907 PU14000901 PU14003571 C014100911 PU14000902 PK5A489J14 PK5A408J05 PU14000903 Safety Risk: Engine block heater wiring that overheats or melts could create the risk of a fire. Corrective Actions: Toyota recommends that you should stop using the engine block heater immediately. Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to disable the engine block heater. For some vehicles, the corrective actions for this recall are under development. For others, a new engine block heater cannot be installed, and the owner will receive a refund of the purchase price of the engine block heater.

Fuel system

2020514 28 Oct 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recalls SRC R95/SRC R96 and SRC RA2/SRC RA3 (Transport Canada Recall Numbers 2020-005 and 2020-088). Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Fuel system 2020088 4 Mar 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recall SRC R95/SRC R96 (Transport Canada Recall No. 2020-005) Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Fuel system 2020005 13 Jan 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

> Listed for the model year, not checked against your VIN. Lexus confirms which apply.
> Check your VIN with Lexus Canada or call a Lexus dealer with your VIN.
> www.lexus.ca/en/maintain-your-lexus/campaigns/

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $37,990[5], $5,410 over the median of $32,580[4].



Lowest ask	$27,995
Middle half	$29,940 – $34,990
Median ask	$32,580
This car	$37,990

Same model year · 27 live listings · as of 29 Nov 2026

OTHER 2018 LEXUS RX LISTINGS [5]

Edmonton, AB · 74,704 km	$34,986
Vancouver, BC · 115,984 km	$30,798
London, ON · 148,929 km	$31,798
Kitchener, ON · 148,925 km	$29,500
St Stephen, NB · 123,349 km	$29,858
Niagara Falls, ON · 88,478 km	$34,570

§4 EVENTS

2018	Model year 2018[1] Assembly plant Cambridge, Ontario, Canada
13 Jan 2020	Transport Canada recall 2020005[2] Issued for the model year · Fuel system
4 Mar 2020	Transport Canada recall 2020088[2] Issued for the model year · Fuel system

28 Oct 2020	Transport Canada recall 2020514[2]	Issued for the model year · Fuel system
24 Nov 2021	Transport Canada recall 2021723[2]	Issued for the model year · Electrical
25 Nov 2026	Listed for sale, Nanaimo, BC[5]	Mercedes-Benz Nanaimo · asking $37,990
28 Nov 2026	Listing last updated[5]	asking $37,990

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 27 live listings, as of 29 Nov 2026
[5] Live public dealer listings on Cardog, as of 29 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.