Register entry, as of 29 October 2026 Listed for sale Record ID 736810f5553a

2020 Toyota RAV4

2.5 L, 4 cylinders · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

2T3	B1RFV	7	L	W	118706
WMI 1-3	DESCRIPTOR 4-8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12-17
Toyota Motor Manufacturi…	RAV4 · 2.5 L	Verified	2020	Woodstock	Build sequence

§1 IDENTITY [1]

Model year	2020	Engine	2.5 L, 4 cylinders
Make	Toyota	Fuel	Gasoline
Model	RAV4	Drive	Not in the decode
Trim	Not in the decode	Maker	TOYOTA MOTOR MANUFACTURING CANADA
Body	Not in the decode	Plant	Woodstock, Ontario, Canada

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/toyota/rav4/2020

5 recalls listed by Transport Canada for this model year

Airbag

2023684 20 Dec 2023

Issue: On certain vehicles, a sensor for the occupant classification system (OCS) may not have been manufactured properly. As a result, the sensor could short circuit and cause the airbag system to turn off the passenger-front airbag even when a passenger is seated. Note: This problem would cause a warning message to display on the instrument panel and the airbag indicator light would display "passenger airbag off". Safety Risk: An airbag that is turned off could increase the risk of injury to a passenger in a crash. Corrective Actions: Toyota will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the OCS sensor.

Airbag

2020573 25 Nov 2020

Issue: On certain vehicles, the steering column may have been damaged during assembly. As a result, the steering column could move when the driver-front airbag inflates. This could cause reduced protection for the driver in a crash. Safety Risk: Reduced occupant protection could lead to increased injuries in a crash. Corrective Actions: Toyota will notify owners by mail and instruct you to take your vehicle to a dealer to replace the steering column.

Fuel system

2020514 28 Oct 2020

Issue: On certain vehicles, the low-pressure fuel pump could fail. If this happens, then engine may run rough or may not start and the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Note: This recall is an expansion of recalls SRC R95/SRC R96 and SRC RA2/SRC RA3 (Transport Canada Recall Numbers 2020-005 and 2020-088). Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to replace the fuel pump.

Steering

2020288 24 Jun 2020

Issue: On certain vehicles, the cover of the electric power steering (EPS) gearbox may not be properly attached. As a result, water can enter the gearbox and corrode internal components. Under certain conditions, this can result in a loss of power steering assist. Safety Risk: A loss of power steering assist may result in a sudden increase in steering effort, especially at low vehicle speeds. This could increase the risk of a crash. Corrective Action: Toyota will notify owners by mail and instruct you to take your vehicle to a Toyota dealer to replace the electric power steering gear assembly.

Engine

2020039 6 Feb 2020

Issue: On certain vehicles equipped with a 2.5-L 4-cylinder engine, the engine block may be porous. As a result, the engine block could crack and cause internal or external coolant leaks. This could cause engine overheating or internal engine damage and result in an engine failure. For non-hybrid vehicles, this could also result in a sudden loss of engine power while driving. Note: This problem may lead to engine noise, smoke, cause warning lights to turn on and/or cause an audible chime to sound before an engine failure. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Additionally, an engine failure could create the risk of a fire. Corrective Actions: The company will notify owners by mail and instruct you to take your vehicle to a dealer to inspect the engine block casting serial number. If the serial number is within the identified range, the dealer will replace the engine with a new one.

Listed for the model year, not checked against your VIN. Toyota confirms which apply.
Check your VIN with Toyota Canada or call a Toyota dealer with your VIN.
www.toyota.ca/en/owners/recalls/

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $28,750[5], $4,006 over the median of $24,744[4].

Lowest ask	$16,999
Middle half	$21,871 – $27,354
Median ask	$24,744
This car	$28,750

Same configuration · 36 live listings · as of 29 Oct 2026

OTHER 2020 TOYOTA RAV4 LISTINGS [5]

Newmarket, ON · 88,005 km	$29,999
Newmarket, ON · 74,000 km	$31,999
Newmarket, ON · 88,005 km	$32,499
Ottawa, ON · 187,967 km	$23,947
Montmagny, QC · 189,352 km	$18,993
Lethbridge, AB · 148,197 km	$29,995

§4 EVENTS

2020	Model year 2020[1] Assembly plant Woodstock, Ontario, Canada
6 Feb 2020	Transport Canada recall 2020039[2] Issued for the model year · Engine

24 Jun 2020	Transport Canada recall 2020288[2] Issued for the model year · Steering
28 Oct 2020	Transport Canada recall 2020514[2] Issued for the model year · Fuel system
25 Nov 2020	Transport Canada recall 2020573[2] Issued for the model year · Airbag
20 Dec 2023	Transport Canada recall 2023684[2] Issued for the model year · Airbag
29 Oct 2026	Listed for sale, Winnipeg, MB[5] St. James Volkswagen · asking $28,750

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 36 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.