

Register entry, as of 27 October 2026

Listed for sale

Record ID 8958b02e6755

2002 Dodge Ram

5.9 L, 6 cylinders · 4WD · Pickup · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

3B7 **KF236** **5** **2** **M** **256606**

WMI 1-3

Dodge · CHRYSLER DE ME...

DESCRIPTOR 4-8

Ram · 5.9 L

CHECK 9

Verified

YEAR 10

2002

PLANT 11

Mexico City

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2002	Engine	5.9 L, 6 cylinders
Make	Dodge	Fuel	Diesel
Model	Ram	Drive	4WD
Trim	Not in the decode	Maker	CHRYSLER DE MEXICO TOLUCA
Body	Pickup	Plant	Mexico City, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/dodge/ram/2002

5 recalls listed by Transport Canada for this model year

Electrical 2009081 11 Mar 2009

Certain aftermarket replacement windshield wiper motor assemblies, sold during the '08 and '09 calendar year for use as service equipment on 2002-2009 Dodge Ram pickup trucks, may be susceptible to water intrusion that could result in partial or complete loss of windshield wiping capability. Should this occur during a rainy/snowy day, it could increase the risk of a crash, causing property damage, personal injury or death. Correction: Owners who had windshield wiper motor assemblies serviced during the '08 and '09 calendar year will be requested to take their vehicle to a Chrysler dealer for inspection and repair if required.

Other 2007389 5 Dec 2007

On certain vehicles, the ignition/park shift interlock system may become inoperable. This can allow the shifter to be moved out of the PARK position with the ignition key removed (or in the lock position) or it could allow the ignition key to be removed when the shifter has not been placed in the PARK position. This could allow the vehicle to roll away, possibly causing property damage and/or personal injury or death. Correction: Dealers will replace the gearshift blocker and bracket assembly.

Electrical 2003059 10 Mar 2003

On certain pickup trucks, the electrical connector at the bottom of the steering column may contain an under-sized terminal in the Heater Ventilation Air Conditioning (HVAC) blower motor circuit. Localized heating from current flow with the blower speed set on high may cause the terminal contacts to relax and lose contact. This can cause the HVAC blower motor to become inoperative. Correction: Dealer will install an approved wiring harness.



Visual system

2003058 7 Mar 2003

On certain pickup trucks, the detent system on the exterior mirror housing may lose functionality, potentially affecting the driver's rearward field of vision. Correction: Dealer will install a mirror detent retainer kit on the driver and passenger side outside rearview mirrors.

Brakes

2002110 6 Jul 2002

On certain Ram 1500 4x4 pickup trucks the rear axle flange weld to the axle tube could fatigue and allow the brake caliper assembly to rotate. During rotation, the brake line could separate from the caliper resulting in a brake fluid loss in the rear brake hydraulic system potentially resulting in a crash. Correction: Dealers will install rear brake caliper reinforcement collars on the rear axle tube assemblies.

Listed for the model year, not checked against your VIN. Dodge confirms which apply.

Check your VIN with Mopar Canada or call a Dodge dealer with your VIN.

www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 12 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE [4]

This car asks \$12,888^[5], the median^[4].



Lowest ask	\$12,888
Middle half	\$12,888 – \$12,888
Median ask	\$12,888
This car	\$12,888

Same model year · 1 live listings · as of 27 Oct 2026

§4 EVENTS

2002	Model year 2002 ^[1] Assembly plant Mexico City, Mexico
6 Jul 2002	Transport Canada recall 2002110 ^[2] Issued for the model year · Brakes
7 Mar 2003	Transport Canada recall 2003058 ^[2] Issued for the model year · Visual system
10 Mar 2003	Transport Canada recall 2003059 ^[2] Issued for the model year · Electrical
5 Dec 2007	Transport Canada recall 2007389 ^[2] Issued for the model year · Other
11 Mar 2009	Transport Canada recall 2009081 ^[2] Issued for the model year · Electrical
22 Aug 2026	Listed for sale, Kelowna, BC ^[5] Elite Auto Centre · asking \$12,888



26 Oct 2026 Listing last updated^[5]
asking \$12,888

§5 DOCUMENTS

Window sticker This VIN reads as model year 2002, before our coverage for this manufacturer.

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 1 live listings, as of 27 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | |
| [3] NHTSA recall records (United States), listed for the model year | [5] Live public dealer listings on Cardog, as of 27 Oct 2026 |

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

