

Register entry, as of 28 October 2026

Listed for sale

Record ID de5ab0e062fc

2018 Jeep Compass Longitude, North, Latitude

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3C4 **NJDBB** **4** **J** **T** **454331**

WMI 1-3

Jeep · CHRYSLER DE MEXI...

DESCRIPTOR 4-8

Compass · 2.4 L

CHECK 9

Verified

YEAR 10

2018

PLANT 11

Toluca

SERIAL 12-17

Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	2.4 L, 4 cylinders
Make	Jeep	Fuel	Gasoline
Model	Compass	Drive	4WD
Trim	Longitude, North, Latitude	Maker	CHRYSLER DE MEXICO TOLUCA
Body	Sport Utility Vehicle	Plant	Toluca, State Of Mexico, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/compass/2018

6

 recalls listed by Transport Canada for this model year**Label** 2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Powertrain 2018422 9 Aug 2018

Certain vehicles may have been built with a defective powertrain controller. If the powertrain controller fails while driving the engine may stall, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the powertrain controller.

Brakes 2018421 9 Aug 2018

On certain vehicles, a problem with the brake system may cause gas bubbles to form in the brake fluid. This could cause a soft brake pedal feel and a reduction in brake performance, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will bleed the rear brakes as necessary.



Suspension

2018222 1 May 2018

On certain vehicles, the front suspension lower control arm(s) may have been improperly welded during the manufacturing process, causing the welds to fracture. Fractured welds on the front suspension lower control arm(s) could result in a loss of vehicle stability, increasing the risk of a crash causing injury and/or property damage. Correction: Dealers will inspect, and if necessary, replace the front lower control arms.

Lights and instruments

2017575 22 Nov 2017

Certain vehicles may not comply with Canada Motor Vehicle Safety Standard (CMVSS 101) – Location and Identification of Controls and Displays. The photo-sensor calibration of the instrument cluster panel may not detect day-to-night lighting transition correctly. This could prevent the instrument cluster panel from providing backlighting with at least two levels of brightness contrary to the requirements of the standard. Correction: Dealers will update the instrument cluster panel software with new photo-sensor calibrations as necessary.

Airbag

2017573 22 Nov 2017

Certain vehicles may contain loose passenger airbag inflator mount nuts inside the passenger airbag module assembly. In the event of a crash requiring a passenger airbag deployment, a loose nut inside the passenger airbag module could increase the risk of injury to the seat occupant. Correction: Dealers will replace the passenger airbag module assembly.

Listed for the model year, not checked against your VIN. Jeep confirms which apply.


Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.

www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$18,888^[5], \$3,893 over the median of \$14,995^[4].



Lowest ask	\$9,995
Middle half	\$12,222 – \$17,989
Median ask	\$14,995
This car	\$18,888

Same configuration · 15 live listings · as of 28 Oct 2026

OTHER 2018 JEEP COMPASS LISTINGS ^[5]

Kapuskasing, ON · 90,053 km	\$15,900
London, ON · 171,954 km	\$15,020
Kitchener, ON · 139,000 km	\$12,999
London, ON · 171,954 km	\$16,879
Kentville, NS · 101,601 km	\$15,435
Wilkie, SK · 116,850 km	\$16,995

§4 EVENTS

2018

Model year 2018^[1]

Assembly plant Toluca, State Of Mexico, Mexico

22 Nov 2017

Transport Canada recall 2017575^[2]

Issued for the model year · Lights and instruments



22 Nov 2017	Transport Canada recall 2017573 ^[2] Issued for the model year · Airbag
1 May 2018	Transport Canada recall 2018222 ^[2] Issued for the model year · Suspension
9 Aug 2018	Transport Canada recall 2018422 ^[2] Issued for the model year · Powertrain
9 Aug 2018	Transport Canada recall 2018421 ^[2] Issued for the model year · Brakes
15 Aug 2024	Transport Canada recall 2024548 ^[2] Issued for the model year · Label
18 Sep 2025	Listed for sale, New Westminster, BC ^[5] Alliance Motor Cars · asking \$18,888
14 Sep 2026	Window sticker collected ^[6] Issued by STELLANTIS
27 Oct 2026	Listing last updated ^[5] asking \$18,888

§5 DOCUMENTS ^[6]

Window sticker	PDF, issued by STELLANTIS, collected 14 Sep 2026 VIN not read from the file
----------------	--

SOURCES

[1] Cardog identity register, decoded from the VIN	[4] Cardog market quote, same configuration, 15 live listings, as of 28 Oct 2026
[2] Transport Canada recall database, listed for the model year	[5] Live public dealer listings on Cardog, as of 28 Oct 2026
[3] NHTSA recall records (United States), listed for the model year	[6] Window sticker, issued by STELLANTIS, collected 14 Sep 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote, live public dealer listings and the window sticker. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

