Register entry, as of 29 October 2026 Listed for sale Record ID 2e4f4077db06

2018 Jeep Compass Trailhawk

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3C4	NJDDB	6	J	T	493533
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jeep · CHRYSLER DE MEXI…	Compass · 2.4 L	Verified	2018	Toluca	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	2.4 L, 4 cylinders
Make	Jeep	Fuel	Gasoline
Model	Compass	Drive	4WD
Trim	Trailhawk	Maker	CHRYSLER DE MEXICO TOLUCA
Body	Sport Utility Vehicle	Plant	Toluca, State Of Mexico, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/compass/2018

6 recalls listed by Transport Canada for this model year

Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Powertrain

2018422 9 Aug 2018

Certain vehicles may have been built with a defective powertrain controller. If the powertrain controller fails while driving the engine may stall, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the powertrain controller.

Brakes

2018421 9 Aug 2018

On certain vehicles, a problem with the brake system may cause gas bubbles to form in the brake fluid. This could cause a soft brake pedal feel and a reduction in brake performance, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will bleed the rear brakes as necessary.

Suspension

2018222 1 May 2018

On certain vehicles, the front suspension lower control arm(s) may have been improperly welded during the manufacturing process, causing the welds to fracture. Fractured welds on the front suspension lower control arm(s) could result in a loss of vehicle stability, increasing the risk of a crash causing injury and/or property damage. Correction: Dealers will inspect, and if necessary, replace the front lower control arms.

Lights and instruments

2017575 22 Nov 2017

Certain vehicles may not comply with Canada Motor Vehicle Safety Standard (CMVSS 101) – Location and Identification of Controls and Displays. The photo-sensor calibration of the instrument cluster panel may not detect day-to-night lighting transition correctly. This could prevent the instrument cluster panel from providing backlighting with at least two levels of brightness contrary to the requirements of the standard. Correction: Dealers will update the instrument cluster panel software with new photo-sensor calibrations as necessary.

Airbag

2017573 22 Nov 2017

Certain vehicles may contain loose passenger airbag inflator mount nuts inside the passenger airbag module assembly. In the event of a crash requiring a passenger airbag deployment, a loose nut inside the passenger airbag module could increase the risk of injury to the seat occupant. Correction: Dealers will replace the passenger airbag module assembly.

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $9,000[5], $6,435 under the median of $15,435[4].

Lowest ask	$8,350
Middle half	$12,000 – $17,995
Median ask	$15,435
This car	$9,000

Same configuration · 17 live listings · as of 29 Oct 2026

OTHER 2018 JEEP COMPASS LISTINGS [5]

Aylmer, ON · 184,000 km	$11,995
Fort McMurray, AB · 65,115 km	$17,955
Perth, ON · 93,798 km	$15,995
Kitchener, ON · 171,954 km	$16,879
Kapuskasing, ON · 90,053 km	$15,900
London, ON · 171,954 km	$15,020

§4 EVENTS

2018	Model year 2018[1] Assembly plant Toluca, State Of Mexico, Mexico
22 Nov 2017	Transport Canada recall 2017575[2] Issued for the model year · Lights and instruments
22 Nov 2017	Transport Canada recall 2017573[2] Issued for the model year · Airbag
1 May 2018	Transport Canada recall 2018222[2] Issued for the model year · Suspension

9 Aug 2018	Transport Canada recall 2018422[2] Issued for the model year · Powertrain
9 Aug 2018	Transport Canada recall 2018421[2] Issued for the model year · Brakes
15 Aug 2024	Transport Canada recall 2024548[2] Issued for the model year · Label
28 Oct 2026	Listed for sale, Rouyn Noranda, QC[5] Thibault Chevrolet Cadillac Buick GMC De Rouyn Noranda Ltée · asking $9,000

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 17 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.