Register entry, as of 27 October 2026 Listed for sale Record ID 64f22233daf0

2022 Jeep Compass Latitude Lux, Altitude

2.4 L, 4 cylinders · 4WD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3C4	NJDFB	5	N	T	235328
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jeep · CHRYSLER DE MEXI…	Compass · 2.4 L	Verified	2022	Toluca	Build sequence

§1 IDENTITY [1]

Model year	2022	Engine	2.4 L, 4 cylinders
Make	Jeep	Fuel	Gasoline
Model	Compass	Drive	4WD
Trim	Latitude Lux, Altitude	Maker	CHRYSLER DE MEXICO TOLUCA
Body	Sport Utility Vehicle	Plant	Toluca, Mexico, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/compass/2022

5 recalls listed by Transport Canada for this model year

Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Visual system

2024338 13 Jun 2024

Issue: On certain vehicles, a software problem could cause the rearview camera image not to appear on the display. Canadian regulations require the rearview image to display when the transmission is shifted into reverse gear. Note: For the Grand Cherokee model, this recall affects 2022-2023 Jeep Grand Cherokee and 2021-2023 Grand Cherokee L models. Safety Risk: A rearview camera image that doesn't display could reduce a driver's ability to see behind the vehicle while backing up. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the radio software.

Lights and instruments

2023457 14 Aug 2023

Issue: On certain vehicles, a software problem in the body control module (BCM) could cause the backlight for the instrument cluster display not to work correctly. As a result, you may not be able to see certain information about the vehicle, including the gauges, messages, and tell-tale graphics. Safety Risk: An instrument cluster display that isn't visible could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to update the body control module (BCM) software.

Seats and restraints

2022187 14 Apr 2022

Issue: On a small number of vehicles, the head restraints on the front seats may not have been properly welded. As a result, a head restraint could move or detach from a seat in a crash. Safety Risk: Head restraints that move or detach in a crash could increase the risk of an injury. Corrective Actions: FCA Canada will contact owners by mail and instruct you to take your vehicle to a dealership to replace the front seat head restraints.

Label

2022006 13 Jan 2022

Issue: On certain vehicles, the airbag warning label on the passenger-side sun visor does not have both English and French text. Canadian regulations require that information on the label must be bilingual. Safety Risk: An incorrect airbag warning label could cause confusion. This could lead to an increased risk of injury in a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to inspect, and if necessary, replace the passenger-side sun visor.

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $25,994[5], $1,999 over the median of $23,995[4].

Lowest ask	$13,895
Middle half	$21,595 – $25,994
Median ask	$23,995
This car	$25,994

Same model year · 101 live listings · as of 27 Oct 2026

OTHER 2022 JEEP COMPASS LISTINGS [5]

Toronto, ON · 65,771 km	$24,743
Toronto, ON · 199,910 km	$13,895
Mississauga, ON · 30,477 km	$28,995
Airdrie, AB · 94,146 km	$21,495
Vernon, BC · 58,051 km	$22,995
Hamilton, ON · 68,516 km	$24,975

§4 EVENTS

2022	Model year 2022[1] Assembly plant Toluca, Mexico, Mexico
13 Jan 2022	Transport Canada recall 2022006[2] Issued for the model year · Label
14 Apr 2022	Transport Canada recall 2022187[2] Issued for the model year · Seats and restraints
14 Aug 2023	Transport Canada recall 2023457[2] Issued for the model year · Lights and instruments

13 Jun 2024	Transport Canada recall 2024338[2] Issued for the model year · Visual system
15 Aug 2024	Transport Canada recall 2024548[2] Issued for the model year · Label
16 Oct 2026	Listed for sale, Taber, AB[5] McDonald Chevrolet Buick GMC · asking $25,994
27 Oct 2026	Listing last updated[5] asking $25,994

§5 DOCUMENTS

Window sticker We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 101 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.