Register entry, as of 27 October 2026 Listed for sale Record ID 763424b8cc2a

# 2016 Dodge Journey SE

2.4 L, 4 cylinders · FWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 3C4 | PDCAB | 9 | G | T | 157916 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Dodge · CHRYSLER DE ME… | Journey · 2.4 L | Verified | 2016 | Toluca | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2016 | Engine | 2.4 L, 4 cylinders |
| Make | Dodge | Fuel | Gasoline |
| Model | Journey | Drive | FWD |
| Trim | SE | Maker | CHRYSLER DE MEXICO TOLUCA |
| Body | Sport Utility Vehicle | Plant | Toluca, State Of Mexico, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/dodge/journey/2016

**4** recalls listed by Transport Canada for this model year

### Engine

2018269 17 May 2018

On certain vehicles, an electronic fault may create a situation where the cruise control cannot be deactivated. If this occurs and the driver does not apply the brakes or shift the transmission to neutral, the vehicle could maintain speed or accelerate without warning, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the Powertrain Control Module (PCM) software and perform an update as necessary. Note: In the interim, owners are advised not to use the cruise control until the vehicle is repaired.

### Powertrain

2016624 14 Dec 2016

Certain vehicles may experience intermittent operation of the crankshaft or camshaft sensor. Intermittent operation of the crankshaft or camshaft sensor may result in illumination of a malfunction indicator lamp (“MIL”), the vehicle not starting or the engine stalling while driving, causing a loss of motive power which could increase the risk of a crash causing injury and/or property damage. Correction: Dealers will replace the crankshaft and camshaft connector.

### Powertrain

2016306 14 Jun 2016

On certain vehicles, a defect may cause the transmission pump rotor to seize or break, resulting in a loss of transmission pressure. This could result in a loss of motive power which, in conjunction with traffic and road conditions, and the driver's reactions may increase the risk of a crash causing injury. Correction: dealers will replace the transmission pump assembly.

### Steering

2016202 5 May 2016

On certain vehicles, the power steering return hose could rupture at engine start up if the vehicle is exposed to extended cold weather conditions. A power steering hose leak could result in the loss of power steering assist and increased steering effort, which depending on the driver's reactions and traffic conditions, could increase the risk of a crash resulting in injury and/or damage to property. Correction: Dealers will replace the return side power steering lines with new parts that are validated for extreme cold weather performance.

> Listed for the model year, not checked against your VIN. Dodge confirms which apply.
> Check your VIN with Mopar Canada or call a Dodge dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 4 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $6,999[5], $2,996 under the median of $9,995[4].

| | |
|---|---|
| Lowest ask | $3,950 |
| Middle half | $8,497 – $11,994 |
| Median ask | $9,995 |
| This car | $6,999 |

Same configuration · 23 live listings · as of 27 Oct 2026

### OTHER 2016 DODGE JOURNEY LISTINGS [5]

| | |
|---|---|
| Hamilton, ON · 117,284 km | $11,992 |
| Grande Prairie, AB · 118,676 km | $9,999 |
| Laval, QC · 106,940 km | $8,995 |
| Chatham-Kent, ON · 109,553 km | $14,688 |
| Vernon, BC · 130,611 km | $11,528 |
| Québec, QC · 66,600 km | $11,995 |

## §4 EVENTS

| | |
|---|---|
| 2016 | Model year 2016[1]<br>Assembly plant Toluca, State Of Mexico, Mexico |
| 5 May 2016 | Transport Canada recall 2016202[2]<br>Issued for the model year · Steering |
| 14 Jun 2016 | Transport Canada recall 2016306[2]<br>Issued for the model year · Powertrain |
| 14 Dec 2016 | Transport Canada recall 2016624[2]<br>Issued for the model year · Powertrain |
| 17 May 2018 | Transport Canada recall 2018269[2]<br>Issued for the model year · Engine |

27 Oct 2026 Listed for sale, Coquitlam, BC[5]
Blue Jay Auto Sales · asking $6,999

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 23 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026

### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.