Register entry, as of 24 November 2026 Listed for sale Record ID f9af441a9340

2012 Dodge Journey SXT

3.6 L, 6 cylinders · FWD · Sport Utility Vehicle · Flexible Fuel Vehicle (FFV)

VEHICLE IDENTIFICATION NUMBER [1]

3C4	PDCCG	3	C	T	322751
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dodge · CHRYSLER DE ME…	Journey · 3.6 L	Verified	2012	Toluca	Build sequence

§1 IDENTITY [1]

Model year	2012	Engine	3.6 L, 6 cylinders
Make	Dodge	Fuel	Flexible Fuel Vehicle (FFV)
Model	Journey	Drive	FWD
Trim	SXT	Maker	CHRYSLER DE MEXICO TOLUCA
Body	Sport Utility Vehicle	Plant	Toluca, State Of Mexico, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/dodge/journey/2012

6 recalls listed by Transport Canada for this model year

Airbag

2017336 7 Jul 2017

On certain vehicles, an electrical short could occur in the steering wheel wiring harness, which could result in an inadvertent deployment of the driver frontal airbag. Unintended airbag deployment, in a non-warranted (non-impact) situation, could startle the driver, which could result in a vehicle crash causing property damage and/or personal injury. In some instances, inadvertent deployment could cause minor injuries to vehicle occupants. Correction: Dealers will inspect the steering wheel wiring and replace it as necessary. A protective covering will also be installed on the wiring harness.

Steering

2016202 5 May 2016

On certain vehicles, the power steering return hose could rupture at engine start up if the vehicle is exposed to extended cold weather conditions. A power steering hose leak could result in the loss of power steering assist and increased steering effort, which depending on the driver's reactions and traffic conditions, could increase the risk of a crash resulting in injury and/or damage to property. Correction: Dealers will replace the return side power steering lines with new parts that are validated for extreme cold weather performance.

Brakes

2015478 16 Oct 2015

Certain vehicles may experience water wicking through the wire harness to the Anti-lock Brake System (ABS) module, which may disable the ABS and/or Electronic Stability Control (ESC) systems. Disabled ABS and/or ESC systems could increase the risk of a crash causing in injury and/or damage to property. Correction: Dealers will seal the ground eyelets with dual wall heat shrink, repair the wiring harness as required and replace the ABS Module as necessary.

Engine
2015297 2 Jul 2015

On certain vehicles equipped with a 2.4L engine, the engine cover could shift over time due to road vibrations. If the engine cover were to displace, it could result in the cover contacting the exhaust manifold, which could result in a fire, increasing the risk of injury and/or property damage. Correction: Dealers will install an enhanced retaining device to the engine cover.

Brakes
2011400 14 Nov 2011

Certain vehicles may have had their brake system inadvertently filled with contaminated brake fluid during vehicle assembly. This could damage certain brake components, which could increase stopping distance, and result in a crash causing property damage and/or personal injury. Correction: Dealers will replace all brake components that come in contact with hydraulic brake fluid.

Engine
2011351 27 Sep 2011

On certain vehicles equipped with a 3.6L engine, debris in the cylinder block (from the manufacturing process) could cause connecting rod bearing and crankshaft bearing damage. As a result, abnormal engine performance may be noticed, and in some cases the engine could fail. Engine failure would result in lost vehicle propulsion which, in conjunction with traffic and road conditions, and driver reactions, could increase the risk of a crash causing property damage and/or personal injury. Correction: Dealers will replace the engine assembly.

> Listed for the model year, not checked against your VIN. Dodge confirms which apply.
> Check your VIN with Mopar Canada or call a Dodge dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $2,495[5], $4,465 under the median of $6,960[4].



Lowest ask	$2,200
Middle half	$4,724 – $9,448
Median ask	$6,960
This car	$2,495

Same model year · 27 live listings · as of 24 Nov 2026

OTHER 2012 DODGE JOURNEY LISTINGS [5]

Richmond, BC · 129,471 km	$5,999
Cochrane, AB · 186,095 km	$11,888
Québec, QC · 272,002 km	$4,498
Portage la Prairie, MB · 48,775 km	$15,000
London, ON · 51,320 km	$8,995
Toronto, ON · 155,798 km	$6,950

§4 EVENTS

2012	Model year 2012[1] Assembly plant Toluca, State Of Mexico, Mexico
27 Sep 2011	Transport Canada recall 2011351[2] Issued for the model year · Engine

14 Nov 2011	Transport Canada recall 2011400[2] Issued for the model year · Brakes
2 Jul 2015	Transport Canada recall 2015297[2] Issued for the model year · Engine
16 Oct 2015	Transport Canada recall 2015478[2] Issued for the model year · Brakes
5 May 2016	Transport Canada recall 2016202[2] Issued for the model year · Steering
7 Jul 2017	Transport Canada recall 2017336[2] Issued for the model year · Airbag
19 Nov 2026	Listed for sale, Aylmer, ON[5] Goodwill's Used Cars · asking $2,495
24 Nov 2026	Listing last updated[5] asking $2,495

§5 DOCUMENTS

Window sticker	This VIN reads as model year 1982 or 2012, before our coverage for this manufacturer.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 27 live listings, as of 24 Nov 2026
[5] Live public dealer listings on Cardog, as of 24 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.