Register entry, as of 23 November 2026 Listed for sale Record ID dc3ba904e275

# 2015 Dodge Journey SXT

3.6 L, 6 cylinders · FWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

| 3C4 | PDCCG | 9 | F | T | 697564 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Dodge · CHRYSLER DE ME… | Journey · 3.6 L | Verified | 2015 | Toluca | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2015 | Engine | 3.6 L, 6 cylinders |
| Make | Dodge | Fuel | Gasoline |
| Model | Journey | Drive | FWD |
| Trim | SXT | Maker | CHRYSLER DE MEXICO TOLUCA |
| Body | Sport Utility Vehicle | Plant | Toluca, State Of Mexico, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/dodge/journey/2015

**6** recalls listed by Transport Canada for this model year

### Engine — 2018269 — 17 May 2018

On certain vehicles, an electronic fault may create a situation where the cruise control cannot be deactivated. If this occurs and the driver does not apply the brakes or shift the transmission to neutral, the vehicle could maintain speed or accelerate without warning, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the Powertrain Control Module (PCM) software and perform an update as necessary. Note: In the interim, owners are advised not to use the cruise control until the vehicle is repaired.

### Airbag — 2017336 — 7 Jul 2017

On certain vehicles, an electrical short could occur in the steering wheel wiring harness, which could result in an inadvertent deployment of the driver frontal airbag. Unintended airbag deployment, in a non-warranted (non-impact) situation, could startle the driver, which could result in a vehicle crash causing property damage and/or personal injury. In some instances, inadvertent deployment could cause minor injuries to vehicle occupants. Correction: Dealers will inspect the steering wheel wiring and replace it as necessary. A protective covering will also be installed on the wiring harness.

### Powertrain — 2016306 — 14 Jun 2016

On certain vehicles, a defect may cause the transmission pump rotor to seize or break, resulting in a loss of transmission pressure. This could result in a loss of motive power which, in conjunction with traffic and road conditions, and the driver's reactions may increase the risk of a crash causing injury. Correction: dealers will replace the transmission pump assembly.

### Steering

2016202 5 May 2016

On certain vehicles, the power steering return hose could rupture at engine start up if the vehicle is exposed to extended cold weather conditions. A power steering hose leak could result in the loss of power steering assist and increased steering effort, which depending on the driver's reactions and traffic conditions, could increase the risk of a crash resulting in injury and/or damage to property. Correction: Dealers will replace the return side power steering lines with new parts that are validated for extreme cold weather performance.

### Brakes

2015478 16 Oct 2015

Certain vehicles may experience water wicking through the wire harness to the Anti-lock Brake System (ABS) module, which may disable the ABS and/or Electronic Stability Control (ESC) systems. Disabled ABS and/or ESC systems could increase the risk of a crash causing in injury and/or damage to property. Correction: Dealers will seal the ground eyelets with dual wall heat shrink, repair the wiring harness as required and replace the ABS Module as necessary.

### Engine

2015297 2 Jul 2015

On certain vehicles equipped with a 2.4L engine, the engine cover could shift over time due to road vibrations. If the engine cover were to displace, it could result in the cover contacting the exhaust manifold, which could result in a fire, increasing the risk of injury and/or property damage. Correction: Dealers will install an enhanced retaining device to the engine cover.

> Listed for the model year, not checked against your VIN. Dodge confirms which apply.
> Check your VIN with Mopar Canada or call a Dodge dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $9,900[5], $1,903 over the median of $7,997[4].




| | |
|---|---|
| Lowest ask | $2,998 |
| Middle half | $5,888 – $10,231 |
| Median ask | $7,997 |
| This car | $9,900 |

Same configuration · 16 live listings · as of 22 Nov 2026

### OTHER 2015 DODGE JOURNEY LISTINGS [5]

| | |
|---|---|
| Truro, NS · 256,582 km | $10,991 |
| Camrose, AB · 65,520 km | $12,995 |
| Sarnia, ON · 181,056 km | $9,495 |
| Brantford, ON · 145,000 km | $8,999 |
| Laval, QC · 91,000 km | $5,699 |
| Mississauga, ON · 248,246 km | $2,998 |

## §4 EVENTS

| | |
|---|---|
| 2015 | Model year 2015[1]<br>Assembly plant Toluca, State Of Mexico, Mexico |
| 2 Jul 2015 | Transport Canada recall 2015297[2]<br>Issued for the model year · Engine |

| | |
|---|---|
| 16 Oct 2015 | Transport Canada recall 2015478[2]<br>Issued for the model year · Brakes |
| 5 May 2016 | Transport Canada recall 2016202[2]<br>Issued for the model year · Steering |
| 14 Jun 2016 | Transport Canada recall 2016306[2]<br>Issued for the model year · Powertrain |
| 7 Jul 2017 | Transport Canada recall 2017336[2]<br>Issued for the model year · Airbag |
| 17 May 2018 | Transport Canada recall 2018269[2]<br>Issued for the model year · Engine |
| 19 Nov 2026 | Listed for sale, Chilliwack, BC[5]<br>SMS Motors Chilliwack · asking $9,900 |
| 23 Nov 2026 | Listing last updated[5]<br>asking $9,900 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We have not collected this label yet. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same configuration, 16 live listings, as of 22 Nov 2026

[5] Live public dealer listings on Cardog, as of 23 Nov 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.