Register entry, as of 23 November 2026 Listed for sale Record ID 4407664c3eb4

2015 Dodge Journey R/T

3.6 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3C4	PDDFG	9	F	T	665909
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dodge · CHRYSLER DE ME…	Journey · 3.6 L	Verified	2015	Toluca	Build sequence

§1 IDENTITY [1]

Model year	2015	Engine	3.6 L, 6 cylinders
Make	Dodge	Fuel	Gasoline
Model	Journey	Drive	AWD
Trim	R/T	Maker	CHRYSLER DE MEXICO TOLUCA
Body	Sport Utility Vehicle	Plant	Toluca, State Of Mexico, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/dodge/journey/2015

6 recalls listed by Transport Canada for this model year

Engine — 2018269 — 17 May 2018

On certain vehicles, an electronic fault may create a situation where the cruise control cannot be deactivated. If this occurs and the driver does not apply the brakes or shift the transmission to neutral, the vehicle could maintain speed or accelerate without warning, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the Powertrain Control Module (PCM) software and perform an update as necessary. Note: In the interim, owners are advised not to use the cruise control until the vehicle is repaired.

Airbag — 2017336 — 7 Jul 2017

On certain vehicles, an electrical short could occur in the steering wheel wiring harness, which could result in an inadvertent deployment of the driver frontal airbag. Unintended airbag deployment, in a non-warranted (non-impact) situation, could startle the driver, which could result in a vehicle crash causing property damage and/or personal injury. In some instances, inadvertent deployment could cause minor injuries to vehicle occupants. Correction: Dealers will inspect the steering wheel wiring and replace it as necessary. A protective covering will also be installed on the wiring harness.

Powertrain — 2016306 — 14 Jun 2016

On certain vehicles, a defect may cause the transmission pump rotor to seize or break, resulting in a loss of transmission pressure. This could result in a loss of motive power which, in conjunction with traffic and road conditions, and the driver's reactions may increase the risk of a crash causing injury. Correction: dealers will replace the transmission pump assembly.

Steering
2016202 5 May 2016

On certain vehicles, the power steering return hose could rupture at engine start up if the vehicle is exposed to extended cold weather conditions. A power steering hose leak could result in the loss of power steering assist and increased steering effort, which depending on the driver's reactions and traffic conditions, could increase the risk of a crash resulting in injury and/or damage to property. Correction: Dealers will replace the return side power steering lines with new parts that are validated for extreme cold weather performance.

Brakes
2015478 16 Oct 2015

Certain vehicles may experience water wicking through the wire harness to the Anti-lock Brake System (ABS) module, which may disable the ABS and/or Electronic Stability Control (ESC) systems. Disabled ABS and/or ESC systems could increase the risk of a crash causing in injury and/or damage to property. Correction: Dealers will seal the ground eyelets with dual wall heat shrink, repair the wiring harness as required and replace the ABS Module as necessary.

Engine
2015297 2 Jul 2015

On certain vehicles equipped with a 2.4L engine, the engine cover could shift over time due to road vibrations. If the engine cover were to displace, it could result in the cover contacting the exhaust manifold, which could result in a fire, increasing the risk of injury and/or property damage. Correction: Dealers will install an enhanced retaining device to the engine cover.

> Listed for the model year, not checked against your VIN. Dodge confirms which apply.
> Check your VIN with Mopar Canada or call a Dodge dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $5,995[5], $3,000 under the median of $8,995[4].



Lowest ask	$2,900
Middle half	$6,109 – $9,999
Median ask	$8,995
This car	$5,995

Same model year · 42 live listings · as of 22 Nov 2026

OTHER 2015 DODGE JOURNEY LISTINGS [5]

Truro, NS · 256,582 km	$10,991
Camrose, AB · 65,520 km	$12,995
Chilliwack, BC · 108,475 km	$9,900
Sarnia, ON · 181,056 km	$9,495
Brantford, ON · 145,000 km	$8,999
Laval, QC · 91,000 km	$5,699

§4 EVENTS

2015	Model year 2015[1] Assembly plant Toluca, State Of Mexico, Mexico
2 Jul 2015	Transport Canada recall 2015297[2] Issued for the model year · Engine

16 Oct 2015	**Transport Canada recall 2015478**[2] Issued for the model year · Brakes
5 May 2016	**Transport Canada recall 2016202**[2] Issued for the model year · Steering
14 Jun 2016	**Transport Canada recall 2016306**[2] Issued for the model year · Powertrain
7 Jul 2017	**Transport Canada recall 2017336**[2] Issued for the model year · Airbag
17 May 2018	**Transport Canada recall 2018269**[2] Issued for the model year · Engine
22 Aug 2026	**Listed for sale, Dieppe, NB**[5] Subaru Of Moncton · asking $5,995
22 Nov 2026	**Listing last updated**[5] asking $5,995

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 42 live listings, as of 22 Nov 2026
[5] Live public dealer listings on Cardog, as of 23 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.