Register entry, as of 23 November 2026 Listed for sale Record ID 3fd2af99f264

2018 Dodge Journey Crossroad (M,U,C)

3.6 L, 6 cylinders · AWD · Sport Utility Vehicle · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3C4	PDDGG	9	J	T	359395
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Dodge · CHRYSLER DE ME…	Journey · 3.6 L	Verified	2018	Toluca	Build sequence

§1 IDENTITY [1]

Model year	2018	Engine	3.6 L, 6 cylinders
Make	Dodge	Fuel	Gasoline
Model	Journey	Drive	AWD
Trim	Crossroad (M,U,C)	Maker	CHRYSLER DE MEXICO TOLUCA
Body	Sport Utility Vehicle	Plant	Toluca, State Of Mexico, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/dodge/journey/2018

6 recalls listed by Transport Canada for this model year

Lights and instruments — 2019388 — 8 Aug 2019

Issue: On certain vehicles, the front amber side reflex reflector does not meet the requirements of Canadian regulations. Safety Risk: This may cause the vehicle to be less visible to others and could create an increased risk of a crash. Corrective Actions: The company will notify owners by mail and instruct them to take their vehicle to a dealer to replace the headlight assemblies.

Powertrain — 2018422 — 9 Aug 2018

Certain vehicles may have been built with a defective powertrain controller. If the powertrain controller fails while driving the engine may stall, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will replace the powertrain controller.

Brakes — 2018421 — 9 Aug 2018

On certain vehicles, a problem with the brake system may cause gas bubbles to form in the brake fluid. This could cause a soft brake pedal feel and a reduction in brake performance, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will bleed the rear brakes as necessary.

Other — 2018325 — 15 Jun 2018

Certain vehicles equipped with a rearview mirror backup camera display may fail to conform to the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 111 – Mirrors and Rear Visibility Systems. The cautionary message text in the rearview image display may temporarily reduce the field of view, which is contrary to the requirements of the standard. This could increase the risk of property damage or injury to nearby pedestrians in the event the driver does not check surroundings through traditional means. Correction: Dealers will replace the rearview mirror.

Other

2018324 15 Jun 2018

Certain vehicles equipped with a rearview mirror backup camera display may fail to conform to the requirements of Canada Motor Vehicle Safety Standard (CMVSS) 111 – Mirrors and Rear Visibility Systems. Some conditions may cause the system not to display a rearview image, which is contrary to the requirements of the standard. This could increase the risk of property damage or injury to nearby pedestrians in the event the driver does not check surroundings through traditional means. Correction: Dealers will replace the rearview mirror.

Engine

2018269 17 May 2018

On certain vehicles, an electronic fault may create a situation where the cruise control cannot be deactivated. If this occurs and the driver does not apply the brakes or shift the transmission to neutral, the vehicle could maintain speed or accelerate without warning, increasing the risk of a crash causing injury and/or damage to property. Correction: Dealers will inspect the Powertrain Control Module (PCM) software and perform an update as necessary. Note: In the interim, owners are advised not to use the cruise control until the vehicle is repaired.

> Listed for the model year, not checked against your VIN. Dodge confirms which apply.
> Check your VIN with Mopar Canada or call a Dodge dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $14,995[5], $560 over the median of $14,435[4].



Lowest ask	$8,704
Middle half	$11,958 – $14,924
Median ask	$14,435
This car	$14,995

Same configuration · 8 live listings · as of 22 Nov 2026

OTHER 2018 DODGE JOURNEY LISTINGS [5]

Edmonton, AB · 105,955 km	$13,999
Edmonton, AB · 32,272 km	$14,440
Drayton Valley, AB · 183,923 km	$8,704
Lévis, QC · 136,000 km	$11,987
Fergus, ON · 101,862 km	$16,999
Edmonton, AB · 102,734 km	$15,988

§4 EVENTS

2018	Model year 2018[1] Assembly plant Toluca, State Of Mexico, Mexico
17 May 2018	Transport Canada recall 2018269[2] Issued for the model year · Engine
15 Jun 2018	Transport Canada recall 2018325[2] Issued for the model year · Other

15 Jun 2018	Transport Canada recall 2018324[2]	Issued for the model year · Other
9 Aug 2018	Transport Canada recall 2018422[2]	Issued for the model year · Powertrain
9 Aug 2018	Transport Canada recall 2018421[2]	Issued for the model year · Brakes
8 Aug 2019	Transport Canada recall 2019388[2]	Issued for the model year · Lights and instruments
26 Oct 2026	Listed for sale, Penticton, BC[5]	Bannister Kia Penticton · asking $14,995
22 Nov 2026	Listing last updated[5]	asking $14,995

§5 DOCUMENTS

Window sticker	We have not collected this label yet.

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 8 live listings, as of 22 Nov 2026
[5] Live public dealer listings on Cardog, as of 23 Nov 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.