Register entry, as of 27 October 2026 Listed for sale Record ID 596fd1297160

2025 Jeep Wagoneer S

AWD · Sport Utility Vehicle · Electric

VEHICLE IDENTIFICATION NUMBER [1]

3C4	RJNBK	9	S	T	568978
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Jeep · CHRYSLER DE MEXI…	Wagoneer S	Verified	2025	Toluca	Build sequence

§1 IDENTITY [1]

Model year	2025	Engine	Not in the decode
Make	Jeep	Fuel	Electric
Model	Wagoneer S	Drive	AWD
Trim	Not in the decode	Maker	CHRYSLER DE MEXICO TOLUCA
Body	Sport Utility Vehicle	Plant	Toluca, Mexico, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/jeep/wagoneer-s/2025

4 recalls listed by Transport Canada for this model year

Visual system

2026205 23 Apr 2026

Issue: On certain vehicles, a software problem could cause the instrument panel cluster screen not to display. If this happens, you may not be able to see certain information about the vehicle, including the gear selection, warnings, and tell-tales. Note: For the Charger model, this recall only affects the Charger Daytona model. Safety Risk: Warnings, tell-tales and gauges that don't display could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to update the instrument panel cluster software.

Structure

2026112 12 Mar 2026

Issue: On certain vehicles, the hinge covers for the liftgate may not have been properly attached. As a result, the cover(s) could loosen and detach from the vehicle. Safety Risk: Parts that detach from the vehicle could create a hazard for others and increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to inspect and secure or replace the liftgate hinge covers, as necessary.

Electrical

2026043 2 Feb 2026

Issue: On certain vehicles, the trailer tow module could fail. As a result, the trailer lights may not work when towing a trailer. This problem could also cause the trailer brakes not to work. Note: This recall also affects certain RAM 3500, 4500 and 5500 chassis cab incomplete vehicles. Safety Risk: Trailer lights that don't work could make the vehicle less visible and cause following drivers not to recognize that the vehicle is braking or intends to turn or change lanes. These issues could increase the risk of a crash. Additionally, a loss of trailer brakes could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the trailer tow module.

Lights and instruments

2025143 20 Mar 2025

Issue: On certain vehicles, covers were not installed over the horizontal headlamp adjusters, and the vertical headlamp adjusters may not be accessible. As a result, the headlamps may be adjusted horizontally, and may not be adjusted vertically. Canadian regulations don't allow for horizontal headlamp adjustment unless the vehicle is equipped with a built-in aiming device, and require vertical headlamp adjusters to be accessible. Safety Risk: Headlamps that aren't properly adjusted could cause reduced visibility or glare for oncoming drivers, and increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to repair the headlamps.

> Listed for the model year, not checked against your VIN. Jeep confirms which apply.
> Check your VIN with Mopar Canada or call a Jeep dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 6 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $56,995[5], $14,754 under the median of $71,749[4].

Lowest ask	$46,995
Middle half	$61,736 – $82,485
Median ask	$71,749
This car	$56,995

Same configuration · 39 live listings · as of 27 Oct 2026

OTHER 2025 JEEP WAGONEER S LISTINGS [5]

Hamilton, ON · 13,206 km	$58,975
Hamilton, ON · 17,381 km	$56,950
Hamilton, ON · 10,274 km	$57,888
Hamilton, ON · 17,427 km	$58,950
Niagara Falls, ON · 7,257 km	$59,995
Pickering, ON · 4,267 km	$59,998

§4 EVENTS

2025	Model year 2025[1] Assembly plant Toluca, Mexico, Mexico
20 Mar 2025	Transport Canada recall 2025143[2] Issued for the model year · Lights and instruments
2 Feb 2026	Transport Canada recall 2026043[2] Issued for the model year · Electrical
12 Mar 2026	Transport Canada recall 2026112[2] Issued for the model year · Structure
23 Apr 2026	Transport Canada recall 2026205[2] Issued for the model year · Visual system

29 Jul 2026	Listed for sale, Napanee, ON[5] Peter Boyer Chevrolet Buick · asking $56,995
14 Sep 2026	Window sticker collected[6] Issued by STELLANTIS
27 Oct 2026	Listing last updated[5] asking $56,995

§5 DOCUMENTS [6]

Window sticker	PDF, issued by STELLANTIS, collected 14 Sep 2026 VIN not read from the file

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same configuration, 39 live listings, as of 27 Oct 2026
[5] Live public dealer listings on Cardog, as of 27 Oct 2026
[6] Window sticker, issued by STELLANTIS, collected 14 Sep 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote, live public dealer listings and the window sticker. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.