

Register entry, as of 29 October 2026

Listed for sale Record ID 1b35aa7b53d2

2024 Ram 3500 Tradesman

6.7 L, 6 cylinders · 4WD · Pickup · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

3C6 3R3GL X R G 416738

WMI 1-3 Ram · CHRYSLER DE MEXI...	DESCRIPTOR 4-8 3500 · 6.7 L	CHECK 9 Verified	YEAR 10 2024	PLANT 11 Saltillo	SERIAL 12-17 Build sequence
--------------------------------------	--------------------------------	---------------------	-----------------	----------------------	--------------------------------

§1 IDENTITY [1]

Model year	2024	Engine	6.7 L, 6 cylinders
Make	Ram	Fuel	Diesel
Model	3500	Drive	4WD
Trim	Tradesman	Maker	CHRYSLER DE MEXICO TOLUCA
Body	Pickup	Plant	Saltillo, Coahuila, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/3500/2024

3 recalls listed by Transport Canada for this model year

Label 2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Airbag 2024170 14 Mar 2024

Issue: On certain vehicles, the steering column control module may not have been manufactured properly. As a result, the driver-front airbag may not inflate in a crash. Note: This problem would cause the airbag warning light to turn on. Safety Risk: An airbag that is turned off could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to take your vehicle to a dealership to inspect and, if necessary, replace the steering column control module.

Lights and instruments 2023636 28 Nov 2023

Issue: On certain vehicles, a problem with the steering control module could cause a turn signal not to turn off or to flash briefly in the opposite direction after making a turn or changing lanes. This problem could also cause the high beams to turn on when a turn signal is activated, or a turn signal to turn on when the high beams are turned on. Safety Risk: Turn signals that stay on or flash in the opposite direction after making a turn or changing lanes could create confusion for others. High beams that turn on when a turn signal is activated could cause reduced visibility and/or glare for oncoming drivers. These issues could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and advise you to bring your vehicle to a dealer to update the steering control module software. The dealer will also inspect and, if necessary, replace the module.



Listed for the model year, not checked against your VIN. Ram confirms which apply.
Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 2 NHTSA records for this model year, kept apart from the Canadian listing.^[3]

§3 VALUE ^[4]

This car asks \$67,990^[5], \$2,000 over the median of \$65,990^[4].



Lowest ask	\$48,300
Middle half	\$58,997 – \$78,392
Median ask	\$65,990
This car	\$67,990

Same model year · 141 live listings · as of 29 Oct 2026

OTHER 2024 RAM 3500 LISTINGS ^[5]

Sherwood Park, AB · 54,416 km	\$56,906
Nanaimo, BC · 27,643 km	\$54,995
Edmonton, AB · 39,245 km	\$61,145
Edmonton, AB · 49,019 km	\$91,425
Edmonton, AB · 33,864 km	\$69,876
Winnipeg, MB · 31,387 km	\$58,689

§4 EVENTS

2024	Model year 2024 ^[1] Assembly plant Saltillo, Coahuila, Mexico
28 Nov 2023	Transport Canada recall 2023636 ^[2] Issued for the model year · Lights and instruments
14 Mar 2024	Transport Canada recall 2024170 ^[2] Issued for the model year · Airbag
15 Aug 2024	Transport Canada recall 2024548 ^[2] Issued for the model year · Label
14 Sep 2026	Window sticker collected ^[6] Issued by STELLANTIS
26 Oct 2026	Listed for sale, Calgary, AB ^[5] South Trail Chrysler · asking \$67,990
28 Oct 2026	Listing last updated ^[5] asking \$67,990



§5 DOCUMENTS [6]

Window sticker PDF, issued by STELLANTIS, collected 14 Sep 2026
VIN not read from the file

SOURCES

- | | |
|---|--|
| [1] Cardog identity register, decoded from the VIN | [4] Cardog market quote, same model year, 141 live listings, as of 29 Oct 2026 |
| [2] Transport Canada recall database, listed for the model year | [5] Live public dealer listings on Cardog, as of 29 Oct 2026 |
| [3] NHTSA recall records (United States), listed for the model year | [6] Window sticker, issued by STELLANTIS, collected 14 Sep 2026 |
-

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote, live public dealer listings and the window sticker. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.

