Register entry, as of 29 October 2026 Listed for sale Record ID 4caf758e170e

2017 Ram 3500 ST

5.7 L, 8 cylinders · 4WD · Pickup · Gasoline

VEHICLE IDENTIFICATION NUMBER [1]

3C6	3R3GT	9	H	G	675641
WMI 1–3	DESCRIPTOR 4–8	CHECK 9	YEAR 10	PLANT 11	SERIAL 12–17
Ram · CHRYSLER DE MEXI…	3500 · 5.7 L	Verified	2017	Saltillo	Build sequence

§1 IDENTITY [1]

Model year	2017	Engine	5.7 L, 8 cylinders
Make	Ram	Fuel	Gasoline
Model	3500	Drive	4WD
Trim	ST	Maker	CHRYSLER DE MEXICO TOLUCA
Body	Pickup	Plant	Saltillo, Coahuila, Mexico

§2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/3500/2017

16 recalls listed by Transport Canada for this model year

Airbag

2025013 16 Jan 2025

Issue: On certain trucks, the side curtain airbag inflators may be defective. As a result, the driver and/or passenger side curtain airbag inflator(s) could rupture unexpectedly and metal fragments could be propelled toward vehicle occupants. Note: This recall also affects certain 2016 model year RAM 3500 chassis cab incomplete vehicles. Safety Risk: An airbag inflator that ruptures can create a risk of injury. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to replace the affected side curtain airbag(s).

Brakes

2024727 27 Nov 2024

Issue: On certain trucks, the brake hydraulic control unit could fail. Over time, this could cause the antilock braking system (ABS), electronic stability control (ESC) system and/or traction control not to work. Note: This recall also affects certain RAM 3500, 4500 and 5500 chassis cab incomplete vehicles. Safety Risk: An antilock braking system, electronic stability control system and/or traction control system that doesn't work could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your truck to a dealership to replace the brake hydraulic control unit.

Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

Wheels

2021336 28 May 2021

Issue: On certain pickup and chassis-cab trucks, the owner's manual and service manual list the wrong torque specification for the wheel nuts. As a result, some trucks may have had the lug nuts over-tightened during servicing. This can damage the wheel studs and, over time, they could break. If this happens, a wheel could separate from the truck. Note: This recall only affects trucks equipped with dual rear wheels and flanged lug nuts. Safety Risk: A wheel separation could cause a loss of control and increase the risk of a crash. A wheel that separates could also hit another person or vehicle. Corrective Action: FCA Canada will contact owners by mail and instruct you to take your truck to a dealer to inspect and replace the wheel studs, as necessary. They will also provide an update for the torque specification listed in the owner's manual.

Steering

2020312 8 Jul 2020

Issue: This recall is for certain replacement parts for use on Ram Heavy Duty trucks that were sold by dealer parts departments. This recall is not being conducted under the requirements of the Motor Vehicle Safety Act. If the outboard steering linkage jam nut is not welded according to the Dealer Service Instructions for safety recall V06, it could loosen and allow one end of the drag link to separate from the adjuster sleeve. A drag link separation can result in a loss of steering control. The following 4x4 style steering system parts are included in this recall: Drag Link Assembly (Part # 68369907AA) Jam Nut (Part # 06510749AA and Part # 06510750AA) Drag Link Outer (Part # 68111301AA) Drag Link Adjuster (Part #68111302AA) Drag Link Inner (Part # 68111304AA) Safety Risk: A loss of steering control could increase the risk of a crash. Corrective Actions: FCA Canada will notify potential owners using dealer sales records. Owners will be instructed to take their vehicle to a dealer to inspect the drag link assembly. If the drag link is not welded but the jam nuts are properly tightened, the nuts will be welded to the adjuster sleeve. If the nuts are not properly tightened, the drag link assembly will be assessed for replacement. If a component or assembly is returned, FCA will reimburse the customer.

Structure

2019441 30 Aug 2019

Issue: On certain trucks equipped with a power locking tailgate, the tailgate may open while driving. If this occurs, cargo that is not secured could fall out of the truck bed and onto the road. Note: This is an expansion of recall U74 (Transport Canada recall 2018-398). Safety Risk: Cargo that falls from the truck bed could create a road hazard for others. Corrective Actions: The company will notify owners by mail and instruct them to take their truck to a dealer to modify the tailgate locking mechanism. Note: This recall supersedes recall 2019-221

10 more on the model-year record, cardog.app/tools/recalls/ram/3500/2017

> Listed for the model year, not checked against your VIN. Ram confirms which apply.
> Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 13 NHTSA records for this model year, kept apart from the Canadian listing.[3]

§3 VALUE [4]

This car asks $25,888[5], $11,854 under the median of $37,742[4].

Lowest ask	$16,999
Middle half	$28,246 – $42,998
Median ask	$37,742
This car	$25,888

Same model year · 34 live listings · as of 29 Oct 2026

OTHER 2017 RAM 3500 LISTINGS [5]

Lévis, QC · 153,000 km	$36,994
Orangeville, ON · 60,279 km	$53,900
Kelowna, BC · 149,571 km	$54,900
Orangeville, ON · 60,279 km	$53,900
Sundridge, ON · 60,279 km	$53,900
Sundridge, ON · 218,005 km	$46,769

§4 EVENTS

2017	Model year 2017[1] Assembly plant Saltillo, Coahuila, Mexico
13 Sep 2017	Transport Canada recall 2017441[2] Issued for the model year · Engine
21 Dec 2017	Transport Canada recall 2017659[2] Issued for the model year · Powertrain
22 Dec 2017	Transport Canada recall 2017663[2] Issued for the model year · Accessories
8 Feb 2018	Transport Canada recall 2018081[2] Issued for the model year · Powertrain
3 May 2018	Transport Canada recall 2018230[2] Issued for the model year · Accessories
17 May 2018	Transport Canada recall 2018269[2] Issued for the model year · Engine
31 Jul 2018	Transport Canada recall 2018398[2] Issued for the model year · Structure
25 Jan 2019	Transport Canada recall 2019038[2] Issued for the model year · Steering
10 May 2019	Transport Canada recall 2019221[2] Issued for the model year · Structure
21 Aug 2019	Transport Canada recall 2019420[2] Issued for the model year · Other
30 Aug 2019	Transport Canada recall 2019441[2] Issued for the model year · Structure
8 Jul 2020	Transport Canada recall 2020312[2] Issued for the model year · Steering
28 May 2021	Transport Canada recall 2021336[2] Issued for the model year · Wheels
15 Aug 2024	Transport Canada recall 2024548[2] Issued for the model year · Label
27 Nov 2024	Transport Canada recall 2024727[2] Issued for the model year · Brakes
16 Jan 2025	Transport Canada recall 2025013[2] Issued for the model year · Airbag
13 Mar 2025	Listed for sale, Surrey, BC[5] Sukhi Bath Motors · asking $25,888

14 Sep 2026	Window sticker collected[6] Issued by STELLANTIS
29 Oct 2026	Listing last updated[5] asking $25,888

§5 DOCUMENTS [6]

Window sticker	PDF, issued by STELLANTIS, collected 14 Sep 2026 VIN not read from the file

SOURCES

[1] Cardog identity register, decoded from the VIN
[2] Transport Canada recall database, listed for the model year
[3] NHTSA recall records (United States), listed for the model year
[4] Cardog market quote, same model year, 34 live listings, as of 29 Oct 2026
[5] Live public dealer listings on Cardog, as of 29 Oct 2026
[6] Window sticker, issued by STELLANTIS, collected 14 Sep 2026

STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote, live public dealer listings and the window sticker. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.