Register entry, as of 27 October 2026 Listed for sale Record ID 2b153644c75a

# 2021 Ram 3500 Limited

6.7 L, 6 cylinders · 4WD · Pickup · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

| 3C6 | 3R3PL | 5 | M | G | 549514 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Ram · CHRYSLER DE MEXI… | 3500 · 6.7 L | Verified | 2021 | Saltillo | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2021 | Engine | 6.7 L, 6 cylinders |
| Make | Ram | Fuel | Diesel |
| Model | 3500 | Drive | 4WD |
| Trim | Limited | Maker | CHRYSLER DE MEXICO TOLUCA |
| Body | Pickup | Plant | Saltillo, Coahuila, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/3500/2021

**9** recalls listed by Transport Canada for this model year

### Airbag

2025613 6 Nov 2025

Issue: On a small number of vehicles, the steering column control module may not have been manufactured properly. As a result, the driver-front airbag may not inflate in a crash. Note: This problem would cause the airbag warning light to turn on. Safety Risk: An airbag that is turned off could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners in writing and advise you to take your vehicle to a dealership to replace the steering column control module.

### Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

### Electrical

2023026 9 Feb 2023

Issue: On certain trucks and chassis-cabs equipped with a 6.7 L Cummins diesel engine, the intake air heater relay could short circuit. This could happen even when the vehicle is parked, and the ignition switch is in the off position. Safety Risk: A short circuit could create a fire risk. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the intake air heater relay. FCA recommends that you should park your vehicle outside and away from other vehicles or buildings until the recall repairs are completed.

### Powertrain
2022644 10 Nov 2022

Issue: On certain trucks, a buildup of heat and pressure inside the transmission could cause fluid to leak from the transmission dipstick tube. Note: This recall only affects trucks equipped with a Cummins 6.7 L diesel engine and a 68RFE automatic transmission. Safety Risk: A transmission fluid leak could create the risk of a fire. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the transmission dipstick and vent assembly.

### Brakes
2022108 11 Mar 2022

Issue: On certain vehicles, the warning lamp for the electronic stability control (ESC) system may not turn on when there is a problem with the ESC system. Safety Risk: A driver that is not aware of a problem with the ESC system could have an increased risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to update the antilock brake system (ABS) control module software.

### Airbag
2021722 24 Nov 2021

Issue: On certain trucks, there may be a problem with the side airbag curtain inflators. As a result, the side airbag curtains may not inflate properly in a crash. Safety Risk: A side airbag curtain that does not inflate properly could increase the risk of injury in a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to inspect and replace the side curtain airbag assemblies, as necessary.

3 more on the model-year record, cardog.app/tools/recalls/ram/3500/2021

> Listed for the model year, not checked against your VIN. Ram confirms which apply.
> Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 9 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $67,995[5], $10,649 over the median of $57,346[4].

| | |
|---|---|
| Lowest ask | $39,999 |
| Middle half | $52,969 – $65,414 |
| Median ask | $57,346 |
| This car | $67,995 |

Same model year · 16 live listings · as of 27 Oct 2026

OTHER 2021 RAM 3500 LISTINGS [5]

| | |
|---|---|
| Terrace, BC · 13,958 km | $78,990 |
| Prescott, ON · 93,657 km | $56,698 |
| Edmonton, AB · 96,526 km | $68,892 |
| Terrace, BC · 13,958 km | $78,990 |
| Watford, ON · 235,777 km | $44,795 |

## §4 EVENTS

2021 Model year 2021[1]
Assembly plant Saltillo, Coahuila, Mexico

| | |
|---|---|
| 11 Mar 2021 | Transport Canada recall 2021138[2]<br>Issued for the model year · Electrical |
| 28 May 2021 | Transport Canada recall 2021336[2]<br>Issued for the model year · Wheels |
| 14 Oct 2021 | Transport Canada recall 2021629[2]<br>Issued for the model year · Electrical |
| 24 Nov 2021 | Transport Canada recall 2021722[2]<br>Issued for the model year · Airbag |
| 11 Mar 2022 | Transport Canada recall 2022108[2]<br>Issued for the model year · Brakes |
| 10 Nov 2022 | Transport Canada recall 2022644[2]<br>Issued for the model year · Powertrain |
| 9 Feb 2023 | Transport Canada recall 2023026[2]<br>Issued for the model year · Electrical |
| 15 Aug 2024 | Transport Canada recall 2024548[2]<br>Issued for the model year · Label |
| 6 Nov 2025 | Transport Canada recall 2025613[2]<br>Issued for the model year · Airbag |
| 26 Oct 2026 | Listed for sale, Gatineau, QC[5]<br>Buckingham Hyundai · asking $67,995 |
| 27 Oct 2026 | Listing last updated[5]<br>asking $67,995 |

## §5 DOCUMENTS

Window sticker We have not collected this label yet.

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 16 live listings, as of 27 Oct 2026

[5] Live public dealer listings on Cardog, as of 27 Oct 2026


### STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.