Register entry, as of 29 October 2026 Listed for sale Record ID d02fa9e63493

# 2020 Ram 3500 Limited

6.7 L, 6 cylinders · 4WD · Pickup · Diesel

VEHICLE IDENTIFICATION NUMBER [1]

| 3C6 | 3R3SL | 1 | L | G | 254366 |
|---|---|---|---|---|---|
| WMI 1–3 | DESCRIPTOR 4–8 | CHECK 9 | YEAR 10 | PLANT 11 | SERIAL 12–17 |
| Ram · CHRYSLER DE MEXI… | 3500 · 6.7 L | Verified | 2020 | Saltillo | Build sequence |

## §1 IDENTITY [1]

| | | | |
|---|---|---|---|
| Model year | 2020 | Engine | 6.7 L, 6 cylinders |
| Make | Ram | Fuel | Diesel |
| Model | 3500 | Drive | 4WD |
| Trim | Limited | Maker | CHRYSLER DE MEXICO TOLUCA |
| Body | Pickup | Plant | Saltillo, Coahuila, Mexico |

## §2 OBLIGATIONS [2]

cardog.app/tools/recalls/ram/3500/2020

**12** recalls listed by Transport Canada for this model year

### Label

2024548 15 Aug 2024

Issue: On certain vehicles, the tire and loading information label does not list that there is no spare tire in both official languages. The label reads as "NONE" when it should read as "NONE / AUCUN". Canadian regulations require the information to be listed on the label in both English and French. Safety Risk: This error does not affect vehicle safety. Corrective Actions: This is not a recall. The company has corrected the tire and loading information label for all new vehicles.

### Structure

2022699 8 Dec 2022

Issue: On certain trucks, the tailgate could unlatch and open while driving. If this happens, cargo that is not secured could fall out of the truck bed and onto the road. Safety Risk: Cargo that falls from the truck bed could create a road hazard for others. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your truck to a dealership to inspect the alignment of the tailgate strikers, and adjust them if necessary.

### Powertrain

2022644 10 Nov 2022

Issue: On certain trucks, a buildup of heat and pressure inside the transmission could cause fluid to leak from the transmission dipstick tube. Note: This recall only affects trucks equipped with a Cummins 6.7 L diesel engine and a 68RFE automatic transmission. Safety Risk: A transmission fluid leak could create the risk of a fire. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the transmission dipstick and vent assembly.

### Brakes

2022108 11 Mar 2022

Issue: On certain vehicles, the warning lamp for the electronic stability control (ESC) system may not turn on when there is a problem with the ESC system. Safety Risk: A driver that is not aware of a problem with the ESC system could have an increased risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to update the antilock brake system (ABS) control module software.

### Visual system

2022025 27 Jan 2022

Issue: On certain trucks, the nuts that attach the windshield wiper arms may not have been tightened properly. This could cause the wipers to slip and not clear the windshield properly. Safety Risk: Windshield wipers that do not work properly could affect a driver's visibility. This could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealer to tighten the nuts on the windshield wiper arms.

### Fuel system

2021691 12 Nov 2021

Issue: On certain vehicles equipped with a 6.7 L Cummins diesel engine, the high-pressure fuel pump could fail. If this happens, you may notice a change in engine performance, a fuel leak, or the check engine light may turn on. This could also result in a sudden loss of engine power while driving. Safety Risk: A sudden loss of engine power could increase the risk of a crash. Corrective Actions: FCA Canada will notify owners by mail and instruct you to take your vehicle to a dealership to replace the high-pressure fuel pump and update the powertrain control module software. Additional fuel system parts may be replaced, if necessary.

6 more on the model-year record, cardog.app/tools/recalls/ram/3500/2020

> Listed for the model year, not checked against your VIN. Ram confirms which apply.
> Check your VIN with Mopar Canada or call a Ram dealer with your VIN.
> www.mopar.com/en-ca/my-vehicle/recalls/search.html

United States: 11 NHTSA records for this model year, kept apart from the Canadian listing.[3]

## §3 VALUE [4]

This car asks $49,995[5], $7,475 under the median of $57,470[4].

| | |
|---|---|
| Lowest ask | $29,999 |
| Middle half | $48,430 – $59,998 |
| Median ask | $57,470 |
| This car | $49,995 |

Same model year · 30 live listings · as of 29 Oct 2026

### OTHER 2020 RAM 3500 LISTINGS [5]

| | |
|---|---|
| Winnipeg, MB · 59,950 km | $70,192 |
| Regina, SK · 59,950 km | $70,192 |
| Winnipeg, MB · 59,950 km | $70,192 |
| Saskatoon, SK · 374,264 km | $47,909 |
| Saint-malachie, QC · 115,817 km | $54,995 |
| Abbotsford, BC · 129,000 km | $61,295 |

## §4 EVENTS

| | |
|---|---|
| 2020 | Model year 2020[1]<br>Assembly plant Saltillo, Coahuila, Mexico |
| 24 Jan 2020 | Transport Canada recall 2020025[2]<br>Issued for the model year · Powertrain |
| 6 Apr 2020 | Transport Canada recall 2020145[2]<br>Issued for the model year · Visual system |
| 9 Apr 2020 | Transport Canada recall 2020153[2]<br>Issued for the model year · Structure |
| 27 Aug 2020 | Transport Canada recall 2020396[2]<br>Issued for the model year · Engine |
| 28 May 2021 | Transport Canada recall 2021336[2]<br>Issued for the model year · Wheels |
| 10 Jun 2021 | Transport Canada recall 2021360[2]<br>Issued for the model year · Engine |
| 12 Nov 2021 | Transport Canada recall 2021691[2]<br>Issued for the model year · Fuel system |
| 27 Jan 2022 | Transport Canada recall 2022025[2]<br>Issued for the model year · Visual system |
| 11 Mar 2022 | Transport Canada recall 2022108[2]<br>Issued for the model year · Brakes |
| 10 Nov 2022 | Transport Canada recall 2022644[2]<br>Issued for the model year · Powertrain |
| 8 Dec 2022 | Transport Canada recall 2022699[2]<br>Issued for the model year · Structure |
| 15 Aug 2024 | Transport Canada recall 2024548[2]<br>Issued for the model year · Label |
| 28 Oct 2026 | Listed for sale, Lower Sackville, NS[5]<br>Autolane & Cycle Inc. · asking $49,995 |

## §5 DOCUMENTS

| | |
|---|---|
| Window sticker | We have not collected this label yet. |

### SOURCES


[1] Cardog identity register, decoded from the VIN

[2] Transport Canada recall database, listed for the model year

[3] NHTSA recall records (United States), listed for the model year

[4] Cardog market quote, same model year, 30 live listings, as of 29 Oct 2026

[5] Live public dealer listings on Cardog, as of 29 Oct 2026

## STATEMENT OF SCOPE

This record is what public sources held about this vehicle when Cardog read it, each fact cited to its source. It read the VIN decode, Transport Canada's recall listing, NHTSA's recall records, Cardog's market quote and live public dealer listings. Recalls are listed for the model year, not checked against this VIN; the manufacturer confirms which apply. It is not a vehicle history or ownership report, and it carries no owner information.